U.S. Senate Desk Description and Condition Report

Desk No: 001

Paper Label No.(on shelf bottom): 57

Painted No. (on bottom): 36

Other identifying labels or marks (specify location): Two brass plaques on stretcher reading "56" and "57"; stamped on inkboard "56"; in pencil underside of leg bracket "118" and "119"

Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	36 3/8	31 5/8		
Width (front)	28 1/4	26 1/2	25 5/8	
Width (rear)	25 5/8	23 5/8	22 7/8	
Depth	19 5/8	20	19 5/8	9

^{*} Note: not including "booster" blocks added to feet or writing box

Woods

Primary:	Mahogany	Character of case mahogany:	Plain
	Mahogany veneer		Ribbon 🗆
Other Wo	Rosewood veneer od (specify):		Mottled
			Crotch
184			Other

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				1	
Drawer Bottom			1		
Drawer Back			1		
Case Interior	1	1			

Construction Details

other:_

	-	_	
	•	п	
_	•	м	

Wood Type	rosewood crossband	other crossband	no crossband
mahog. veneer	1		
solid mahogany			1710
other:		3340	

Foot construction	:		1-part □ 2-part ■	Cockbead width on b	ottom of	Na	arrow 🗆
			THE STATE OF THE S			Full	width
D. Hebert		Other:	5-part 🗆	Opening in original to	p for ink	well:	Yes ■
Double bead on e	eage of leg:	Thickne	ess: 1 1/8"	Roundels: S	ingle pie	ce ("yo-yo"	form)
Shape of cross-s	tretcher edg					Applied	boss 🗆
F			ctanular	Inset distance of sing panel:	le bead		ck e: 1 1/4"
Spindle type:	Thick	Thin	Other			1	Гор: 7/8"
Number	2	8				Botton	n: 13/16"
Joinery of lower of	drawer blade	e to case	sides:	No. of Glue Blocks	Case	Stretch'r	Shelf
		single	dovetail	Original/Old			2
		2 0	dovetails	New/Recent	3		
		3 d	lovetails	Missing			

lap joint

	Top: 13		
No. of Glue Blocks	Case	Stretch'r	Shelf
Original/Old			2
New/Recent	3		
Missing			

Case built-out for drawer:	Yes
	No 🗆

Condition of Desk

Structure

			A Section 1		
Previous breaks in structural elements: (show on schematic)	Yes ■	Wear on Feet	Extreme	Moderate	Minor
(Show on scriematic)	No □	Front	1		
		Rear			1
Current split or broken elements:	Yes ■	La caracteristic de la car			
(show on schematic)	W-10100	Number of loose	spindles:		5700 50
	No □			****	No: 1
Other loose or damaged joinery: (describe in narrative)	Yes □	Number of replace (show on schere		s:	No: 2
	No 🔳	Popland vance	ra and area	a bandina.	Vac =
Damage to drawer fronts: E	xtreme	Replaced venee (show on scher		s-banding.	Yes
	5350	***************************************			No 🗆
Mod	derate ■ Minor □				
	Willion L.	Missing veneers (show on scher		banding:	Yes
Drawer lock: relocated on face	Yes 🖿	(Show on Scher	nauc)		No 🗆
Drawer lock: resized on inside	Yes ■	Delaminated/loo cross-banding:	se veneers	&	Yes ■
	naged	(show on scher	natic)		No 🗆
(show on schematic)	Missing 🗆	Shelf supports:		Origi	nal/old
	Loose			New	recent
Penlace	ments 🗆				/lissing □
Керіасе	ments L				mooning _
Replaced drawer-side runners:	Yes	Shelf molding ap	plied:		Yes 🗆
	No □		200	INTERNATION	No ■
Replaced case-side runners:	Yes □	Dowel support b	oard in cas	e:	Yes ■
	No ■			1899	No 🗆
Drawer bottom pieced-out at back edge	: Yes □				
li de la companya de	No ■				

Finish

Age	Excellent	Good	Fair	Poor
New		1		
Old				
Unk.				

Note: Describe finish problems in narrative.

Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)	1		/
Knob (R)			

Toe cap size: Right toe: 1

Left toe: 7