

## U.S. Senate Desk Description and Condition Report

Desk No : **66.00000.085**

Paper Label No.(on shelf bottom): 68

Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 67, 68, LXXXV / Top: 67 (stamped), 83 (?) (crayon) / Drawer Bottom: outside - No. 19, 67 (pencil - twice), paper remnant / Drawer Back: 3 (pencil) / Bottom of Shelf (other than paper label): chalk marking / Inkwell: 55 (pencil), 55 (chalk) / Drawer Front: inside - VI, 41 (pen)

### Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 3/4	32 3/16		
Width (front)	27 15/16	26 5/16	25 5/8	
Width (rear)	26 5/8	23 9/16	22 7/8	
Depth	19 1/2	20 1/16	19 1/4	9 9/16

\* Note: Dimensions do not include "booster" blocks added to feet or writing top.

### Woods

Primary:

Mahogany

Mahogany veneer

Rosewood veneer

Other Wood (specify): \_\_\_\_\_

\_\_\_\_\_

Character of case mahogany:

Plain

Ribbon

Mottled

Crotch

Other

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				✓	
Drawer Bottom			✓		
Drawer Back			✓		
Case Interior	✓	✓			
Drawer Front	✓				



**Condition of Desk**

## Structure

Previous breaks in structural elements: Yes   
(shown on schematic)  
No

Current split or broken elements: Yes   
(shown on schematic)  
No

Other loose or damaged joinery: Yes   
(describe in narrative)  
No

Damage to drawer front: Extreme   
Moderate   
Minor

Drawer lock: relocated on face Yes   
Drawer lock: resized on inside Yes

Cockbead on drawer front: Damaged   
(show on schematic)  
Missing   
Loose   
Replacements

Replaced drawer-side runners: Yes   
No

Replaced case-side runners: Yes   
No

Drawer bottom pieced-out at back edge: Yes   
No

Wear on Feet	Extreme	Moderate	Minor
Front	✓		
Rear			✓

Number of loose spindles: No: 0

Number of replaced spindles: No: 7  
(show on schematic)

Replaced veneers and cross-banding: Yes   
(show on schematic)  
No

Missing veneers and cross-banding: Yes   
(show on schematic)  
No

Delaminated/loose veneers & cross-banding: Yes   
(show on schematic)  
No

Shelf supports: Original/old   
New/recent   
Missing

Spindle support board in case: Yes   
No

**Finish**

Age	Excellent	Good	Fair	Poor
New			✓	
Old				
Unk.				

Note: Describe finish problems in narrative.

**Hardware/Attachments**

Item	Mismatch	Missing	Damaged
Knob (L)	✓		
Knob (R)			

Toe cap size:	Right toe: 6
	Left toe: 6