U.S. Senate Desk Description and Condition Report

Desk No: 66.00000.024

Paper Label No.(on shelf bottom): 24

Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 24, 24, XXIV / Top: 24 (stamped) / Drawer Bottom: outside - No. 7; inside - 23 (pencil) / Drawer Back: 24 (pencil) / Inside Case Back: 52 (pencil) / Inkwell: 24 (pencil)

Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 1/4	32 3/8		
Width (front)	28	26 3/8	25 5/8	
Width (rear)	24 1/8	21 7/8	21 5/16	- Y-111
Depth	19 3/4	20	19 1/4	9 5/8

^{*} Note: Dimensions do not include "booster" blocks added to feet or writing top.

Woods

Primary:	Mahogany ■ Mahogany veneer ■	Character of case mahogany:	Plain 🗆
	Rosewood veneer ■		Ribbon 🗆
Other Wo	ood (specify):		Mottled ■
-			Crotch □
			Other

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				1	
Drawer Bottom			/		
Drawer Back			/		
Case Interior	1	1			
Drawer Front	1				

Desk Descript	ion and Condition	on Repor	t: Desk No:	024	- 14 W			Page 2
Construction	n Details							
	Wood Type				rosewood crossband	other crossban	d cross	7.7
	mahog. venee	er			/			
	solid mahogai	ny						
	other:		_					
oot construc	tion:		1-part □	Co	ckbead width on t	oottom of	drawer from	nt:
			2-part ■				Na	arrow [
			5-part □	2)			Full	width I
		Other:		On	ening in original to	op for ink	well:	Yes I
Double bead	on edge of leg:				ching in original t	op ioi min		No E
		Bea	d: Thick	-				
	Loga	hickness	Thin 🗆	Ro	undels:	Single pie	ce ("yo-yo	form)
	Leg	nickness	s: 1 3/16 "				Applied	boss [
Shape of cros	s-stretcher edg	es:		_			Naki	
			Rounded 🗆		et distance of sin	gle bead	on desk ba	ck
	***	Rec	tangular	pai	nel:		Side	: 1 5/16
Spindle type:	Thick	Thin	Other				Т	op: 7/8
Number	1	5	4				Bottom	: 13/16
Joinery of low	er drawer blade	to case	sides:					
			dovetail 🗆	N	o. of Glue Blocks	Case	Stretch'r	Shelf
		2 d	ovetails		Original/Old	-		2
		3 d	ovetails 🗆	\vdash	New/Recent			_
		1	ap joint 🗆		Missing			1
	other:	<u> </u>	Miles	Inte	erior case-side flu	sh with co	orner block	? Yes
							(Ri	ght side
Shelf molding	applied:		Yes 🗆				//	No left side
			No ■		- 1000			.en side
				Wi	dth of drawer-ope	ning offse	_	ht : 5/8
					C-10-20-20-00		Left	: 2 3/8"

Condition of Desk

Structure

Previous breaks in structural elemen (shown on schematic)	ts: Yes ■	Drawer bottom p	ieced-out a	t back edge	Yes
	No □				No 🗆
Current split or broken elements:	Yes □	Wear on Feet	Extreme	Moderate	Minor
(shown on schematic)	No ■	Front	/		
		Rear			1
Other loose or damaged joinery: (describe in narrative)	Yes ■	Number of loose	snindles:	*	
(describe in narrative)	No □		No: 1		
Damage to drawer front:	Extreme □ Moderate ■	Number of replace (show on schero	The state of the s	s:	No: 5
200	Minor 🗆	Replaced venee		s-banding:	Yes I
Drawer lock: relocated on face	Yes ■	(show on scher	natic)		No 🗆
Drawer lock: resized on inside	Yes ■	Missing veneers		banding:	Yes [
Cockbead on drawer front: (show on schematic)	Damaged				No
	Missing	Delaminated/loo cross-banding:	se veneers	&	Yes 🗆
	Loose	(show on scher	No I		
Repl	acements	Shelf supports:		Origi	nal/old
Replaced drawer-side runners:	Yes ■			New	recent [
	No □			N	lissing □
Replaced case-side runners:	Yes ■	Spindle support	board in ca	ise:	Yes 🗆
	No □				No.
		L			No

Desk Description and Condition Report: Desk No: 024	Des	sk Description and Condition Report: Desk	No:	024	Page 4
---	-----	---	-----	-----	--------

Finish

Age	Excellent	Good	Fair	Poor
New			1	
Old				
Unk.				

Note: Describe finish problems in narrative.

Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)			
Knob (R)	7		/

Toe cap size:	Right toe: 2
	Left toe: 11