



Front View

Rear View



Loose/broken/delaminated

Previous repair

Missing

Add-ons


Damage/wear/hole

Replaced piece

Spindles not original to desk


Inscriptions

Right Side




- Loose/broken/delaminated
- Previous repair
- Damage/wear/hole
- Replaced piece

Left Side



- Missing
- Add-ons
- Spindles not original to desk
- Inscriptions

Top



■ Loose/broken/delaminated

■ Previous repair

■ Missing

■ Add-ons


■ Damage/wear/hole

■ Replaced piece


■ Spindles not original to desk

■ Inscriptions

Bottom



Bottom



■ Loose/broken/delaminated

■ Previous repair

■ Missing

■ Add-ons

■ Damage/wear/hole

■ Replaced piece


■ Spindles not original to desk

■ Inscriptions

Drawer Front, Outer Surface



Rear Surface of Drawer Front



■ Loose/broken/delaminated

■ Previous repair

■ Missing

■ Add-ons

■ Damage/wear/hole



■ Replaced piece

■ Spindles not original to desk

■ Inscriptions

Inside Surface of Left Drawer Side

Inside Surface of Right Drawer Side



■ Loose/broken/delaminated

■ Previous repair

■ Missing

■ Add-ons

■ Damage/wear/hole

■ Replaced piece


■ Spindles not original to desk

■ Inscriptions

Rear Surface of Drawer Back



Front Surface of Drawer Back



Loose/broken/delaminated

Previous repair

Missing

Add-ons

Damage/wear/hole



Replaced piece

Spindles not original to desk

Inscriptions

Upper Surface of Drawer Bottom

Lower Surface of Drawer Bottom



■ Loose/broken/delaminated

■ Previous repair

■ Missing

■ Add-ons

■ Damage/wear/hole

■ Replaced piece


■ Spindles not original to desk

■ Inscriptions



Outside Surface, Right Drawer Side

Outside Surface, Left Drawer Side



■ Loose/broken/delaminated

■ Previous repair

■ Missing

■ Add-ons

■ Damage/wear/hole

■ Replaced piece

■ Spindles not original to desk

■ Inscriptions