

# The Metal-Nonmetal Monitor

# 2006 Fatal Accidents

Wednesday, September 19, 2007



No	Acc Date	St	Contra- tor	Class	Mine Type	Mine Status	Mineral	Equip or Location	Occupation	Empl- oyees	Age	Mining Exp (yr . mo)	Job Exp (yr . mo)	PPE Involved	Training Rec'd
<a href="#">1</a>	1/5/2006	AZ	No	Falling/Sliding Material	QU	F	Sand & Gravel	Repairing Loader	Mechanic	64	39	12.6	12.6	No	Yes
<a href="#">2</a>	1/27/2006	OR	No	Machinery	QU	F	Limestone (C&B)	Operating Dozer	Heavy Equipment Operator	15	60	10	10	Yes	Yes
<a href="#">3</a>	2/13/2006	PA	No	Machinery	QU	F	Crushed Stone	Repairing Crusher	Superintendent	6	25	6	2.6	No	Yes
<a href="#">4</a>	4/3/2006	TN	No	Electrical	QU	F	Limestone (C&B)	Setting Pump House	Electrician	25	50	11	11	No	Yes
<a href="#">5</a>	4/4/2006	MI	No	Powered Haulage	QU	I	Sand & Gravel	Clean Tailpiece	Plant Laborer	7	23	0.1	0.1	No	Yes
<a href="#">6</a>	4/11/2006	TX	No	Powered Haulage	QU	F	Dimension Stone	Handling Rock	Rock Handler	42	22	0.9	0.9	No	Yes
<a href="#">7</a>	4/21/2006	IN	No	Fall of Highwall	QU	F	Dimension Stone	Drilling Rock	Driller	15	35	0.11	0.11	No	Yes
<a href="#">8</a>	4/22/2006	TN	No	Powered Haulage	UG	F	Limestone (C & B)	Walking by Scales	Utility Operator	48	53	33	5.5	No	Yes
<a href="#">9</a>	5/3/2006	UT	No	Powered Haulage	QU	F	Sand & Gravel	Adjusting Belt	Laborer	18	19	0.1	0.1	No	Yes
<a href="#">10</a>	5/19/2006	LA	Yes	Electrical	QU	F	Sand	Checking Motor	Electrician	8	77	58	58	No	Yes
<a href="#">11</a>	5/23/2006	KY	No	Powered Haulage	QU	F	Limestone (C&B)	Installing roller	Plant Operator	29	44	11	8	No	Yes
<a href="#">12</a>	5/22/2006	CA	No	Fall of Person	QU	F	Crushed Stone	Changing Screens	Mechanic	135	42	14.1	0.9	Yes	Yes
<a href="#">13</a>	5/26/2006	FL	Yes	Machinery	QU	F	Phosphate	Operating Dozer	Dozer Operator	146	58	12	12	No	Yes
<a href="#">14</a>	6/12/2006	VA	No	Falling Material	QU	F	Crushed Stone	Repairing Loader	Plant Operator	11	39	1.2	0.3	No	Yes
<a href="#">15</a>	6/21/2006	WA	Yes	Electrical	QU	I	Sand & Gravel	Installing Circuit	Electrician	2	75	50	50	No	Yes
<a href="#">16</a>	6/28/2006	MI	No	Fall of Person	QU	F	Iron Ore	Washing Roof	Utilityman	676	49	20.6	0.1	No	Yes
<a href="#">17</a>	7/15/2006	PR	No	Powered Haulage	QU	F	Sand & Gravel	Operating Truck	Truck Driver	15	61	40	33	No	Yes
<a href="#">18</a>	7/27/2006	MA	Yes	Electrical	QU	F	Limestone (C&B)	Cutting Weeds	Laborer	164	25	2	2	No	Yes
<a href="#">19</a>	8/17/2006	CA	Yes	Fall of Person	ML	F	Cement	Cleaning Kiln	Field Service Technician	170	37	15	5.6	No	Yes
<a href="#">20</a>	8/29/2006	PA	Yes	Powered Haulage	QU	F	Limestone (C&B)	Struck by Loader	Paving Supervisor	31	61	31	31	No	Yes
<a href="#">21</a>	10/4/2006	MN	Yes	Falling Material	QU	F	Sand & Gravel	Repairing Dragline	Dragline Operator	1	59	12	10	No	Yes
<a href="#">22</a>	10/10/2006	MI	No	Machinery	DR	I	Sand & Gravel	Operating Dredge	Dredge Operator	21	45	9.6	8	Yes	Yes
<a href="#">23</a>	10/12/2006	MN	No	Electrical	QU	F	Iron Ore	Motor Control Area	Maintenance Coordinator	295	24	1.4	1.4	No	Yes
<a href="#">24</a>	11/10/2006	MN	No	Falling Material	QU	I	Sand & Gravel	Conveyor Fell	Equipment Operator	6	41	4	4	No	Yes
<a href="#">25</a>	12/15/2006	AK	No	Falling Material	QU	F	Lead/Zinc Ore	Face of Highwall	Geologist	191	51	11	2.1	No	Yes
<a href="#">26</a>	9/21/2006	AK	No	Falling Material	QU	I	Sand & Gravel	Clamshell Bucket	Operator/Welder	2	59	9	9	No	Yes

Mine Types: UG - Underground, OP - Open Pit, QU - Quarry, SG - Sand & Gravel, ML - Mill, DR - Dredge

Mine Status: F - Full Time, I - Intermittent, N - Nonproducing, P - Closed

**Red Block Indicates Link to Fatalgram with subsequent link to Fatal Investigation Report \*ND - Not Determined as Fatal Investigation Report has not been completed.**