
U.S. Department of Labor



Mitte Citat	ion/Order			Mine Safety and	Health Administ	tration	
Section ⊢Viola	ition Data				In Charles	-/	
1. Date	Mo Da Yr	2. Time (24 Hr. Cloc 1130			3. Citation Order	n/ Number 758330	5
4. Served To	03/31/2006	1130		5. Operator			
	ong, Maintenance	e Superintendent		WOLF RUN M	INING COMPA	NY	
6. Mine	Olig, Maintenane			7. Mine ID 46-	08791		(Contractor)
SAGO M	INE			10		8a, Written N	(Contractor)
	D-s-Alexa				7	the No.10,	
breake	as not prov r was set a ength of ca	at 300 amps	proper snow	vailable fau	ilt current	. The circui . is 246 amp	s for
9. Violation	Safety ✓ Other □	B. Section of Act	C	Part/Section of Title 30 CFR		Continuation Form (MSHA	Form 7000-3a)
	spector's Evaluation						
10. Gravity:	: vor liiness (has) (is):	No Likelihood	Unlikely 🗸	Reasonably Likely	Highly Lik	cely 🗌 Occum	ed 🗌
B. Injury	or illness could rea-	No. 1 and Mandada	rys Lost Wo	rkdays Or Restricted D	uty 🗹 Permar	nentiy Disabling	Fatal _
	oly be expected to be ficant and Substantia		No ✓		D. Numbe	er of Persons Affected:	001
11. Neglige	ence (check one)	A. None		Moderate 🗸	D. High	E. Reckless Disrega	rd 🗌
12. Type of			13. Type of Is	suance (check one)	Citation 🗹	Order 🗌	Safeguard _
14. Initial A	ction		D. Written Notice	E. Citation/ Order Number		F. Dated	Mo Da Yr
15. Area or	r Equipment						
16. Termin	ation Due A. Date	Mo Da Yr 03/31/2006	B. Time (24 Hr. Clock	1130			· · · · · · · · · · · · · · · · · · ·
Section III-1	Termination Action						
17. Action	to Terminate The	cable was	cut off th	is pump.			

in accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has MSHA Form 7000-3, Mar 85 (revised) INSIA FORM 700U-3, Mair so (revised) In accordance with the provisions of the Small Business Augustus Principella (1990, the Small Business Augustus Principella (1990), the Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20418. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

1130

21. Primary or Mill

23. AR Number

Mo Da Yr

03/31/2006

E16

20. Event Number

B. Time (24 Hr. Clock

4134415

18. Terminated

22. Signature

A. Date

Section IV-Automated System Data

19. Type of Inspection

(activity code)

U.S. Department of Labor Mine Safety and Health Administration



Section IVio	lation Data			T	O Chatian/			
1. Date	Mo Da Yr	2. Time (24 Hr. Clock) 1130		ľ	3. Citation/ Order Number	7583306		
03/31/2006 1130 4. Served To Dick Wilfong, Maintenance Superintendent		5. Operator WOLF R	UN MINING C	COMPANY				
6. Mine			7. Mine ID	46-08791		(Contracto		
SAGO M						8a. Written Notic	e (103g)	
8. Condition	n or Practice		2 0 m 1-1 -	Dook Dug				

The cable supplying power to the No.2 Trickle Rock Duster located at the 39 cross cut of No.3 belt was laying on the mine floor. The entire 50 feet length of the cable was not hung on insulators.

								See C	Continuation Form	(MSHA Form	7000-3a)
9. Violation	A. Health Safet Othe	√	B. Section of Act			C. Part/Section of Title 30 CFR	of	7	75.516		
Section II-Insp	pector's Evalu	etion					<u></u>				
10. Gravity:					_					–	-
A. Injury o	or Ilin ess (h	28) (is):	No Likeliho	od 🗌	Unlikely 🗹	Reasonably	/ Likely	Highly Llk	ely 📋 (Occurred _	<u> </u>
	or illness co y be expect		No Lost	Workda	ays 🗌 🛮 Lost V	Vorkdays Or Restr	icted Duty 🗹	Perman	ently Disabling	☐ Fa	tal 🗌
C. Signific	cant and Su	ibstantia	: Yes		No 🗹			D. Numbe	r of Persons Aff	lected:	001
11. Negligen	ice (check d	one)	A. None]	B. Low 🗌	C. Moderate 🗹	D. High		E. Reckless D	nagerai	
12. Type of	Action	104(a)		13. Type o	f Issuance (check	one)	Citation 🗹	Order 🗌	s	afeguard 🗌
14. Initial Ac A. Citation		rder 🗌	C. Safegua	m []	D. Written Notice [E. Citation/ Order Nu	ımber		F. Da	ted N	MoDaYr
16. Termina	tion Due	A. Date	Mo Da		B. Time (24 Hr. Clo	ock) 113(,	- · · · · · · · · · · · · · · · · · · ·			
Section III-Tel	rmination Act	100	03/31/20	106							
17. Action to	Terminate	The	power	cab.	le was cut	off the	duster.				
18. Termina	A. Date	03/	Da Yr 31/2006	B. Time	(24 Hr. Clock	1130					
Section IV-Au		em Data									
19. Type of l		E16	20. Event	Number	413441	5 21. F	Primary or Mill				
22. Signatur	0	4	2		7		•	23. /	AR Number	- G	7

MSHA Form 7000-3, Mar 85 (revised)
In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration



		المناب المنافع المناب المنافع ا				
Section I-Vic	olation Data	To the Clock		3. Cita		7
1. Date	Mo Da Yr	2. Time (24 Hr. Clock) 1130	<u> </u>	Orde	er Number 750550	
4. Served 7	03/31/2006 To		5. Operator WOLF R	JN MINING COM	PANY	
	lfong, Maintenan	ce Superintendent	7. Mine ID	46-08791		(Contractor)
6. Mine SAGO N	ATNE				8a. Written N	
	on or Practice			mot	or located a	t the 39

The No.2 Trickle Rock Duster 480 volt 1.7 horse power motor, located at the 39 cross cut of No.3 belt was not provided with short circuit protection. The circuit breaker was set at 300 amps and the allowable amount for this small motor is 15 amps.

							See C	ontinuation For	n (MSHA Form	7000-3 a)
9. Violation	A. Health [Safety] Other [⊒ 1 ⁻	3. Section of Act		C. Part/Section of Title 30 CFR		7	5.518		
Section II-Inspe	ctor's Evalua	ion								
10. Gravity: A. Injury o	r Illness (ha	s) (is):	No Likelihood 🗌	Unlikely 🗹	Reasonably	Likely 🗌	Highly Like	ely 🗌	Occurred [
B Injury 0	r illness cou be expecte	ld rea-	No Lost Workd	ays 🗌 Lost V	Vorkdays Or Restri	cted Duty 🔽		ently Disablin		atal 🗌
	ant and Sut		Yes 🗌	No ✓			D. Numbe	r of Persons /		001
44 Northoon	an Jahank M	<u> </u>	A. None	B. Low	C. Moderate	D. High		E. Reckless	Disregard [J
11. Negligen		104(8			of Issuance (check	one)	Citation 🗹	Order [Safeguard
12. Type of A 14. Initial Ac A. Citation	tion		C. Safeguard	D. Written Notice	E. Citation/ Order Nu	ımber		F. (Dated	Mo Da Yr
15. Area or I										
16. Termina	tion Due	A. Date	Mo Da Yr 03/31/2006	B. Time (24 Hr. C	lock) 113	0				
Section III-Te	rmination Acti	on								rivi co
17. Action to	o Terminate	The	power cal	ole was cu	t off the	duster	and re	moved	TOM Se	TVICE.
18. Termina	A. Dari	03/3	Da Yr 31/2006 B. Tim	ne (24 Hr. Clock	1130					
	utomated Sys	tem Data			124	Primary or Mill				
19. Type of (activity	Inspection code)	E16	20. Event Numb	er 41344	15	rillialy of Mill		. AR Number	 	

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Act of 1996, the Small Business Administration has enforcement actions. The Ombudaman annually evaluates enforcement actions of MSHA, you may each 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Act of 1996, the Small Business Ac

U.S. Department of Labor Mine Safety and Health Administration



			Willio Octob	
Section I-Vic	olation Data	2. Time (24 Hr. Clock)	3. 0	Okation/ 7583308
1. Date	1010	1130		Order Number
4. Served	03/31/2006 To		5. Operator WOLF RUN MINING CO	MPANY
Dick Wi	lfong, Maintenand	e Superintendent	7. Mine ID 46-08791	(Contractor)
6. Mine SAGO N	MINE			8a. Written Notice (103g)
8. Condition	on or Practice		halt drive motor was	not provided with

The No.4, 575 volt 200 horse power belt drive motor was not provided with proper overload protection. The overload was set at 264 amps and the maximum allowable for this motor is 225 amps.

							See Co	ontinuation Fo	m (MSHA F	orm 7000-3a	
. Violation	A. Health [Safety]	B. Section of Act			Part/Section of Title 30 CFR		7:	5.518			
ection II-Insp	ctor's Evaluat	lon								_	
0. Gravity: A. Injury o	r Iliness (hai	s) (is): No Likeliho	ood 🗌	Unlikely 🗹	Reasonably L	ikely 🗌	Highly Like		Occurre		
B Injury 0	r illness cou	ld rea-	t Workdays	Lost Worl	kdays Or Restrict	ed Duty 🗹	Perman	ently Disabli	ng 📋	Fatal [
	be expects ant and Sub	0 10 00.	s No				D. Numbe	r of Persons	Affected:	001	
					Moderate 🗸	D. High		E. Reckles	s Disregal	rd 🗌	
1. Negligen					suance (check or	ne)	Citation 🗹	Order [Safegua	ard 🗌
12. Type of / 14. Initial Ac A. Citation	tion	104(a) der ☐ C. Safegu	ard D. W	ritten Notice	E. Citation/ Order Num			F.	Dated	Mo Da	Yr
15. Area or l		Mo Da	Yr In-	T	9 1130			·- · · · · · · · · · · · · · · · · · ·			
10. I CHILIDIA	IUON DOO	A. Date 03/31/	2006 B. I	ime (24 Hr. Cloci	1130						
Section #ITo	rmination Act	on									
17. Action t	o Terminate	The over	load wa	s set to 	220 amps	•					
18. Termina	^. Dall	03/31/2006	B. Time (24	Hr. Clock	1130	L					
	utomated Sys				[24 B	rimary or Mill					
19. Type o	(Inspection y code)	E16 20. Ew	ent Number	4134415	5 21. F			45 M 5			
22. Signati		- '(6		7			23	3. AR Numbe	"L {	0]	

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small business about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-588-REG-FAIR (1-588-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman. 409 3rd enforcement actions of MSHA, you may call 1-588-REG-FAIR (1-588-734-3247), or write the Ombudaman is in addition to any other rights you may have, including Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration

NI

IAU IC OIC			Millie Odicty Circ		
Section I-Vic		2. Time (24 Hr. Clock)		3. Citation/ Order Number	7583309
1. Date	Mo Da Yr 03/31/2006	1130	5. Operator		
4. Served	Го	aintendent	WOLF RUN MIN	ING COMPANY	
	lfong, Maintenand	e Superintendent	7. Mine ID 46-0	8791	(Contractor)
6. Mine	m TE				8a. Written Notice (103g)
SAGO N	AINE				se at 15 cross

The 480 volt No.6 Stanco Pump being used in the return air course at 15 cross cut of No. 4 belt was not maintained permissible as approved. The approved Stanco controller was removed and replaced with a non permissible Flygt type controller.

											See C	ontinuatio	on Form (MS	SHA For	m 7000-3a	
9. Violation	A. Health Safety Other		Section of Act				rt/Section e 30 CFI				75.5	607-1(a)			
Section II-Insp	ector's Evaluation	on														
10. Gravity: A. Injury C	or iliness (has) (is):	lo Likelihood	U	nlikely 🗹		Reasons	bly Lii	cely 🗌	<u>`</u>	y Like			curred		
B Injury	or illness coul y be expected	ree-	No Lost We	orkdays 🗌	Lost \	Norkda	ys Or Re	stricte	d Duty 😾				sabling [Fatai 🗌	
	cant and Sub		Yes [No 🗹]						umbe		sons Affec		001	
44 Neglicer	ice (check on	e) A	. None	B. Low	, 	C. Mod	derate	Z	D. Hij	gh 🗌		E. Re	ckless Dis	regard		
12. Type of		104(a)			13. Type (of Issua	nce (che	ck one	e)	Citatio	· 🗹	Or	der 🗌		Safegue	ard 🗌
14. Initial Ac	tion		C. Safeguard	D. Writt	ten Notice		E. Citati Order	on/ Numl	per				F. Date	d 	Mo Da	Yr
15. Area or	Equipment										_			·····		
16. Termina	ation Due	A. Date	Mo Da Yr 03/31/200	B. Tim	e (24 Hr. C	lock)	1	130								
Section III-T	ermination Actio	on									· -	21.1.				
17. Action 1	to Terminate	The	pump as	ssembly	y was	repl	Laced	ı Wi	th a	perm	185	TDTe	e unit	•		
18. Termin	ated A. Date		Da Yr 1/2006 B.	Time (24 H	r. Clock	1	1130									
Section IV-/	Automated Syst	em Deta						04 6		E211	1					
	f Inspection y code)	E16	20. Event N	umber	41344	15		21. PC	imary or M	7111	<u> </u>			-		
22. Signat		. –	6		7						23	. AR Nu	mber	Ç		

MSHA Form 7000-3, Mer 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Falmess Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman is in addition to any other rights you may have, including Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration

|--|

Aill in Circles			WILLIAM COLICE	7			
Section I-Violatic		2. Time (24 Hr. Clock)	T		3. Citation/ Order Number	7583310	
1. Date	Mo Da Yr 03/31/2006	1130	5. Operator		<u> </u>		
4 Conved To		Consintandent	WOLF R	UN MINING	COMPANY		
Dick Wilfor	ng, Maintenanc	e Superintendent	7. Mine ID	46-0879	l		(Contractor)
6. Mine	**					8a. Written Noti	ce (103g)
SAGO MIN	Practice		od in t	he retur	n air cour	se at 15	cross

The 480 volt No.6 Stanco Pump being used in the return air course at 15 cross cut of No.4 belt was not provided with proper overload protection. The overloads provided were set at 17 amps and the allowable setting is 9.2 amps.

									See C	ontinuation F	orm (MSH/	A Form 7000-3a)
. Violation	A. Health Salety Other	2	B. Section of Act			C. Part/ Title	Section of 30 CFR		7	5.518		
action II—Insp	ector's Evalua	tion									_	
). Gravity:	- ·	-> #->-	No Likelihoo	-d [Unlikely 🗸	R	asonably L	ikely 🗌	Highly Like	ely 🗌	Occu	med 🗌
	or Illness (ha						O- Contrict	ad Daty 57	Perman	ently Disak	ling 🔲	Fatal 🗌
B. Injury C	or illness cou y be expecte	nd to be:	No Lost	Workda	rys Lost	Workday	Or Resulci	ed Duty 🗹		r of Person		t: 001
	cant and Sul		: Yes	П	No ₹				D. Numbe	r or Pensor	S AIRECIO	a: 001
			A. None		B. Low	C. Mode	erate 🔽	D. High		E. Reckle	es Disreç	pard 🗌
	ce (check o						e (check or	16)	Citation 🗹	Orde		Safeguard
2. Type of	Action	104((a)		13. 1300					Ti	. Dated	Mo Da Yr
4. Initial Ac		der 🗌	C. Safegua	ard 📋 !	D. Written Notice	17	. Citation/ Order Nun	ber				
	Equipment		Mo Da	V.							· · · · · · ·	
16. Termina	ation Due	A. Dat			B. Time (24 Hr.	Clock)	1130					
Section III-T	ermination Ac	ion						1	-4 b b	normi	eeihl	e unit.
17. Action (to Terminate	The	e entir	e pu	ump assem	bly w	as rep	Taced V	with a	permi		
18. Termin	A. Dar	03	o Da Yr /31/2006	B. Tim	e (24 Hr. Clock	1	130					
	Automated Syn	stern Det		. A. A.J			21 F	rimary or Mil	1			
40 T	f Inspection		20. Ever	n Numbe	^{er} 4134	415	1		l l			
	y code)	El	6		7157					3. AR Num	Var (

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Falmess Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions.

U.S. Department of Labor Mine Safety and Health Administration



Section I-Violation Data			3. Citation/	7583311
1. Date Mo Da Yr 2.	Time (24 Hr. Clock) 1130		Order Number	7303311
03/31/2006 4. Served To		5. Operator WOLF RUN M	INING COMPANY	
Dick Wilfong, Maintenance S	super mendem	7. Mine ID 46-	08791	(Contractor)
SAGO MINE				8a. Written Notice (103g)

The 1600 feet long 2/0 power cable supplying power from No. 9 cross cut to 25 cross cut of No.4 belt was not provided with proper short circuit protection. This circuit was supplying power to a distribution box feeding other electrical equipment. The circuit breaker was set at 1125 amps and the allowable amount for this length cable is 842 amps.

										See C	ontinuatio	n Form (MSHA	Form 7000-3a)
). Violation A.	Health Safety Other	Z I	3. Section of Act				art/Section tie 30 CFR			7	5.518		
Section W-Inspector	rs Evaluat	on											
10. Gravity: A. Injury or Illi	ness (has	i) (is):	No Likelihoo	d 🗀	Unlikely 🗹		Reasonal	oly Likel	y 🗆	Highly Like		Occum	
B. Injury or ille	ness coul	ld rea-	No Lost	Workdays	Lost \	Workda	eys Or Rea	stricted	Duty 🔽	Perman	ently Dis	abling 🗌	Fatal 🗌
sonably be C. Significant										D. Numbe	r of Pers	ons Affected:	001
11. Negligence ((check on	(e)	A. None	B. l	Low 🗌	C. Mc	oderate 💆	3	D. High		E. Rec	kless Disrega	ard 🗌
12. Type of Activ		104(8	<u>)</u>		13. Type (of Issue	ance (chec	k one)	C	itation 🗹	Ord	ler 🗌	Safeguard [
14. Initial Action A. Citation	· _		C. Safeguar	d 🔲 D. V	Vritten Notice		E. Citatio Order	n/ Number				F. Dated	Mo Da Yr
15. Area or Equ	ipment												
16. Termination	Due	A. Date	Mo Da Y 03/31/20		Time (24 Hr. C	lock)	11	30		·····			
Section III-Termin	nation Action	on											
17. Action to Te	minate	The	cable	disco	nnectin	g d	evice	was	move	d to a	cir	cuit br	reaker
that was	s set												
18. Terminated	A. Date	03/	Da Yr 31/2006	B. Time (24	4 Hr. Clock		1130			<u> </u>			
Section IV-Autor	nated Syst	em Data					- 12	4 Dalam	A 4 ²³⁴				
19. Type of Ina (activity co		E16	20. Event	Number	41344	15	2	1. Pnmi	ary or Mill				
22. Signature		T	4	2	7					23	. AR Nur	nber	<u>6</u>

MSHA Form 7000-3, Mer at (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1998, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration of the National Ombudaman and 10 Regional Pair Regional Pa

U.S. Department of Labor Mine Safety and Health Administration

|--|

Section I-Vio	plation Data				3. Citation/	7583312	
1. Date	Mo Da Yr	2. Time (24 Hr. Clock) 1130	l		Order Number	7505512	
4. Served T	03/31/2006_		5. Operator WOLF RU	JN MINING C	COMPANY		
B. Mine	ltong, Maintenar	ce Superintendent	7. Mine ID	46-08791			(Contractor)
SAGO M	MINE					8a. Written Not	ice (103g)
	or Practice					to A helt	to the

The 480 volt 2/0 power cable supplying power from 9 cross cut No.4 belt to the No 1 distribution box at 12 cross cut contained a damaged area. The insulation was damaged on a splice, exposing the shielded power conductors. One crosscut inby this, the shielding was not continuous.

										See C	continuatio	n Form (MSHA	Form 7000-	3a) 🗌
9. Violation A. Health B. Section of Act Other				C. Part/Section of Title 30 CFR					7					
Section N-Inspi	ector's Evalua	tion												
10. Gravity: A. Injury o	or Illn ess (ha	ıs) (is):	No Likelihood	i 🗆 🕓	Jniikely 🔽		Reasonably	Likely		Highly Lik	ely 🗌	Occur		
B. Injury 9	or illness con y be expecte	ıld rea-	No Lost V	Vorkdays [Lost V	Norkda	ys Or Restr	icted D	outy 🗌			abling 🗌	Fatal (
	cant and Su		: Yes	☐ No 5						D. Numbe	or of Pers	ons Affected	001	
11. Negligen			A. None	B. Lo		C. Mo	derate 🗹		D. High		E, Rec	kless Disreg	ard 🗌	
12. Type of		1040	(a)		13. Type o	f Issua	nce (check	one)	C	itation 🗹	Ord	ler 🗌	Safeg	uard 🗌
14. Initial Ac A. Citation	tion	rder 🗌	C. Safeguare	ı 🔲 D. Wri	tten Notice		E. Citation/ Order Nu					F. Dated	Mo D	a Yr
15. Area or i	Equipment													
16. Termina	tion Due	A. Dat	Mo Da Y	1 1 1 1 1 1 1 1 1	me (24 Hr. C	lock)	113	0						
Section III-Te	ermination Ac	ion												
17. Action to	o Terminate	The	e cable	was re	paired	•								
18. Termina	A. Dat	<u> </u>	Da Yr /31/2006	B. Time (24)	ir. Clock		1130							
Section IV-A		stem Data					164	D-1	or or Nam	 				
19. Type of (activity		E10	20. Event	Number	41344	15	21.	Pnm2	ry or Mill					
22. Signatu			(,		1					23	3. AR Nur	nber	6	

MSHA Form 7000-3, Mer 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small business about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration



Section I-Vic	plation Data		3. Citation/ 7583313	
1. Date	Mo Da Yr	2. Time (24 Hr. Clock)	Order Number /363313	
	03/31/2006	1130	5. Operator	
4. Served T	Γο	g talam damb	WOLF RUN MINING COMPANY	
Dick Wil	lfong, Maintenan	ce Superintendent		
6. Mine			40-00/91 (Contr	
SAGO M	AINE		8a. Written Notice (103	(g)
a Conditio	o or Practice			

The circuit breaker and receptacle supplying power to the disconnecting device for the No.6 slurry pump located in the No.4 belt intake air course, was not properly identified. The circuit breaker and receptacle was identified as supplying power to the No.10 slurry pump.

									See C	ontinuation	Form (MSHA	Form 7000-3a)	
9. Violation	A. Health Safety Other	7	B. Section of Act				art/Section of tie 30 CFR		7	5.904	· · · · · · · · · · · · · · · · · · ·		
Section II-Insp	ector's Evalua	tion											
10. Gravity: A. Injury o	r iliness (ha	s) (is):	No Likeliho	od 🗀 U	Inlikely 🔲		Reasonably Lil	cely 🔽	Highly Like	ely 🗌	Occurr	ed 🗌	
	r illness cou		No Lost	Workdays [Lost W	orkd	ays Or Restricts	d Duty 🗌			abling 🗌	Fatal 🗸	
	ant and Sut		Yes	☑ No []				D. Numbe	r of Perso	ons Affected:	001	
11. Negligen	ce (check of	ne)	A. None	B. Lov	"	C. M	oderate 🗹	D. High		E. Reck	iless Disrega	ird 🗌	
12. Type of A	Action	104(1)		13. Type of	Issu	ance (check one)	Citation 🗹	Ord	er 🗌	Safegua	rd []
14. Initial Act		der 🗌	C. Safegua	rd D. Writ	ten Notice [E. Citation/ Order Numb	per	·		F. Dated	Mo Da	Yr
15. Area or E			Mo Da	v. T									
16. Terminal	tion Due	A. Date	03/31/20	IRTIM	ne (24 Hr. Ck	ock)	1130						
Section III-Te	rmination Acti										1 1 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		
17. Action to supply				it break No.6 s			eceptacl p.	e was	proper	ту 10	ientiii	.ea as	
18. Termina	A. Date	03/:	Da Yr 31/2006	B. Time (24 H	ir. Clock		1130						
Section IV-A		em Data					12121						
19. Type of (activity		E16	20. Even	Number	413441	.5	21. Pri	mary or Mill					
22. Signatu	re		6						23.	AR Num	ber	(p)	

MSHA Form 7000-3, Mer 85 (revised) in accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudamen and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudamen annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudamen at Small Business Administration, Office of the National Ombudamen, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration

Ѿ

Section IViolation Data		3. Citation/	7592214
1. Date Mo Da Yr	2. Time (24 Hr. Clock) 1130	Order Number	7583314
4. Served To Dick Wilfong, Maintenance		5. Operator WOLF RUN MINING COMPANY	
6. Mine	Superimone	7. Mine ID 46-08791	(Contractor)
SAGO MINE			8a. Written Notice (103g)

The 4000 + feet No.10/5 cable supplying 480 volts power from the 9 block of No.4 belt to the No 10 slurry pump at 45 block of No.4 belt was not provided with proper short circuit protection. The circuit breaker was set at 900 amps and the available fault current for this length of cable is 24 amps.

										Sec	Continuatio	n Form (MSH/	Form 7000-	3a) 🔲
9. Violation	A. Health Safety Other		B. Section of Act				art/Section de 30 CFR	of			75.518			
Section II-Insp	ector's Evalua	ition												
10. Gravity: A. Injury o	or liiness (he	ıs) (is):	No Likelihoo	od []	Unlikely [Reasonabl	y Likely	\square	Highly L	ikely 🗌	Occur	red 🗌	
B. Injury o	or illness cor	uld rea-	No Lost	Workdays	Lost	Workda	sys Or Resi	ricted D	ruty 🗌	Perm	enently Dis	abling 🗌	Fatai 🖟	<u> </u>
	cant and Su		Yes	₩ No						D. Num	ber of Pers	ons Affected	l: 0 01	
11. Negligen	ice (check o	ne)	A. None	B. 1	Low 🗌	C. Mc	oderate 🗹		D. High		E. Rec	kless Disreg	ard 🗌	
12. Type of /	Action	104(a)	· · · · · · · · · · · · · · · · · · ·	13. Type	of Issua	ince (check	cone)	C	itation 🗸	Ord	er 🗌	Safeg	uard 🗌
14. Initial Ac		rder 🔲	C. Safegua	rd D.V	Vritten Notice		E. Citation Order N					F. Dated	Mo D	a Yr
15. Area or I			Mo Da '	,					- 					
16. Termina	tion Du e	A. Date	03/31/20	IR	Time (24 Hr. C	Clock)	113	30						
Section III-Te	emination Ac	ion												
17. Action to	o Terminate			was c	ut off	bot!	h ends	and	the	ump	remov	ed Iro	m serv	ice.
18. Termina	A. Dat	_	Da Yr 31/2006	B. Time (24	Hr. Clock		1130			. —				<u>-</u>
Section IV-A	utomated Sys	tem Data												
19. Type of (activity		E16	20. Event	Number	41344	15	21	. Primar	y or Mill					
22. Signatu			(0	د	7					12	3. AR Nun	nber _	6]

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small business about federal agency enforcement actions. The Ombudaman annually evaluates enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration

|--|

Section I-Vic	olation Data		3. Citation/ 7583	3315
1. Date	Mo Da Yr	2. Time (24 Hr. Clock) 1130	Order Number / 58.	
4. Served	03/31/2006 To	ce Superintendent	5. Operator WOLF RUN MINING COMPANY	
6. Mine		ee Supermienten	7. Mine ID 46-08791	(Contractor)
SAGO N	MINE		8a. Wri	tten Notice (103g)
9 Conditio	on or Practice			+ 27 CTOSS

The scoop battery charger located in the intake air course at 4 belt, 27 cross cut was neither housed in a noncombustible structure, or equipped with a fire suppression system.

									See C	Continuation For	m (MSHA Form 7	000-3a) 🗌
). Violation	A. Health Safety Other	2	3. Section of Act				Section of 30 CFR		7	75.340		
Section II Inspe	ctor's Evalue	tion										
10. Gravity: A. Injury o	r illness (ha	s) (is):	No Likelihoo	xd 🗌	Unlikely 🗹	R	sasonably Lik	ely 🗌	Highly Llk	ely 🗌	Occurred	
B. Injury o	r illness cou	ld rea- d to be:	No Lost	Workdays	Lost \	Vorkdays	Or Restricte	d Duty 🗹		nently Disablin		M 🗌
	ant and Sul		Yes	□ N	· 🗹				D. Numbe	r of Persons		12
11. Negligeno	ce (check o	10)	A. None	В.	Low 🗌	C. Mode	rate 🗹	D. High		E. Reckles	s Disregard 🗌	
12. Type of A		104(a			13. Type o	f Issuanc	e (check one) (Citation 🗹	Order [] Sa	rfeguard 🗌
14. Initial Act	tion		C. Safegua	rd [] D. 1	Written Notice	_ E	Citation/ Order Numb	er		F.	Dated M	o Da Yr
15. Area or E	· · ·		Mo Da	Yr a	Time (74 He C		1130				·	
		A. Date	03/31/20	006 B.	Time (24 Hr. C		1130	l				
Section III-Ter	rmination Act	on										
17. Action to	Terminate	The	charg	er was	s mover	from	the in	take a	ir cou	rse.		
18. Termina	A. Date		Da Yr 31/2006	B. Time (2	24 Hr. Clock	11	30					
Section IV-A	utomated Sys	em Data										
19. Type of		E16	20. Event	Number	41344	15	21. Prir	nary or Mill				
(activity	code)	EIO	1		11511					. AR Number		

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from amail businesses about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration



Section I-Vic		2. Time (24 Hr. Clock)	3. Citation/ 7583316	
1. Date	Mo De Yr 03/31/2006	1130	Order Munices	
4. Served 1	To	ce Superintendent	5. Operator WOLF RUN MINING COMPANY	
B. Mine	liong, Maintenan	ce Superintendent	7. Mine ID 46-08791 (Contra	
SAGO M	MINE		8a. Written Notice (103g	
	on or Practice		5 the No 6 cable	

The 575 volt ungrounded (unshielded) power conductors of the No.6 cable supplying power to the No.4 charger located on the surface were fed from underground, were not provided with lightning arrestors.

										See C	Continuatio	Form (MSHA	Form 7000-3	<u>) [</u>
9. Violation	A. Health Safety Other	$\overline{\mathbf{Z}}$	B. Section of Act				art/Section itle 30 CF			7	5.521			
Section II—Insp	ector's Evalua	tion												
10. Gravity: A. Injury o	or Illness (ha	ıs) (is):	No Likelihoo	x d []	Unlikely []	Reasona	bly Like	y 🗹	Highly Llf	ely 🗌	Occum	ed 🗌	
B. Injury C	or itiness co	uld rea-	No Lost	Workday	s. ☐ Los	t Workd	lays Or Re	stricted	Duty 🗌	Permai	ently Dis	abling 🗌	Fatal 🔽	
sonabh	y be expecte	ed to be		TTOIRGE						D. Numbe	er of Pers	ons Affected	001	
C. Signific	cant and Su	bstantia	i: Yes	☑ N	io 🗌					J. 144				
11. Negligen	ice (check o	ne)	A. None	E	. Low 🗌	C. M	oderate	Z	D. High		E. Rec	kless Disrega	ard 🗌	
12. Type of		104	(a)		13. Type	of Issu	ance (che	ck one)		itation 🗹	Ord	er 🗌	Safegu	ard 🗌
14. Initial Ac	tion	rder 📋	C. Safegua	rd 🔲 D.	. Written Notice	• 🗆	E. Citati Orde	on/ Numbe	er			F. Dated	Mo Da	Yr
15. Area or	Equipment													
16. Termina	tion Due	A. Dat	Mo Da 03/31/20	`` [2	3. Time (24 Hr.	Clock)	1	130						
Section III-To	ermination Ac	ion									1	1	20120	
	o Terminate				removed	fro	m the	e cha	arger.	The c	cnarg	er is i	PETING	
powere	ed from	n the	e surfa	ce.										
18. Termina	A. Dan	03	o Da Yr /31/2006	B. Time	(24 Hr. Clock		1130				<u></u>			
	lutomated Syr	tem Dat					т	04 D-2-	and or Maria					
19. Type of (activity	f Inspection y code)	El	20. Even	t Number	4134	415		21. PM	nary or Mill					
22. Signatu	ure	(7					23	S. AR Nur	nber	P	

MSHA Form 7000-3, Mer 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ornbudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ornbudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration of the National Ombudsman at Small B

U.S. Department of Labor Mine Safety and Health Administration



Section I-Vic	plation Data		3. Citation/	## ## ## ## ## ## ## ## ## ## ## ## ##
1. Date	Mo Da Yr	2. Time (24 Hr. Clock) 1130	Order Nu	mber 7583317
4. Served 1		nce Superintendent	5. Operator WOLF RUN MINING COMPAN	Υ
6. Mine			7. Mine ID 46-08791	(Contractor)
SAGO N				8a. Written Notice (103g)
O Conditio	o or Practice			

The 575 volt ungrounded (unshielded) power conductors of the No.6 cable supplying power to the No.8 charger located on the surface were feed from under ground were not provided with lightning arrestors.

								See C	ontinuation	Form (MSHA	Form 7000-3a)
. Violation	A. Health Safety Other	· ☑	B. Section of Act			Part/Section of Title 30 CFR		7	5.521		
ection II—inep	ector's Evalua	ntion								· · · · · · · · · · · · · · · · · · ·	
0. Gravity: A. Injury o	or illness (ha	18) (is):	No Likeliho	od 🗌 🔰	Unlikely 🗌	Reasonably	Likely 🗹	Highly Like	y 🗆	Occur	ed [
	or itiness co		No Lost	Workdays [Lost Worl	days Or Restric	ated Duty 🗌	Perman	ently Disa	bling 🗌	Fatal 🗹
	cent and Su			₩ No [D. Numbe	r of Perso	ns Affected:	001
11. Negligen	ce (check o	ne)	A. None	B. Lo	w 🗌 C.	Moderate 🗹	D. High		E. Reck	ess Disrega	ird 🗌
12. Type of	Action	104(a)		13. Type of las	uance (check o	ne)	Citation 🗹	Orde	r 🗌	Safeguard
14. Initial Ac	tion	rder 🗌	C. Safegua	rd D. Wri	itten Notice	E. Citation/ Order Nur	nber			F. Dated	Mo Da Yr
15. Area or	Equipment										
16. Termina	tion Due	A. Date	Mo Da 03/31/2	· IR Tir	ne (24 Hr. Clock	1130		-			
Section III-Te	mination Act							 	 		
17. Action to	o Terminate	The	cable	was re	moved fr	om the m	ine. Th	e char	ger i	s beir	ıg
powere	d from	n the	surfa	ce.							
18. Termina	A. Dat	03/	Da Yr 31/2006	B. Time (24 h	Ir. Clock	1130					
	utomated Sys	tem Data									
19. Type of (activity		E16	20. Even	t Number	4134415	21. F	rimary or Mill				
22. Signatu	ire		6		7			23.	AR Numb	er/	6 7

MSHA Form 7000-3, Mer 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudaman annually evaluates enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration



Section IViolation Data	3. Citation/ 7592319
1. Date Mo Da Yr 2. Time (24 Hr. Clock)	3. Citation/ 7583318
03/31/2006 1130 4. Served To Dick Wilfong, Maintenance Superintendent	5. Operator WOLF RUN MINING COMPANY
6. Mine	7. Mine ID 46-08791 (Contractor)
SAGO MINE 8. Condition or Practice	8a. Written Notice (103g)

The 7200 volt high voltage cable at the 4C transformer of the 27 crosscut of No.4 belt was not properly installed. The cable was hung approximately 18 inches lower than the required 6.5 feet from the mine floor and was not guarded where miners are required to travel and work under it. This condition existed for about 15 feet in length.

								See C	Continuation Form (MSHA	Form 7000-3a)
9. Violation	A. Health Safety Other		3. Section of Act			art/Section of itle 30 CFR		7	5.807	
Section II-Inspe	ector's Evalua	tion								
10. Gravity:	r Iliness (ha		No Likelihood 🗌	Unlikely 🗹		Reasonably Like	ely 🗆	Highly Lik	ely Occum	ed 🗌
B. Injury o	r iliness cou	ald rea-	No Lost Works	ays Lost	Workd	lays Or Restricted	Duty 🗌		ently Disabling	Fatal 🗹
	ant and Sul		Yes 🗌	No 🗹				D. Numbe	r of Persons Affected:	001
11. Negligen	ce (check o	ne)	A. None	B. Low 🗌	C. M	oderate 🗹	D. High		E. Reckless Disrega	nd 🗌
12. Type of A	Action	104(a)	13. Type o	of Issu	ance (check one		Citation 🗹	Order 🗌	Safeguard [
14. Initial Act	tion	der 🗍	C. Safeguard	D. Written Notice		E. Citation/ Order Numb	er		F. Dated	Mo Da Yr
15. Area or E		A. Date	Mo Da Yr	B. Time (24 Hr. C	lock)	1130				
Section III-Te	rmination Act	iori	03/31/2006	<u></u>						
17. Action to			cable is	properly	gua	rded.				
18. Termina	A. Dat	03/3	Da Yr 31/2006 B. Tim	e (24 Hr. Clock		1130				
Section IVA		tem Data				Tot mi				
19. Type of (activity		E16	20. Event Numb	er 41344	15	21. Prin	nary or Mill			
22. Signatu	re		6					23	. AR Number	6

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration



Section IVi	olation Data		3. Citation/ 7593310	
1. Date	Mo Da Yr 03/31/2006	2. Time (24 Hr. Clock) 1130	3. Citation/ Order Number 7583319	
4. Served	То	nce Superintendent	5. Operator WOLF RUN MINING COMPANY	
6. Mine	mong, wanten		7. Mine ID 46-08791 (Con	ntractor)
SAGO N			8a. Written Notice (10	03g) 🗌
A 0	an an Dractice			-

The No.6 Fairchild battery powered scoop Serial Number 339-346, approval No. 2G-3599-2 located on the 1st. Left unit was not maintained in permissible condition as approved. The battery plugs were not properly assembled: The locking devices securing the sections of the plugs together were not tight, allowing the sections to unscrew.

							See Co	ontinuation	Form (MSHA	Form 7000-3a)	
. Violation	A. Health Safety Other		3. Section of Act		C. Part/Section of Title 30 CFR	•	7:	5.503		<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	
Section II—Inspe	ctor's Evalua	don							· · · · · · · · · · · · · · · · · · ·		
10. Gravity: A. Injury o	r Iliness (ha	s) (is):	No Likelihood	Unlikely 🗹	Reasonably	Likely 🗌	Highly Like	y 🗆	Occum	ed 🗌	
B. Injury o	r iliness cou	ild rea- d to be:	No Lost Wor	kdays 🗌 Lost V	Vorkdays Or Restri	cted Duty 🗹		ently Disal		Fatal	
	ant and Su		Yes [No 🗹		<u> </u>	D. Number	of Persor	rs Affected:	001	
11. Negligen	ce (check o	ne)	A. None	B. Low	C. Moderate	D. High		E. Reckl	ess Disrega	ard 🗌	
12. Type of A	Action	104(8	1)	13. Type o	f Issuance (check	one)	Citation 🗹	Orde	r 🗌	Safeguard	ı 🗌
14. Initial Act	tion	der 🗌	C. Safeguard	D. Written Notice	E. Citation/ Order Nu	mber		1	F. Dated	Mo Da Y	ï
15. Area or E								·			
16. Terminat	tion Due	A. Date	Mo Da Yr 03/31/2006	B. Time (24 Hr. Cl	lock) 113	0					
Section IIITe	rmination Act					<u></u>				····	
17. Action to	Terminate	The	battery	plugs were	properly	assembl	ed. 				
18. Termina	A. Data	03/	Da Yr 31/2006 B. T	ime (24 Hr. Clock	1130						
Section IVA	utomated Sys	tem Deta									
19. Type of (activity		E16	20. Event Nun	41344	1521.	Primary or Mill					
22. Signatu	re	6	,				23.	AR Numb	er	6 7	

MSHA Form 700-3, Mar 85 (revised)
In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1995, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

Mine Citation/Order	U.S. Department of Labor Mine Safety and Health Administration	
Section IViolation Data 1. Date	3. Citation/ Order Number 7583320	
4. Served To Dick Wilfong, Maintenance Superintendent	WOLF RUN MINING COMPANY	
6. Mine SAGO MINE	7. Mine ID 46-08791 (0	Contractor)
8. Condition or Practice The No.6 Fairchild battery powered score 2G-3599-2 located on the 1st. Left unit maintained fire suppression system. The discharged. (1) the chemical tank was empty, (2) the chemical expellant cartridge was (3) the disc that holds the chemicals (4) the actuator in the operators deck	e fire suppression system had been as discharged, into the tank was ruptured, and	No.

									See Co	ontinuation Form (MSHA	Form 7000-3a)
9. Violation	A. Health Safety Other	z	3. Section of Act			C. Part/Sect Title 30 C			75.11	07-16(b)	
Section II-Insp	ector's Evalue	tion									
10. Gravity: A. Injury o	or Ifiness (ha	s) (is):	No Likelihoo	d []	Unlikely 🗹	Reaso	nably Lil	cely 🗌	Highly Like	iy 🗌 Occum	ed 🗌
B. Injury o	or illness cou	ild rea-	No Lost	Workdays [Lost \	Vorkdays Or	Restricte	d Duty 🗹		ently Disabling	Fatal 🗌
	cent and Sut		Yes	No {	Z				D. Number	of Persons Affected:	001
11. Negligen	ce (check o	ne)	A. None	B. Lo	w []	C. Moderate	\mathbf{Z}	D. High		E. Reckless Disrega	rd 🗌
12. Type of		104(8	<u>)</u>		13. Type o	f Issuance (c	neck one)	Citation 🗹	Order 🗌	Safeguard
14. Initial Ac	tion	<u>-</u>	C. Safeguar	d [D. Wi	ritten Notice	E. Cita	ition/ er Numb	per		F. Dated	Mo Da Yr
15. Area or		A. Date	Mo De N	· 18 Ti	me (24 Hr. C	lock)	1130				
Santan M. Ta	ermination Act		03/31/20	00		<u>,</u>					
17. Action to	o Terminate	The		cal tar		ull. Th	e ex	pellan	it, act	uator cartr	ridge,
18. Termina	A. Dan	03/3	Da Yr 31/2006	B. Time (24	Hr. Clock	1130					
	untornated Sys	tem Data					24 Pe	mary or Mill	 		
19. Type of (activity	f inspection y code)	E16	20. Event	Number	41344	15	21. PII	III GIY UI MINI			
22. Signatu		-	.6		T				23.	AR Number	6

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudarnan and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudarnan annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudarnan at Small Business Administration, Office of the National Ombudarnan, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudarnan at Small Business Administration, Office of the National Ombudarnan, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudarnan at Small Business Administration, Office of the National Ombudarnan, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudarnan at Small Business Administration, Office of the National Ombudarnan, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudarnan at Small Business Act of 1996, the Small Business Administration of the National Ombudarnan and 10 Regional Pairwas Boards to receive comments from small Business Act of 1996, the Small Business Administration of 1996, the Small Business Act of 1996, t

U.S. Department of Labor Mine Safety and Health Administration



ection I-Violatio	n Data Mo Da Y	r T	2. Time (24 Hr. Cloo	zk)			3. Citatio	n/ 7	583321		-	
	03/31/20		1130				Older	Milliper				
. Served To					5. Operator							
Dick Wilfor	ng, Maint	enance	Superintendent			WOLF RUN MINING COMPANY						
. Mine	<u> </u>				7. Mine ID	46-0879	1			(Contra	actor)	
SAGO MIN					<u>.l</u>			8a.	Written N	otice (103g) 🗆	
. Condition or	Practice				on Coris	1 Numbe	r 339-					
The No.	3 Fair	chil	d battery	powered sco	op serre	t maint	ained	in per	missi	ble		
2G-3599	-2 loc	ated	on the Is	st. Left uni	C was in) C MICELLIC	.011100	# F				
conditi	on as	appr	oved.		aida was	not nr	ronerly	v assem	bled.	The		
(1) the	batte	ry p	lug on the	e operators	Side was	, not pr	.opcii.	, 4555				
locking	screw	s we	re loose,		store e	ido hatt	erv n	lug lea	d was	bust	ed	
(2) the	prote	ctiv	e conduit	on the oper	ators s.	ide back	cty p.	-ug				
and con	tained	lah	ole in it,	,	ad appa	site the	oner	ator wa	s dam	aged	and	
(3) the	condu	iit c	n the batt	ery plug le	ad oppos	orce cue	e oper	acor no		y		
missing	for 1	.4 in	ches in le	ength,	duit cl	a mro						
(4) thi	s same	sic	ie was mis	sing the con e same side	was dam	aded and	d need	s repla	ced.	the		
(5) the	batte	sia t	olug on the	e same side	was dam	agea a			•			
inner i	.nsulat	cion	was broke	n,			See	Continuation F	orm (MSHA	Form 7000-3	34) 🗹	
9. Violation	A. Health Safety Other	2	B. Section of Act	C.	Part/Section of Title 30 CFR			75.503				
Section II—Insp												
10. Gravity:								. —	_	. —		
	r Iliness (ha	s) (is):	No Likelihood 🗌	Uniikely 🗹	Reasonably	Likely 🗌	Highly LI	kely 🗌	Occum	M 📋		
B. Injury o	r illness cou be expecte	id rea-	No Lost Workd	ays Lost Worl	days Or Restri	cted Duty 🗹	Perma	nently Disabi	ing 🗌	Fatal []	
	ant and Su		Yes [No ☑			D. Numb	er of Persons	Affected:	001		
11. Negligen	ce (check o	ne)	A. None	B. Low C.	Moderate 🔽	D. High		E. Reckles	s Disrega	rd 🗌		
12. Type of	Action	104(a)	13. Type of is:	suance (check	one)	Citation 🗹	Order		Safegu	uard 🗌	
14. Initial Ac		der 🔲	C. Safeguard	D. Written Notice	E. Citation/ Order Nu	mber		F.	Dated	Mo Da	ı Yr	
15. Area or E	Equipment											
,												
16. Termina	Hon Dun		Mo Da Yr									
IO. I BIIIIIII	UOII DOG	A. Date	03/31/2006	B. Time (24 Hr. Clock) 1130)						
Section III-Te	rmination Act											
17. Action to	Terminate	The	machine w	as restored	to perm	nissible	condi	ition b	y rep	lacin	g	
the ba	tterv	rece	ptacle, ba	ttery plug,	conduit	condu	it cla	amp, an	d pro	perly		
assemb				real proof.		•		-	-			
18. Termina		Mo	Da Yr	e (24 Hr. Clock	1130							
Section IV-A	domated See		31/2006			1						
19. Type of			20. Event Number	er 4134415	21. 1	rimary or Mill						
(activity	code)	E16	1	4124412			133	. AR Numbe	, , –	1	,	
22. Signatu	re	6	·					. AR Numbe		6		
				the three new delegate of the Con	all Business Part	latory Enforceme	ent Fairness A	ct of 1996, the	Small Busin	ess Adminis	stration has	

MSHA Form 7000-3, Mar 85 (revised)
In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

Mine Citation/Order Continuation

U.S. Department of Labor Mine Safety and Health Administration

·//_

CONTRIDUCTION							
Section I-Subsequent Action/Continuation Data 1. Subsequent Action 1a. Continuation	2. Dated	Mo Da	Yr	3. Citation/	7583321		_
	(Original Issue)	03/31/20	06 5. Operate	Older Hariber	7505521		-
4. Served To			WOLF		_		
Dick Wilfong, Maintenance Superi	ntendent		7. Mine I	`		(Contractor)	
6. Mine			\	′ 46-0879			
SAGO MINE							_
Section II-Justification for Action							

Continuation of 8. Condition or Practice

(6) the battery end receptacle on the operators side was damaged, the inner insulation and threads area were busted.

							See Continuation Form
Section III—Subsequent	t Action Taken						
8. Extended To A.	Mo Da Date	Yr B. Time	B. Time (24 Hr. Clock)		C. Vacated	D. Terminated	E. Modified
Section IV-Inspection	Deta						
9. Type of Inspection	on E16	10. Event Nur	nber 4134415				
11. Signatur	6		AR Number	12. Date	Mo Da Yr 03/31/2006	13. Time (24 Hr. C 1130	

MSHA Form 7000-3a, Mar 85 (revised)

U.S. Department of Labor Mine Safety and Health Administration

Section I-Vic	plation Data		3. Citation/ 7592322							
1. Date	Mo Da Yr	2. Time (24 Hr. Clock)	3. Citation/ 7583322							
03/31/2006	1130	5. Operator								
4. Served 7	Го		WOLF RUN MINING COMPANY							
Dick Wil	lfong, Maintenan	ce Superintendent								
6. Mine			7. Mine ID 46-08791 (C	Contractor)						
SAGO N			8a. Written Notice	(103g)						
8. Conditio	n or Practice		live 575 molts to the No.4 discor	nect						

The circuit breaker and receptacle supplying 575 volts to the No.4 disconnect and scoop charger located at 1st left 28 cross cut was not properly identified.

							_		See C	continuation	n Form (MSHA	Form 7000-3a)
9. Violation	A. Health Safety Other	⋈ ¯	. Section of Act			C. Part/Section of Title 30 CFR			75.904			
Section II-Inspe	ctor's Evalua	tion										
10. Gravity: A. Injury o	r Illness (ha	s) (is):	No Likelihood 🗌	Unlikely 🗌		Reasonably L	ikely 🛂	1	Highly Lik	ely 🗌	Occum	d 🗌
B. Injury o	r illness cou be expecte	ıld rea-	No Lost Workd	gys 🗌 Lost V	Vorkd	ays Or Restric	ted Duty				abling 🗌	Fatal 🗹
	ant and Su		Yes 🗹	No 🗌					D. Numbe	of Pers	ons Affected:	001
11. Negligen	ce (check o	ne) /	A. None	B. Low	C. M	oderate 🗹	D.	High		E. Reci	kless Disrega	rd 🗌
12. Type of A		104(a)	13. Type o	f Issu	ance (check or	10)	С	itation 🗹	Ord	er 🗌	Safeguard [
14. Initial Act	tion	· · · · · ·		D. Written Notice		E. Citation/ Order Nun	nber				F. Dated	Mo Da Yr
16. Terminal	tion Due	A. Date	Mo Da Yr 03/31/2006	B. Time (24 Hr. Cl	ock)	1130						
Section III-Te	rmination Act	lon	03/31/2000				<u>_</u>					
17. Action to	Terminate	The		reaker, r	ece	ptacle	and (dis	connec	ting	device	were
18. Termina	A. Date	03/3	Da Yr 1/2006 B. Tim	e (24 Hr. Clock		1130						
Section IVA		tem Data				104.5		- BAIM				
19. Type of (activity		E16	20. Event Number	er 41344	15	21. P	rimary o	r Min				, ,
22. Signatu	ne	6							23	. AR Nun	nber [<u> </u>

MSHA Form 7000-3, Mer 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small business about federal agency enforcement actions. The Ombudaman annually evaluates enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration

|--|

Section I-Violation Data	3. Citation/ 7583323
1. Date Mo Da Yr 2. Time (24 Hr. Clock)	Order Number 7303323
03/31/2006 1130	5. Operator
4. Served To	WOLF RUN MINING COMPANY
Dick Wilfong, Maintenance Superintendent	
6. Mine	7. Mine ID 46-08791 (Contractor)
SAGO MINE	8a. Written Notice (103g)
8. Condition or Practice	terla supplying 575 volts to the No.16 disconnect

The circuit breaker and receptacle supplying 575 volts to the No.16 disconnect and scoop charger located at 1st left 28 cross cut was not properly identified.

										See	Continuatio	on Form (MSHA	Form 7000-	38)
9. Violation	A. Health Safety Other	⋥ ¯	. Section of Act		C. Part/Section of Title 30 CFR 75.904									
Section II-Inspe	ctor's Evalua	tion												
10. Gravity: A. Injury o	r Iliness (ha	s) (is):	No Likeliho	od []	Unlikely []	Reasons	ibly Like	y 🗹	Highly Li	kely 🗌	Occum	ed 🗌	
B. Injury o	r illness cou be expecte	id rea-	No Lost	Workdays	Lost	Workd	ays Or Re	stricted	Duty 🗌			sabling	Fatal	Z
	ant and Sul		Yes	☑ No						D. Numb	er of Peni	ions Affected:	001	
11. Negligeno	ce (check o	ne)	A. None	8.	Low 🗌	C. M	oderate	Z	D. High		E. Rec	kless Disrega	nd 🗌	
12. Type of A	Action	104(a)		13. Type	of Issu	ance (che	ck one)	(Citation 🗹	Or	der 🗌	Safeg	uard 🗌
14. Initial Act	tion		C. Safegua	rd D.	Written Notice		E. Citati Order	on/ Number				F. Dated	Mo D	a Yr
15. Area or E		A. Date	Mo Da 03/31/20	. 18	Time (24 Hr. (Clock)	1	130						·
Section IIITer	mination Act	on												
17. Action to proper	Terminate	The		it bre	eaker, 1	cece	ptacl	e an	d dis	conne	cting	device	were	
18. Termina	A. Dat		Da Yr 1/2006	B. Time (2	24 Hr. Clock		1130							
Section IV-A	utomated Sys	tem Data					- 1	24 Delev						
19. Type of (activity		E16	20. Even	Number	41344	115	[21. PRM	ary or Mill					
22. Signatur	re		6		T					2	3. AR Nur	nber 6		

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small business about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration

|--|

Section I-Violation Data 1. Date Mo Da Yr 2. Time (24 Hr. Clock)			3. Citation/ Order Number 7583324	_
4. Served T	03/31/2006 To	1130	5. Operator WOLF RUN MINING COMPANY	
Dick Wilfong, Maintenance Superintendent 6. Mine SAGO MINE		CC Supermies	7. Mine ID 46-08791 (Contractor 8a. Written Notice (1039))

8. Condition or Practice

The No 6/5 cable supplying 575 volts to the No.16 scoop charger located at 1st left 28 cross cut was not provided with proper short circuit protection. The circuit breaker was set at 1000 amps and the maximum allowable setting is 300 amps.

								_		see Continuati	on Form (MSH/	Form 7000	-3e) 🗌
9. Violation	A. Health Safety Other		B. Section of Act				art/Section of the 30 CFR			75.518			
Section II-Inspe	ctor's Evalua	don											
10. Gravity: A. Injury of	r Iliness (ha	s) (is):	No Likeliho	od []	Unlikely 🗹		Reasonably	Likely 🗌	Highly	Likely 🗌	Оссиг	red 🗌	
B. Injury or sonably	r illness cou	ild rea- d to be:	No Lost	Workdays [] Lost \	Workd	ays Or Restri	cted Duty		manently Di		Fatal (<u>v</u>
C. Signific	ant and Sul	ostantia	: Yes	☐ No {	<u> </u>				D. Nu		sons Affected		
11. Negligeno	ce (check o	ne)	A. None	B. Lo	w 🗌	C. M	oderate 🗹	D. Hi	gh 🗌	E. Rec	kless Disreg	ard 🗌	
12. Type of A	ction	104(a)		13. Type 0	of Issu	ance (check o	one)	Citation	☑ On	der 🗌	Safeç	juard 🗌
14. Initial Act			C. Safegua	rd 🔲 D. Wi	itten Notice		E. Citation/ Order Nu	mber			F. Dated	M o D	a Yr
15. Area or E	Equipment					<u> </u>							,
16. Terminati	ion Due	A. Date	Mo Da 03/31/20	· IRT	me (24 Hr. C	lock)	1130						·
Section III-Ter	minetion Acti	on .											
17. Action to	Terminate	The	circu	it brea	ker wa	s s	et to 3	300 amp	os.				
18. Terminal	A. Date	03/	Da Yr 31/2006	B. Time (24	Hr. Clock		1130						
Section IVAu	tomated Sys	tem Deta											
19. Type of I		E16	20. Even	Number	41344	15	21. 1	Primary or M	AUF				
22. Signatur	re /	4	>		7					23. AR Nu	mber	6	

MSHA Form 7000-3, Mer 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudamen and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please nots, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration



tion IViolati		2. Time (24 Hr. Clo				3. Citation	7. 75	83325		
Date	Mo Da Yr	2. Time (24 Hr. Cid	(CK))	·		Order I	lumber /			
7.	03/31/2006	115	·	5. Operator		COL 4D A	NIV			
Served To	na Maintenano	e Superintenden	t	WOLF RUI	MINING	COMPA	NI			
	olig, Maintenant	- S-P		7. Mine ID	46-08791	l			(Contrac	ctor)
Mine MO MIII	NE			<u> </u>			8a. ¹	Written Not	ice (103g	
Condition C	or Practice			h	locate	i in t				
ne 480	volt 3 p	hase 58 ho	rse power fly	ygt pump	tible c	anditi	on as	pprov	red.	
eturn	air cours	e was not	maintained i	7	~					
1) the	e system W	as powered	by a 600 vo	r syste	 ad with	a nor	permi	ssible	shop	,
2) the	e permissi	pre courro	Tier was see			•				
uilt (controller	,			intring	ically	, safe	120 vo	olt	
3) the	e floats l	ocated wit	h the pump w iring SO cab	ere non le was s	nivladu	g the	contro	l circ	cuit,	
ype,	and incorr	ect type w	iring be eas			_				
nd					-+ ~ ~	wit n	rotecti	on. Th	ne	
4) th	e motor wa	s not prov	rided with pr : 750 amps an	d the al	lowable	sett	ing for	this	pump	is
ircui	t breaker	was set at	, 100 amps an							
07 am	ps.								7000	Г
						See	Continuation Fo	rm (MSHA F	om /000-	(a)
. Violation	A. Health	B. Section	C.	Part/Section of		75	.507-1(a)			
, Viciation	Safety 🗹	of Act		Title 30 CFR		7.5	.507-1(a)			
	Other									
	pector's Evaluation							0	- -	
10. Gravity: A Injury	or iliness (has) (is)	: No Likelihood [Unlikely 🗌	Reasonably	ikely 🔽	Highly LI	kely	Occurre		
R Injury	or illness could rea	- Al-14 18/ord	I net Wor	kdavs Or Restric	ted Duty 🔽	Perma	nently Disabli	ng 🗀	Fatal 🗌]
sonal	or illness could rea bly be expected to b	e: 110 COST 175.1	days Lost Wor	kdays Or Restric	ted Duty 🗹]
sonal	or illness could read bly be expected to b ificant and Substant	e: 110 COST 175.1	kdays	kdays Or Restrik	ted Duty 🗹		er of Persons	Affected:	001]
sonat C. Signi	by be expected to b	e: 140 2004 1110.1	No 🗆	kdays Or Restric	ted Duty 🗹 D. High	D. Numb		Affected:	001	
c. Signi	bly be expected to b ficant and Substant ence (check one)	e: Yes 🗹	No B. Low C.		D. High	D. Numb	er of Persons	Affected:	001	uard [
C. Signi 11. Neglige	oly be expected to bufficent and Substant ence (check one) f Action 10	e: Yes 🗹	No B. Low C.	Moderate suance (check of E. Citation/	D. High	D. Numb	E. Reckles	Affected:	001	uard [
C. Signi 11. Neglige	oly be expected to bufficent and Substantience (check one) If Action 10	e: Yes 🗹 A. None 🗌	No B. Low C.	Moderate 🗹	D. High	D. Numb	E. Reckles	Affected:	001	uard [
c. Signi 11. Neglige 12. Type o 14. Initial A A. Citatie	oly be expected to bufficant and Substant ence (check one) f Action 10 Action B. Order	e: Yes 🗹 A. None 🗌	No B. Low C. 13. Type of Is	Moderate suance (check of E. Citation/	D. High	D. Numb	E. Reckles	Affected:	001	uard [
c. Signi 11. Neglige 12. Type o 14. Initial A A. Citatie	oly be expected to bufficent and Substantience (check one) If Action 10	e: Yes 🗹 A. None 🗌	No B. Low C. 13. Type of Is	Moderate suance (check of E. Citation/	D. High	D. Numb	E. Reckles	Affected:	001	uard [
c. Signi 11. Neglige 12. Type o 14. Initial A A. Citatie	oly be expected to bufficant and Substant ence (check one) f Action 10 Action B. Order	e: Yes 🗹 A. None 🗌	No B. Low C. 13. Type of Is	Moderate suance (check of E. Citation/	D. High	D. Numb	E. Reckles	Affected:	001	uard [
C. Signi 11. Neglige 12. Type of 14. Initial A A. Citatie 15. Area of	oly be expected to be incentially and Substant and Substant ance (check one) of Action 10-Action B. Order Fequipment	e: ial: Yes A. None 4(a) C. Safeguard	No B. Low C. 13. Type of Is D. Written Notice	Moderate suance (check of E. Citation/Order Nu	D. High	D. Numb	E. Reckles	Affected:	001	uard [
c. Signi 11. Neglige 12. Type o 14. Initial A A. Citatie	oly be expected to be incentially and Substant and Substant ance (check one) of Action 10-Action B. Order Fequipment	e: ial: Yes A. None 4(a) C. Safeguard Mo Da Yr	No B. Low C. 13. Type of Is	Moderate suance (check of E. Citation/Order Nu	D. High	D. Numb	E. Reckles	Affected:	001	uard [
C. Signi 11. Neglige 12. Type of 14. Initial A A. Citatio 15. Area of	ificant and Substant ence (check one) f Action Action B. Order r Equipment A. D. Temberton Action	A. None A. None 4(a) C. Safeguard Mo Da Yr 03/31/2006	No B. Low C. 13. Type of Is D. Written Notice B. Time (24 Hr. Clock	Moderate suance (check c E. Citation/ Order Nu	D. High	D. Numb	E. Reckles Order [Affected: s Disregard Dated	001	uard [
C. Signi 11. Neglige 12. Type of 14. Initial A A. Citatio 15. Area of	ificant and Substant ence (check one) f Action Action B. Order r Equipment A. D. Temberton Action	A. None A. None 4(a) C. Safeguard Mo Da Yr 03/31/2006	No B. Low C. 13. Type of Is D. Written Notice B. Time (24 Hr. Clock	Moderate suance (check c E. Citation/ Order Nu	D. High	D. Numb	E. Reckles Order [Affected: s Disregard Dated	001	uard [
c. Signi 11. Neglige 12. Type of 14. Initial A A. Citatio 15. Area of	ificant and Substant ence (check one) f Action Action B. Order r Equipment A. D. Temberton Action	A. None A. None 4(a) C. Safeguard Mo Da Yr 03/31/2006	No B. Low C. 13. Type of Is D. Written Notice	Moderate suance (check c E. Citation/ Order Nu	D. High	D. Numb	E. Reckles Order [Affected: s Disregard Dated	001	uard (
C. Signi 11. Neglige 12. Type of 14. Initial A A. Citatio 15. Area of	ificant and Substant ence (check one) f Action Action B. Order r Equipment A. D. Temberton Action	A. None A. None 4(a) C. Safeguard Mo Da Yr 03/31/2006	No B. Low C. 13. Type of Is D. Written Notice B. Time (24 Hr. Clock	Moderate suance (check c E. Citation/ Order Nu	D. High	D. Numb	E. Reckles Order [Affected: s Disregard Dated	001	uard (
sonal C. Signi 11. Neglige 12. Type of 14. Initial A A. Citatio 15. Area of 16. Termin Section III— 17. Action	ificant and Substant ance (check one) Action 10 Action B. Order r Equipment Termination Action to Terminate Th	A. None 4(a) C. Safeguard 303/31/2006 The complete	No B. Low C. 13. Type of Is D. Written Notice B. Time (24 Hr. Clock	Moderate suance (check of E. Citation/ Order Number 1130) 1 was rem	D. High	D. Numb	E. Reckles Order [Affected: s Disregard Dated	001	uard (
C. Signi 11. Neglige 12. Type of 14. Initial A A. Citatio 15. Area of	phy be expected to be incentially and Substant and Substa	A. None 4(a) C. Safeguard 303/31/2006 The complete	No B. Low C. 13. Type of Is D. Written Notice B. Time (24 Hr. Clock	Moderate suance (check c E. Citation/ Order Nu	D. High	D. Numb	E. Reckles Order [Affected: s Disregard Dated	001	uard (
11. Neglige 12. Type of 14. Initial A A. Citatle 15. Area of 16. Termin Section III— 17. Action	phy be expected to be incentially and Substant and Substa	A. None B. Ti 3/31/2006	No B. Low C. 13. Type of Is D. Written Notice B. Time (24 Hr. Clock	Moderate suance (check of E. Citation/ Order Num 1130	D. High	D. Numb	E. Reckles Order [Affected: s Disregard Dated	001	uard (
Section IV-19. Type	poly be expected to be discard and Substant and Substant and Substant and Substant and Check one) If Action 10- Action B. Order Control B. Order Control B. Order Control Con	A. None B. Ti 3/31/2006	No B. Low C. 13. Type of Is D. Written Notice B. Time (24 Hr. Clock pump system me (24 Hr. Clock	Moderate Suance (check of E. Citation/ Order Number 1130	D. High	D. Numb	E. Reckles Order [Affected: s Disregard Dated	001	uard [
Section IV- 19. Type	poly be expected to be difficent and Substant and Substan	A. None A. Non	No B. Low C. 13. Type of Is D. Written Notice B. Time (24 Hr. Clock pump system me (24 Hr. Clock	Moderate Suance (check of E. Citation/ Order Number 1130	D. High	D. Numb	E. Reckles Order [Affected: s Disregard Dated	001	uard (

MSHA Form 7000-3, Mar 85 (revised) an accordance with the provisions of the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions and proposed page of the National Ombudsman and 10 Regional Fairness Boards to receive comments from small business act or receive comments

U.S. Department of Labor Mine Safety and Health Administration



Section I-Vic	vietico Data					
1. Date	Mo Da Yr	2. Time (24 Hr. Clock) 1130	3. Citation/ Order Numb	7583326		
4. Served 7			5. Operator WOLF RUN MINING COMPANY			
Dick Wilfong, Maintenance Superintendent			7. Mine ID 46-08791	(Contractor)		
SAGO N	AINE			8a. Written Notice (103g)		

8. Condition or Practice

The No.6 cable supplying 575 volts to the No.3 T and T pump located at the 46 block of No.4 belt was not provided with proper short circuit protection. The circuit breaker was set at 700 amps and the maximum allowable is 300 amps. This condition is located at the No. 5 belt transformer.

										See C	ontinuation Fo	orm (MSHA	Form 7000-	3a) 🗌
9. Violation	A. Health Safety Other	\mathbf{Z}	3. Section of Act	-			art/Section itle 30 CFR			7	5.51 8			
Section II-Inspe	ector's Evalue	ition												
10. Gravity: A. Injury o	or Illness (ha	ıs) (ls):	No Likelihoo	d 🗌	Unlikely 🗹		Reasonal	y Likel	<i>,</i> 🗆	Highly Like		Occurre	od 🗌	
B. Injury o	or illness com be expected	uld rea- ed to be:	No Lost	Workdays [Lost \	Norkd	ays Or Res	tricted (Outy 🔽		ently Disabil		Fatal [
C. Signific	ant and Su	bstantial:	Yes	No No	\mathbf{Z}					D. Number	r of Persons	Affected:	001	
11. Negligere	ce (check o	ne)	A. None	B. L	.ow 🗌	C. M	oderate 🔽	3	D. High		E. Reckles	s Disregal	rd 🗌	
12. Type of A	Action	104(8)	-	13. Type o	f Issu	ance (chec	k one)		itation 🗹	Order		Safego	uard 🗌
14. Initial Act	tion	<u>`</u>	C. Safeguar	d [] D. W	/ritten Notice		E. Citatio Order	n/ Number			F.	Dated	Mo Da	Yr
15. Area or E	=quipment											<u>-</u>		
16. Terminal	tion Due	A. Date	Mo Da \\ 03/31/20	127	Time (24 Hr. C	lock)	11	30						
Section III-Ter	rmination Act	ion												
17. Action to	Terminate			ct cir	cuit br	eak ——	er wa:	s in	stall	ed.			<u>., ——</u>	
18. Termina	A. Det	_	Da Yr 31/2006	B. Time (24	Hr. Clock		1130							
Section IV-A	utomated Sys	tem Data			· <u>·</u>				2.511					
19. Type of (activity		E16	20. Event	Number	41344	15	2	I. Prima	ry or Mill					
22. Signatur	re	(6	7						23.	AR Numbe	5	0	

MSHA Form 7000-3, Max 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small business about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration

N//

ection I-Violation Data	3. Citation/ 7583327
Date Mo Da Yr 2. Time (24 Hr. Clock)	Order Number 7363327
. Served To Dick Wilfong, Maintenance Superintendent	5. Operator WOLF RUN MINING COMPANY
Dick willong, Maintenance Supermission	7. Mine ID 46-08791 (Contractor)
SAGO MINE	8a. Written Notice (103g)

The 2nd left 200 horse power belt drive motor was not provided with proper short circuit protection. The circuit breaker was set at 3000 amps and the maximum allowable for this system is 1260.

		See Continuation Form (MSHA!	Form 7000-3a)
Safety (Other) A. Health B. Section of Act	C. Part/Section of Title 30 CFR	75.518	
Section II-Inspector's Evaluation			
10. Gravity: A. Injury or Illness (has) (is): No Likelihood Unlikely 🖳	Reasonably Likely	Highly Likely Occurre	od 🗌
	t Workdays Or Restricted Duty 🗹	Permanently Disabling	Fatal 🗌
C. Significant and Substantial: Yes No		D. Number of Persons Affected:	001
11. Negligence (check one) A. None B. Low	C. Moderate 🗹 D. High	E. Reckless Disrega	rd 🗌
	of Issuance (check one)	Citation 🗹 Order 🗌	Safeguard [
14. Initial Action A. Citation B. Order C. Safeguard D. Written Notice	E. Citation/ Order Number	F. Dated	Mo Da Yr
15. Area or Equipment			
16. Termination Due A. Date Mo Da Yr 03/31/2006 B. Time (24 Hr.	Clock) 1130		
Section III-Termination Action	1.6	-inc due to the	
17. Action to Terminate This belt assembly wa	s removed from the	mine due to the	
destruction from the explosion.			
18. Terminated A. Date Mo Da Yr 03/31/2006 B. Time (24 Hr. Clock	1130		
Section IV-Automated System Data	I Go Driver on Mill		
19. Type of Inspection (activity code) E16 20. Event Number 4134	415 21. Primary or Mill		
22. Signature		23. AR Number	6

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Falmess Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Falmess Boards to receive comments from small business and business and agriculture Regulatory Ombudaman and 10 Regional Falmess Boards to receive comments from small business about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration

|--|

			(7)11(0 0 1 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Section I-Vio			3. Citation/ 7583328	
1. Date	Mo Da Yr	2. Time (24 Hr. Clock) 1130	Order Number 7383328	
4. Served 7	03/31/2006	ce Superintendent	5. Operator WOLF RUN MINING COMPANY	
6. Mine	Hong, Wantenan	oo bapo. a	7. Mine ID 46-08791 (Contra	
SAGO M	MINE		8a. Written Notice (103	
8. Conditio	n or Practice		the No 6 TAT pump located at the track en	try

The No.6 cable supplying power to the No.6 T&T pump located at the track entry of 2nd left unit was not provided with proper short circuit protection. The circuit breaker was set at 480 amps and the maximum allowable for this cable is 300 amps.

								See C	ontinuation	Form (MSHA	Form 7000-3	<u>a)</u>
9. Violation	A. Health [Safety]	-	3. Section of Act			Part/Section of Title 30 CFR		7.	5.518			
Section II-Insp	ector's Evaluat	ion										
10. Gravity:	or liiness (ha		No Likelihoo	d 🗌 U	ntikely 🗹	Reasonably L	ikely 🗌	Highly Like	y 🗆	Occurr	od 🗌	
B. Injury C	or illness cou y be expecte	ki rea-	No Lost 1	Workdays 🗌	Lost Work	days Or Restric	ted Duty 🗹			abling	Fatal [·
	cant and Sub		Yes	□ No 🔽]			D. Number		ns Affected:	001	
11. Negligen	ce (check or	(a)	A. None	B. Lov	v 🗆 C.1	Moderate 🗹	D. High		E. Reck	iess Disrega	rd 🗌	
12. Type of		104(uance (check or	ne)	Citation 🗹	Orde	er 🗌	Safegu	ard 🗌
14. Initial Ac	tion	<u> </u>	C. Safeguan	d 🔲 D. Writ	ten Notice	E. Citation/ Order Num	ber			F. Dated	Mo Da	Yr
15. Area or l			Mo Da Y	r				,,,,				
16. Iemina	mon Due	A. Date	03/31/20	IR Tirr	ne (24 Hr. Clock)	1130						
Section III-Te	ermination Acti	on							<u> </u>		obcor	
17. Action to	o Terminate	The	cable MSH		moved fr	om the p	ump. Tr	nis aba		nt was	ODSEL	-
18. Termina	A. Date		Da Yr 31/2006	B. Time (24 H	r. Clock	1130		, · · · · · · · · · · · · · · · · · ·				
Section IV-A	utomated Syst	em Data										
19. Type of	f Inspection	E16	20. Event	Number	4134415	21. P	rimary or Mill					
22. Signatu			6		7			23.	AR Num	ber	6	

MSHA Form 7000-3, Mar 85 (revised) in accordance with the provisions of the Small Business Regulatory Enforcement Falmess Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Falmess Boards to receive comments from small business about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration

|--|

			Willie Calcity a					
Section I-Vic	olation Data			3. Citation/	7502220			
1. Date	Mo Da Yr	2. Time (24 Hr. Clock)		Order Number	7583329			
	03/31/2006	1130	5. Operator					
4. Served	To 16 Maintenan	ce Superintendent	WOLF RUN	WOLF RUN MINING COMPANY				
	liong, Maintenan	ice Superintendent	7, Mine ID					
6. Mine			7		(Contractor)			
SAGO N	MINE				8a. Written Notice (103g)			
8. Conditio	on or Practice		57516 1	No 7 hattery char	ger powered			
The N	o.6 cable s	supplying power to	the 5/5 Volt	NO. / Dattery char	ort circuit			

The No.6 cable supplying power to the 575 volt No.7 battery charger powered from 2nd left belt transformer was not provided with proper short circuit protection. The circuit breaker was set at 480 amps and the maximum allowable for this cable is 300 amps.

									See	Continuation Fo	MSHA) mm	Form 7000-3a)	
9. Violation	A. Health Safety Other	2	B. Section of Act				url/Section of le 30 CFR			75.518			
Section II Insp	ctor's Evaluat	on											
10. Gravity:					Unlikely 🗸		Reasonably Li	kelv 🗀	Highly Li	kely	Occum	ed 🗌	
	r Iliness (has		No Likelihoo	ж 📋 —								Fotol (
B. Injury o	r illness cou be expected	kd rea- d to be:	No Lost	Workdays [Lost	Workda	rys Or Restrict	ed Duty 🔽	Perma	nently Disabl	ng 📋	Fatel [
	ant and Sub		Yes	□ No	7				D. Numb	er of Persons			
11. Negligen	ce (check on	10)	A. None	B. Le	ow 🗌	C. Mo	derate 🗹	D. Hig	h 🔲 .	E. Recklet	s Disrega	ard 🗌	
12. Type of A	Action	104(a)		13. Type	of Issue	nce (check on	0)	Citation 🗹	Order (Safegua	rd 🗌
14. Initial Ac	tion		C. Safegua	rd D.W	ritten Notice		E. Citation/ Order Num	ber		F.	Dated	Mo Da	Υr
15. Area or t	Equipment												
15. Area or t	tion Due	A. Date	Mo Da		ime (24 Hr. C	Clock)	1130						· · · · · · ·
16. Termina	tion Due		Mo Da 03/31/20		ime (24 Hr. C	Clock)	1130						
16. Terminat	tion Due	on .	03/31/20	006 B. T				e expl	osion a	and rem	oved	from t	he
16. Termina	tion Due	on .	03/31/20	006 B. T			1130	e expl	osion	and rem	oved	from t	he
Section III—Te	mination Action	Thi	03/31/20	006 B. T	s destr	oye		e expl	osion	and rem	oved	from t	he
Section III—Te 17. Action to mine. 18. Termina	mination Actor	Thi	03/31/20 s char Da Yr 31/2006	ger was	s destr	oye	d by the			and rem	oved	from t	he
Section III—Te 17. Action to mine. 18. Termina	ormination Action Terminate A. Date utomated Systems	Thi	03/31/20 s char Da Yr 31/2006	ger was	s destr	oye	d by the	e explo		and rem		from t	he

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small business about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor

7

WILLS CITE			Mine Safety and	Health Administration	
Section IVio				3. Citation/ 75	83330
1. Date	Mo Da Yr	2. Time (24 Hr. Clock)	ł	Order Number 13	63330
	03/31/2006	1130	5. Operator		-
4. Served 1	o Kana Maintenar	ce Superintendent	WOLF RUN M	INING COMPANY	
	Hong, Maintenan	cc Bupermienter	7. Mine ID .4.6	-08791	
6. Mine			40-	-00/91	(Contractor)
SAGO M	INE			8a. \	Written Notice (103g)
8. Conditio	n or Practice		1) 5751+ No	7 trinkle duster	powered
The No	o.6 cable	supplying power to belt transformer wa	the 5/5 voit No	with proper short	circuit
from	2nd left	circuit breaker Wa	as not provided as set at 500 am	mps and the maximu	ım allowable

protection. The circuit breaker was set at 500 amps and for this cable is 300 amps.

								_		see Continu	ation For	n (MSHA I	orm 7000-3	a) [
9. Violation	A. Health Safety Other		3. Section of Act		C	C. Part/Sec Title 30 (75.51	8			
Section II—Insp	ector's Evalua	tion												
10. Gravity: A. Injury o	or liiness (ha	s) (is):	No Likelihood		Jnlikely 🗹	Reaso	onably L	ikely 🗌	Highly	Likely []	Occume	d 🗌	
B. Injury o	r illness cou be expects	ild rea- id to be:	No Lost V	orkdays 🗌	Lost Wo	orkdays Or	Restric	ted Duty 🗸	, ,	manently			Fatal []
C. Signific	ent and Su	ostantial:	Yes [] No [v	<u> </u>				D. Nu	mber of F	ersons /	Affected:	001	
11. Negligen	ce (check o	ne)	A. None	B. Lo	w 🗆 C	. Moderate	• 🗹	D. Hig	gh 🗌	E. 1	Reckless	Disregar	d 🗌	
12. Type of A	Action	104(a)		13. Type of I	ssuance (c	:heck or	ie)	Citation	2	Order []	Safegu	ard 🗌
14. Initial Act		der 🗌	C. Safeguard	D. Wri	tten Notice	E. Cit.	ation/ der Num	ber			F. C	Dated	Mo Da	Yr
15. Area or E			Mo Da Yr	——————————————————————————————————————										
16. Termina	tion Due	A. Date	03/31/200	6 B. Tin	ne (24 Hr. Cloc	:k) 	1130							
Section III-Te	rmination Act													
17. Action to	Terminate	This	unit v	was de	stroyed	by th	ne e:	xplosi	on.					
18. Termina	A. Date	03/3	Da Yr 1/2006 B	Time (24 F	ir. Clock	1130								
Section IV-A		tern Deta			<u> </u>		154 5		T					
19. Type of (activity		E16	20. Event N	umber	4134415	5	21. Pi	rimary or M	ur					
22. Signatu	re /		(0							23. AR	Number)	6	

MSHA Form 7000-3, Mer 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudaman annually evaluates enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration

~	
1	//

	(Mine outst) and the
Section I-Violation Data 1. Date Mo Da Yr 2. Time (24 Hr. Clock) 03/31/2006 1130	3. Citation/ Order Number 7583331
4. Served To Dick Wilfong, Maintenance Superintendent	5. Operator WOLF RUN MINING COMPANY
6. Mine SAGO MINE	7. Mine ID 46-08791 (Contractor) 8a. Written Notice (103g)
8. Condition or Practice	luing power to the No.41 roof bolter located

The 575 volt trailing cable supplying power to the No.41 roof bolter located in the primary intake escapeway at 4 belt block 27 contained a permanent splice with the outer jacket and insulation damaged exposing the power conductors. The splice was not sealed so as to exclude moisture. This splice was very wet on the inside of the splice, and was laying in water.

								See Co	ontinuation F	orm (MSHA	Form 7000-3	a) 🗌
9. Violation	A. Health Safety	1 ⁻	s. Section of Act		C. Part/Se Title 30			75.	604(b)			
ection II-Insp	ctor's Evaluat	on										
10. Gravity:	r Iliness (hat) (is):	No Likelihood 🗍	Unlikely 🗌	Reas	onably Likel	y Y	Highly Like	ly 🗌	Occum	ed 🗌	
B. Injury 0	r illness cou	d rea-	No Lost Workd	lays Lost \	Norkdays O	Restricted I	Outy 🗆	Perman	ently Disabl	ing 🗌	Fatal 🗸	<u> </u>
	ant and Sub		Yes 🗹	No 🗌				D. Number	of Persons	Affected:	001	
11. Nealigen	ce (check on	e) /	A. None	B. Low	C. Moderat	• 🗹	D. High		E. Reckle	ss Disrega	rd 🗌	
12. Type of		104(a	<u> </u>	13. Type o	of Issuance (check one)	C	itation 🗹	Order		Safegu	ard 🗌
14. initial Ac	tion		C. Safeguard	D. Written Notice	1	tation/ der Number			F	. Dated	Mo Da	Yr
15. Area or I	Equipment											·
16. Termina	tion Due	A. Date	Mo Da Yr 03/31/2006	B. Time (24 Hr. C	lock)	1130						
Section III-Te	rmination Action	on										
17. Action to	o Terminate	The	splice wa	as removed	from	the ca	ble.					
18. Termina	A. Date	03/3	Da Yr 31/2006 B. Tim	ne (24 Hr. Clock	1130	·		. <u> </u>				
		em Dete										
Section IV-A			T = 0 - 1.00 - 1			24 Drime	or Mill					
	Inspection	E16	20. Event Numb	er 41344	15	21. Prima	ary or Mill		AR Numbe			

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Falmess Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Falmess Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business.

U.S. Department of Labor



Date Mo Da Yr 03/31/2006 Served To Ck Wilfong, Maintenance Superintendent Mine AGO MINE Condition or Practice the no.41 roof bolter approval 2G-37150 scapeway at 4 belt, block 27 was not approved. 1) the no.4 trailing cable was in exception of the condition	maincaine ==	NG COMPANY 8791 8a	(Contractor) Written Notice (103g)
03/31/2006 1130 Served To Sck Wilfong, Maintenance Superintendent Mine AGO MINE Condition or Practice he no.41 roof bolter approval 2G-37152 scapeway at 4 belt, block 27 was not approved. 1) the no.4 trailing cable was in exc	WOLF RUN MIN 7. Mine ID 46-08 A-0 located in maintained in	NG COMPANY 8791 8a	(Contractor) Written Notice (103g)
Gerved To ck Wilfong, Maintenance Superintendent Mine AGO MINE Condition or Practice ne no.41 roof bolter approval 2G-3715 scapeway at 4 belt, block 27 was not approved. 1) the no.4 trailing cable was in exceptions	WOLF RUN MIN 7. Mine ID 46-08 A-0 located in maintained in	3791 8a	. Written Notice (103g)
ck Wilfong, Maintenance Superintendent Mine AGO MINE Condition or Practice ne no.41 roof bolter approval 2G-3715/ scapeway at 4 belt, block 27 was not approved. 1) the no.4 trailing cable was in exc	7. Mine ID 46-08 A-0 located imaintained in	3791 8a	. Written Notice (103g)
Mine AGO MINE Condition or Practice ne no.41 roof bolter approval 2G-3715; scapeway at 4 belt, block 27 was not in oproved. 1) the no.4 trailing cable was in exc	A-0 located in	n the primary	. Written Notice (103g)
GO MINE Condition of Practice ne no.41 roof bolter approval 2G-3715 scapeway at 4 belt, block 27 was not a proved. 1) the no.4 trailing cable was in exc	A-0 located i	n the primary	. Written Notice (103g)
Condition of Practice ne no.41 roof bolter approval 2G-3715; scapeway at 4 belt, block 27 was not a pproved. 1) the no.4 trailing cable was in exceptions.	maincaine ==	n the primary	
scapeway at 4 belt, block 27 was not a proved. by the no.4 trailing cable was in exc	maincaine ==	n the primary permissible of	
scapeway at 4 belt, block 27 was not a proved. by the no.4 trailing cable was in exc	maincaine ==	J betwraarbre c	ondition as
proved. The no.4 trailing cable was in exc		-	
the no.4 trailing cable was in exc	E 1206 1	Feet in length.	and the
	ess of 1200	_eec in iongo,	
eximum length cable is 600 feet,	cont light W	as not secured	to the frame,
eximum length cable is 600 feet, 2) the front center 120 volt incandes	on degree of	acking gland as	ssembly,
2) the front center 120 voit incandes 3) the same light contained a damaged 4) the operators side center panic ba	r contained	a damaged cable	e restraint
4) the operators side center panic ba	i concarno	<u> </u>	
lamp, 5) the operators side boom end intino	tive safe ci	rcuit junction	box contained
5) the operators side boom end incinc	,0170 5114		
broken entrance gland, and			form (MSHA Form 7000-3a)
		See Continuation F	form (MSHA Form 7000-3a)
Violation A. Health B. Section C.	Part/Section of	75.503	
Safety 🗹 of Act	Title 30 CFR	75.505	
Other			
ction II-Inspector's Evaluation			• 4 🗆
O. Gravity: A. Injury or Illness (has) (is): No Likelihood Unlikely	Reasonably Likely	Highly Likely	Occurred
B. Injury or illness could rea-	kdays Or Restricted Duty	Permanently Disab	iling 🗌 Fatal 🗌
sonably be expected to be:		D. Number of Person	s Affected: 012
C. Significant and Substantial: Yes 🗹 No 🗌			
1. Negligence (check one) A. None B. Low C.	Moderate 🗹 D.	High E. Reckle	ess Disregard
	suance (check one)	Citation 🗹 Order	Safeguard
	E. Citation/	F	. Dated Mo Da Yr
4. Initial Action A. Citation B. Order C. Safeguard D. Written Notice	Order Number		
5. Area or Equipment			
3. Albe of Equipment			
S Termination Due Mo Da Yr			
6. Termination Due A. Date Mo Da Yr 03/31/2006 B. Time (24 Hr. Clock	o) 1130		
Continue III. Termination Action			
Section III—Termination Action	removed, a n	ew light assem	bly was
Section IN-Termination Action 17 Action to Terminate The excessive cable was	removed, a nunction boxe	ew light assem s were repaire	bly was d.
Section III—Termination Action	removed, a n unction boxe	ew light assem s were repaired	d.
Section III—Termination Action 17. Action to Terminate The excessive cable was installed, the restraint clamp, and j	unction boxe	ew light assem s were repaire	bly was d.
Section III-Termination Action 17. Action to Terminate The excessive cable was installed, the restraint clamp, and j 18. Terminated A Date Mo Da Yr B Time (24 Hr. Clock	removed, a n unction boxe	ew light assem s were repaire	bly was d.
Section III—Termination Action 17. Action to Terminate The excessive cable was installed, the restraint clamp, and j	1130	s were repaired	d.
Section III—Termination Action 17. Action to Terminate The excessive cable was installed, the restraint clamp, and j 18. Terminated A. Date Mo Da Yr 03/31/2006 B. Time (24 Hr. Clock Section IV—Automated System Data 19. Type of Inspection Data 20. Event Number 4134415	1130	s were repaired	bly was
Section III—Termination Action 17. Action to Terminate The excessive cable was installed, the restraint clamp, and j 18. Terminated A. Date Mo Da Yr 03/31/2006 B. Time (24 Hr. Clock Section IV—Automated System Data	1130	s were repaired	u.

Mine Citation/Order Continuation

U.S. Department of Labor Mine Safety and Health Administration



Continuation						
Section I—Subsequent Action/Continuation Data 1. Subsequent Action 1a. Continuation	2. Dated (Original Issue)	Mo Da 03/31/20	''	. Citation/ Order Number	7583332	
4. Served To Dick Wilfong, Maintenance Super	intendent		5. Operator WOLF R	UN MININC	COMPANY	(Contractor)
6. Mine SAGO MINE			7. Mille 10	46-0879)1	
Section II—Justification for Action						

Continuation of 8. Condition or Practice

(6) the intrinctive safe circuit junction box under the center covers was not mounted to the frame and contained a damaged entrance gland.

							See Continuation Form
Section III-Subsec	quent Action Taken						
8. Extended To	A. Date Mo Da	Yr B. Ti	ime (24 Hr. Clock)		C. Vacated	☐ D. Terminated	E. Modified
Section IV-Inspec	tion Data						
9. Type of Inspe	ection E16	10. Event I	Number 4134415				
11. Signature	6	1	AR Number	12. Date	Mo Da Yr 03/31/2006	13. Time (24 Hr. C 1130	
MSHA Form 7000)-3a, Mar 85 (revised)	-					

U.S. Department of Labor Mine Safety and Health Administration

7

BOU I—AICHER	on Deta						13. C	tation/	7583	333	
ate	Mo Da Yr	2. Time (24 h	-ir. Clock) 1130					rder Numb	er /363	333	
	03/31/2006	L	1130	5	. Operator						
Served To	ng, Maintenanc	e Superinte	ndent	ĮV	VOLF RU	JN MIN	NG CO	MPANY			
Mine	ng, Mantenane	O Oup		7	. Mine ID	46-08	791			(C	ontractor)
GO MIN	√E								8a. Writi	ten Notice (
Condition o	r Practice			iling cabl	0 01171	alwino	575	volts	power	to th	e
.41 r	coof bolte not provi- The circu	r locat	ed in t	iling cabi he primary r short ci set at 70	-cuit	prote	ction	for	this le	ength	
Violation	A. Health Safety	B. Section of Act			art/Section of	of .		See Contin	uation Form (N	MSHA Form 7	7000-3e)
	Other										
ection II—insp 0. Gravity:	pector's Evaluation				,				^	saumad [1
	or Iliness (has) (is):	No Likeliho	od 🔲 🔝	Unlikely 🗌	Reasonabl	y Likely 💆	Hig	hly Likely		ccurred	1
	or illness could rea										4-1 [7
o. Injury		No Lost	Workdays _	Lost Workda	rys Or Rest	ricted Duty	[] F	eunaneur	/ Disabling	✓ ra	tal 📋
sonab	ly be expected to b): 140 COSt	Workdays [rys Or Rest	ricted Duty			Persons Affe		012
sonab C. Signifi	ly be expected to bi icant and Substanti	al: Yes	₩ No []			D. 1	Number of		octed: (012
sonabl C. Signifi 11. Negliger	ly be expected to b icant and Substanti nce (check one)	al: Yes	₩ No [w C. Mo	derate 🗹	D.	D. I	number of	Persons Affe	octed: (012
Sonable C. Signiff 11. Negliger 12. Type of 14. Initial Ad	ly be expected to bicant and Substantince (check one) Action 104 ction	al: Yes A. None	₩ No [] B. Lo]	derate 🗹	D. one)	D. 1	number of	Persons Affe Reckless Di	sregard S	012 - Safeguard
sonable C. Signiff 11. Negliger 12. Type of 14. Initial Ar A. Citatio	ly be expected to bicant and Substantince (check one) Action 104 ction	A. None [No [B. Lo	C. Mo	derate 🗹	D. one)	D. I	number of	Persons Affe Reckless Di Order	sregard S	012 Safeguard
sonable C. Signiff 11. Negliger 12. Type of 14. Initial Ar A. Citatio	ly be expected to be licant and Substantiance (check one) Action 104 ction B. Order Equipment	A. None [No [] B. Lo	C. Mo	derate 🗹	D. one) / umber	D. I	number of	Persons Affe Reckless Di Order	sregard S	012
sonable C. Signifi 11. Negliger 12. Type of 14. Initial Ar A. Citatio 15. Area or 16. Termina	ly be expected to be licant and Substantiance (check one) Action 104 ction B. Order Equipment ation Due A. Da	A. None C. Safegua te Mo Da 03/31/2	No [B. Lo	C. Mo 13. Type of Issua itten Notice	nce (check E. Citation Order N	D. one) / umber	D. I	Number of E.	Persons Affe Reckless Di Order	sregard S	012 - Safeguard
sonable C. Signifi 11. Negliger 12. Type of 14. Initial Ar A. Citatio 15. Area or 16. Termina	ly be expected to be licant and Substantiance (check one) Action 104 ction B. Order Equipment ation Due A. Da	A. None C. Safegua te Mo Da 03/31/2	No [B. Lo	C. Mo	nce (check E. Citation Order N	D. one) / umber	D. I	Number of E.	Persons Affe Reckless Di Order	sregard S	012 - Safeguard
sonable C. Signifi 11. Negliger 12. Type of 14. Initial Ar A. Citatio 15. Area or 16. Termina Section III—T 17. Action 1	ly be expected to be licant and Substantiance (check one) Action 104 ction B. Order Cartion B. Order Cartion B. Order Cartion Cartion Action to Terminate The listed A. Date 0:	A. None Call(a) C. Safegua Mo Da 03/31/2 e circu Mo Da Yr 3/31/2006	No [B. Lo	mw C. Mo 13. Type of Issue itten Notice me (24 Hr. Clock)	nce (check E. Citation Order N	D. one) / umber	D. I	Number of E.	Persons Affe Reckless Di Order	sregard S	012 - Safeguard
sonable C. Signifi 11. Negliger 12. Type of 14. Initial Ar A. Citatio 15. Area or 16. Termina Section III—T 17. Action to	ly be expected to be licant and Substantiance (check one) Action 104 ction B. Order Equipment ation Due A. Date ferminated A. Date Of Automated System Date of Inspection	A. None [] A. None [] I(a) C. Safegua te Mo Da 03/31/2 e circu No Da Yr 3/31/2006 ta 20. Even	No [B. Lo nrd D. Wr Yr 0006 B. Ti	mw C. Mo 13. Type of Issus itten Notice me (24 Hr. Clock) ker was p:	ince (check E. Citation Order N	D. one) / umber	D. I	Number of E.	Persons Affe Reckless Di Order	sregard S	012 - Safeguard
sonable C. Signiff 11. Negliger 12. Type of 14. Initial Ar A. Citatio 15. Area or 16. Termina Section III—T 17. Action 1 18. Termin 19. Type of	y be expected to be licant and Substantiance (check one) Action 104 ction B. Order Equipment ation Due A. Date of Inspection and A. Date of Inspection by code) Equipment E.	A. None [] A. None [] I(a) C. Safegua te Mo Da 03/31/2 e circu No Da Yr 3/31/2006 ta 20. Even	No [B. Lo ard D. Wr Yr 006 B. Time (24)	mw C. Mo 13. Type of Issue itten Notice me (24 Hr. Clock)	ince (check E. Citation Order N	D. one) / umber y adj	D. I	Number of E.	Persons Affe Reckless Di Order	sregard S	012 Safeguard No Da Yi

emorcement actions. The Ombudaman annually evaluates emorcement activities and rates each agently a responsive reason as small outsides. If you may will be continued on the interest actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3t enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3t enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3t enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3t enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3t enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3t enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3t enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman at Small Business Administration, Office of the National Ombudaman at Small Business Administration, Office of the National Ombudaman at Small Business Administration, Office of the National Ombudaman at Small Business Administration of the National Ombudaman at S

U.S. Department of Labor Mine Safety and Health Administration



1. Date		2. Time (24 Hr. Clock)	3. Citation/ Order Number	3. Citation/ Order Number 7583334				
4. Served To	03/31/2006_	1130	5. Operator WOLF RUN MINING COMPANY					
Dick Wilf		ce Superintendent	7. Mine ID 46-08791					
6. Mine SAGO MI	INE		40-08/91	(Contractor) 8a. Written Notice (103g)				
9 Condition								

The No.41 roof bolter located in the primary intake escapeway at No.4 belt block 27 was not maintained in safe operating condition. The hydraulic release, spring applied auto park brakes were not functional. The brake caliper pads were not coming in contact with the brake disc.

				See Continuation Form	n (MSHA Form 7000-3e)
9. Violation A. Health Safety 10 Other	B. Section of Act	C. Part/S Title 3		75.1725(a)	
Section IIInspector's Evaluation					
10. Gravity: A. Injury or Illness (has) (is): No Likelihood 🗌	Unlikely 🗌 Res	sonably Likely 🗹	Highly Likely	Occurred
B. Injury or litness could re sonably be expected to	e- be: No Lost Workday	B ☐ Lost Workdays (or Restricted Duty		
C. Significant and Substan		lo 🗌		D. Number of Persons A	iffected: 001
11. Negligence (check one)	A. None 🗌 B	. Low C. Modern	ite 🗹 D. Hig	h E. Reckless	Disregard
12. Type of Action 10	4(a)	13. Type of Issuance	(check one)	Citation ✓ Order ☐	Safeguard
14. Initial Action A. Citation B. Order	C. Safeguard D.		Citation/ Order Number	F. D	ated Mo Da Yr
15. Area or Equipment 16. Termination Due A. D.	Mo Da Yr	. Time (24 Hr. Clock)	1130		
	03/31/2006 E				
Section III—Termination Action 17. Action to Terminate T	he brake cali	pers were prop	erly adjus	ted.	
IO. FOITHINGTON A Date	Mo Da Yr)3/31/2006 B. Time (24 Hr. Clock 113	0		
Section IV-Automated System D			10. 5	"	
19. Type of Inspection (activity code)	20. Event Number	4134415	21. Primary or Mi	ii	
22. Signature	6	7		23. AR Number	6

MSHA Form 70003, Mer 85 (revised) in accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-858-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudaman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

U.S. Department of Labor Mine Safety and Health Administration



Section I-Vio 1. Date	Mo Da Yr	2. Time (24 Hr. Clock) 1130	3. Citation/ Order Number	7583335
4. Served T	03/31/2006	ce Superintendent	5. Operator WOLF RUN MINING COMPANY	
6. Mine		ce oupermenter	7. Mine ID 46-08791	(Contractor)
SAGO M	IINE			8a. Written Notice (103g)

8. Condition or Practice

The No.41 roof bolter located in the primary intake escapeway at No.4 belt block 27 contained accumulations of combustible material in the form of oil and oil saturated materials. The accumulations were on the electrical components, under all covers, on the brakes components and in the cable reel compartment. The accumulations measured 0 to 10 inches in depth.

							See	Continuation For	m (MSHA For	n 7000-3a)
. Violation	A. Health Safety Other	_ -	. Section of Act		C. Part/Section of Title 30 CFR			75.400		
ection II-Inspi	ctor's Evaluat	on								
0. Gravity:	r iliness (has		No Likelihood 🔲	Unlikely 🗌	Reasonably	Likely 🔽	Highly LI	kely 🗌	Occurred	
B. Injury o	r illness coul	d ree-	No Lost Workd	ays 🗌 Lost W	orkdays Or Restri	cted Duty		nently Disabili	'8 -	atal 🗌
	ant and Sub		Yes 🗹	No 🗌			D. Numb	er of Persons		012
11. Negligen	ce (check of	e) 4	A. None	B. Low	C. Moderate 🗹	D. Hi	gh 🗌	E. Reckles	B Disregard	
12. Type of		104(a		13. Type of	issuance (check o	one)	Citation 🗸	Order [Safeguard [
14. Initial Ac	tion		C. Safeguard	D. Written Notice	E. Citation/ Order Nu	mber		F.	Dated	Mo Da Yr
16. Termina	tion Due	A, Date	Mo Da Yr 03/31/2006	B. Time (24 Hr. Clo	rck) 1130)				
Section III_Te	rmination Activ	20								
17. Action to		The	accumulat	tions were	removed 1	from th	ne mach	ine.		
			Da Yr	o (24 He Clock	1130					
18. Termina	A. Dete	03/3	1/2006 B. Tin	ne (24 Hr. Clock 		<u> </u>				
Section IV-A	utometed Syst	03/3	1/2006			Primary or N	cin T			
	utometed Syst	03/3	112 1197		121	Primary or N		23. AR Numbe		

MSHA Form 7000-5; Mair 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1995, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from anall business about federal agency enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-886-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-886-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-886-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-886-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-886-734-3247), or write the Ombudaman at Small Business Administration and or the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-886-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-886-734-3247), or write the Ombudaman at Small Business Administration and the National Ombudaman at Small Business Administration and the

Mine Citation/Order			U.S. Department of Labor Mine Safety and Health Administration				
Section I-Violation Data 1 Date Mo Da Yr 2. Time (24 Hr. Clock)			3. Citation/ Order Number	7583336			
1. Dete	Mo Da Yr 03/31/2006	1130		Older Hamber			
4. Served T	0		5. Operator WOLF RUN MINING COMPANY				
Dick Wilfong, Maintenance Superintendent		7. Mine ID 46-0879	1	(Contractor)			
6. Mine			40-0075		8a. Written Notice (103g)		
SAGO M	AINE						
8. Conditio	n or Practice	y powered scoop locate	d at the No.3 b	elt 16 blo	ock was not		
The No	o.16 batter	y powered scoop locate					
maint (1) t (2) t (3) t (4) b	ained in sa he 2 front he operator	head lights were broke s side rear light was c release spring appli f the battery trays we	en off and not s broken off and	not secured to	the frame, ed to the frame, nctional, and		

		See Continuation Form (MS	HA Form 7000-3e)
A. Health B. Section of Act Other	C. Part/Section of Title 30 CFR	75.512	
ection II-Inspector's Evaluation			
0. Gravity: A. Injury or Illiness (has) (is): No Likelihood Unlikely	Reasonably Likely 🗸	, aginy array	curred []
B. Injury or ithress could reasonably be expected to be: No Lost Workdays Lo	st Workdays Or Restricted Duty	D. Number of Persons Affect	
C. Significant and Substantial: Yes ✓ No ✓			
11. Negligence (check one) A. None 🗌 B. Low 🗌	C. Moderate 🗹 D. Hig	jh [] E. Reckless Dist	
40 700	pe of issuance (check one)	Citation 🗹 Order 🗌	Safeguard
12. Type of Action 104(a) 13. Type	·	F. Dated	Mo Da Yr
14. Initial Action A. Citation B. Order C. Safeguard D. Written Notice	ce C Citation/ Order Number		
16. Termination Due A. Date Mo Da Yr O3/31/2006 B. Time (24 He	ir. Clock) 1130		
17. Action to Terminate The machine was remove	ved from the mine	and the mine pro	
II. ALIMI TO TOTALISMO THE MICCITETE WAS TOTAL			percy.
18. Terminated A. Date Mo Da Yr 03/31/2006 B. Time (24 Hr. Clock			percy.
18. Terminated A. Date Mo Da Yr 03/31/2006 B. Time (24 Hr. Clock Section IV-Automated System Data	1130		percy.
18. Terminated A. Date Mo Da Yr 03/31/2006 B. Time (24 Hr. Clock Section IV-Automated System Data			percy.

MSHA Form 7000-3, Mar 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombutasman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudaman annually evaluates enforcement actions. The Ombudaman annually evaluates enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudaman at Small Business Administration at Small Business Admi

U.S. Department of Labor Mine Safety and Health Administration



			White Oction, Cities the				
Section IVic	Mo Da Yr	2. Time (24 Hr. Clock)	3. Citation/ Order Number 758	3337			
4. Served	03/31/2006	1130 ce Superintendent	5. Operator WOLF RUN MINING COMPANY				
6. Mine		ce Supermiterios.	7. Mine ID 46-08791	(Contractor)			
SAGO N	MINE on or Practice		8a. W	ritten Notice (103g)			

The No.1 belt hydraulic take up unit, 480 volt motor was not maintained in safe condition. The motor was being powered by a 575 volt system.

					_	See Continuati	on Form (MSHA	Form 7000-3a) 🗌
. Violation	A. Health Safety Other	B. Section of Act		C. Part/Section of Title 30 CFR		75.512		
ection II-Insp	ector's Evaluation							
0. Gravity:		At the Beach	Unlikely 🗸	Reasonably Likely	- []	Highty Likely 🗌	Occum	ad 🗌
	or Illness (has) (is)					Permanently Di	ablica 🗆	Fatal 🗌
B. Injury o	or illness could rea y be expected to t	No Lost Worl	days 🗌 Lost V	Workdays Or Restricted D	outy 🔽			
	cant and Substant		No ☑		_	D. Number of Per	ons Affected:	001
1 Neclices	nce (check one)	A. None	B. Low	C. Moderate	D. High	☐ E. Re	ckless Disrega	rd 🗌
			13 Type 0	of Issuance (check one)	C	itation 🗹 Or	der 🗌	Safeguard 🔲
2. Type of	Action 10	4(a)	13. 1996				F. Dated	Mo Da Yr
4. Initial Ac		C. Safeguard	D. Written Notice	E. Citation/ Order Number				
15. Area or l		Mo Da Yr	B. Time (24 Hr. C	lock) 1130				
		03/31/2006						
Section III-To	ermination Action			nstalled. Th		ndition Wa	s obset	hatt
					is co		13 00002	. veu
17. Action t	to Terminate A	575 volt n 6	MSHA.	nstalled. III	is co			veu
17. Action to correct	ated A. Date	У Мо Da Yr)3/31/2006 В. Т	MSHA.	1130	is co			veu
17. Action to COTTEC	ated A. Date	Ф Мо Dai Yr 03/31/2006 В. Т	MSHA . ime (24 Hr. Clock	1130				veu
17. Action to Correct 18. Termina Section IV-A 19. Type of	ated A. Date Automated System D	У Мо Da Yr)3/31/2006 В. Т	MSHA . ime (24 Hr. Clock	1130		123. AR N		· · ·

MSHA Form 7000-3, Mer 85 (revised) In accordance with the provisions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small business and susiness and Agriculture Regulatory Ombudaman and 10 Regional Fairness Boards to receive comments from small business. If you wish to comment on the enforcement actions. The Ombudaman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-886-734-3247), or write the Ombudaman at Small Business Administration, Office of the National Ombudaman, 409 3rd enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-886-734-3247), or write the Ombudaman at Small Business Act of 1996, the Small Business Administration has each agency a responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-886-734-3247), or write the Ombudaman at Small Business Act of 1996, the Small Business Administration has agency and small business and small business Administration has a small business and specific federal agency are commented from small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-886-734-3247), or write the Ombudaman at Small Business Act of 1996, the Sm