




Structurally Deficient Bridges on the National Highway System Georgia - Congressional District 08



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 33 structurally deficient NHS bridges in Georgia, 6 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	15300420	I-75 SBL	4 MI SW OF EKLO
2	2100080	US 41 SBL, SR 49	SOUTH EDGE OF MACON C.L.
3	2100940	I-75	IN NORTH CENTRAL MACON
4	2101200	I-16 WBL	IN NORTH MACON
5	23500080	SR 230- US 129-341	E. HAWKINSVILLE-EB LANES
6	23500090	US 129 ALT- US 341	E. HAWKINSVILLE-WB LANES
7	17550090	HUDSON ROAD	8.2 MI S OF DUBLIN