




Structurally Deficient Bridges on the National Highway System Michigan - Congressional District 03



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 261 structurally deficient NHS bridges in Michigan, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	41141029000S230	I-196 WB	IN GRANDVILLE
2	41141061000B010	M-11	IN GRANDVILLE
3	41141029000B034	I-196 M-21 WB	IN GRAND RAPIDS
4	41141029000R063	I-196, M-21 EB	IN GRAND RAPIDS
5	41141029000S154	I-196, M-21 WB	IN GD RAPIDS
6	41141029000S164	I-196, M-21 WB	IN GRAND RAPIDS (LANE AV)
7	41141029000R064	I-196, M-21 WB	IN GRAND RAPIDS
8	41141131000S060	44TH ST	IN WYOMING
9	41141027000S123	I-196 M-21 EB	IN GRAND RAPIDS
10	41141024000R014	I-96 WB	20.0 MI W OF PORTLAND
11	41141024000R013	I-96 EB	20.0 MI W OF PORTLAND
12	82182123000S270	U-TURN N OF G RIV	IN DETROIT