

deficient NHS bridges in Ohio, 7 could not be geolocated because of insufficient data. Structurally deficient bridges am not necessarily unsafe; all public road bridges receive migular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed

Bridge Label	Structure ID	Bridge Description	Location Description	
1	5502586 IR-	75	1.87MI.N. OF JCT. SR-41	
2	5502764 IR-	75	3.57MI.S. OF JCT. USR-36	
3	5503337 IR-	75	1.05MI.N. OF JCT. USR-36	
4	5503361 IR-	75	1.05MI.N. OF JCT. USR-36	
5	5503272 IR-	75	.87MI.N. OF JCT. USR-36	
6	5700604 IR-	75 RAMP	.46MI.N. OF JCT. SR-48	
7	5703034 EB	USR-35	.54MI.W. OF JCT. SR-835	
8	5706211 EB	IR-70	JCT. SR-201	
9	5706181 WB	3 IR-70	JCT. SR-201	
10	5709660 SR	4	.09M S.OF SR4	