




Structurally Deficient Bridges on the National Highway System Arkansas - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 43 structurally deficient NHS bridges in Arkansas, 0 could not be geocoded because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	1253	US 79-SEC 13	1.8 MI W SH 86
2	3730	US 49-SEC 8	1.1 MI N JCT US 70 & 49
3	2409	US 79	0.25 MI S US 49
4	2112	US 63-03- LM 24.21	1 MI E SH 117
5	1871	US 67-19- LM 0.14	.8 M N OF US 62
6	483	US 67NB-18-LM 7.37	0.25 MI S US 62
7	1890	US 412-07- LM 4.60	3.07 MI W OF GREENE CO
8	496	US 67-19- LM 7.31	7.25 MI NE JCT US 62 & 67
9	1289	US 63-04- LM 8.63	.24 MI NW CRAIGHEAD CO
10	1891	US 412-07- LM 6.41	1.26 MI W OF GREENE CO
11	1909	US 412 -8 LM 1.34	1.34 MI E OF CACHE RIVER
12	0000000000B5203	US 63-07NB-LM 2.26	2.26 MI E JCT SH 1
13	0000000000A2644	US 63SB-09-LM 3.19	3.19 MI SE SH 75
14	5327	I 40-SEC 52	3 MI E OF JCT I-55 & I-40
15	0000000000A3288	I 55-12SB-LM 44.54	0.1 MI NO JCT SH 181