




Structurally Deficient Bridges on the National Highway System Wisconsin - Congressional District 06



Consult your state DOT for the most up-to-date status of bridges.



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 102 structurally deficient NHS bridges in Wisconsin, 8 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	B14005200000000	USH 151 NB	4.6M N JCT CTH DE
2	B28003100000000	IH 94 WB	2.9M W JCT CTH F TO N
3	B70002700000000	USH 41 SB	3.2M S JCT USH 45 TO N
4	B36001500000000	STH 32-STH 57	0.4M N JCT STH 67