
Ashtabula County Coastal Erosion Examples

James McDonald

Ohio Division of Geological Survey

















































Shore Structure Failure

