

Figure 1: Site Area in Augusta, Georgia




Figure 2: Peach Orchard Road Municipal Well Field




Figure 3: PCE Investigation Sampling Locations




Figure 4: POR Site Area Demographics




Figure 5: Remedial Investigation of Cretaceous Aquifer




Figure 6: Surface Aquifer PCE Plume




Figure 7: Remedial Investigation of Surficial Aquifer