


Figure 4  
El Rancho Soil Vapor Collection System



608 Clarks Lane

Rub-a-Dub  
Car Wash

611 Clarks Lane

De-frosting Clean  
Overburden To Reuse  
As Backfill

605 Clarks Lane  
Excavation Site

Figure 5

PID Excavation Monitoring



Action Alert Level 0 (Blue Sign)

Figure 6