




Structurally Deficient Bridges on the National Highway System Mississippi - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 32 structurally deficient NHS bridges in Mississippi, 4 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	310000605404430	US 278	7.0 MI W US 51
2	310000605404470	US 278	6.6 MI W US 51
3	210004504414540	US 45	0.4 MI N NOXUBEE CL
4	210004504415110	US 45	6.2 MI N NOXUBEE CL
5	210004504415370	US 45	8.8 MI N NOXUBEE CL
6	210004504415560	US 45	10.7 MI N NOXUBEE CL