

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT CHECK 13 (O'NEILL)

DECEMBER 2008

WATER QUALITY REPORT

RUN DATE: January 6, 2009

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1 | 909 | 616 | 711 |
| 2 | 874 | 621 | 692 |
| 3 | 909 | 630 | 685 |
| 4 | 953 | 647 | 749 |
| 5 | 949 | 639 | 722 |
| 6 | 976 | 638 | 708 |
| 7 | 913 | 662 | 717 |
| 8 | 906 | 666 | 739 |
| 9 | 899 | 694 | 749 |
| 10 | 863 | 685 | 727 |
| 11 | 833 | 674 | 728 |
| 12 | 846 | 647 | 738 |
| 13 | 906 | 689 | 789 |
| 14 | 963 | 679 | 788 |
| 15 | 761 | 679 | 706 |
| 16 | 962 | 687 | 801 |
| 17 | 751 | 679 | 705 |
| 18 | 925 | 682 | 769 |
| 19 | 899 | 669 | 736 |
| 20 | 939 | 685 | 763 |
| 21 | 910 | 675 | 738 |
| 22 | 982 | 688 | 777 |
| 23 | 926 | 706 | 785 |
| 24 | 881 | 713 | 762 |
| 25 | 870 | 710 | 762 |
| 26 | 863 | 723 | 796 |
| 27 | 874 | 696 | 779 |
| 28 | 867 | 710 | 775 |
| 29 | 932 | 693 | 813 |
| 30 | 966 | 695 | 814 |
| 31 | 960 | 722 | 823 |

Comments:

0 reading indicates that the station was out of service.