

PHOTOGRAPHIC LOG


County, State: Baldwin County, Alabama		Project: Spanish Fort Bluff Stabilization	Project No: PDM-PJ-04-AL-2003-006
Photo No. 1	Date: 1/05		
Direction Photo Taken: East			
Description: View from atop bluff showing berms put in place to control erosion			

Photo No. 2	Date: 1/05		
Direction Photo Taken: Southeast			
Description: View from atop bluff showing revetment built to stabilize bluff			

PHOTOGRAPHIC LOG

County, State:
Baldwin County, Alabama

Project:
Spanish Fort Bluff Stabilization

Project No:
PDM-PJ-04-AL-2003-006

Photo No.
3

Date:
1/05

Direction Photo Taken:

Northwest

Description:

View from atop bluff showing retaining wall and storm drain



Photo No.
4

Date:
1/05

Direction Photo Taken:

South

Description:

View from atop bluff looking down



PHOTOGRAPHIC LOG

County, State:
Baldwin County, Alabama

Project:
Spanish Fort Bluff Stabilization

Project No:
PDM-PJ-04-AL-2003-006

Photo No.
5

Date:
1/05

Direction Photo Taken:

Southeast

Description:

View from atop bluff at the northern end of project area



Photo No.
6

Date:
1/05

Direction Photo Taken:

Looking toward bluff

Description:

View of wetland/ditch at inundated area



PHOTOGRAPHIC LOG

County, State: Baldwin County, Alabama		Project: Spanish Fort Bluff Stabilization	Project No: PDM-PJ-04-AL-2003-006
Photo No. 7	Date: 1/05		
Direction Photo Taken: Southerly			
Description: View at base of bluff along Hwy 98			

Photo No. 8	Date: 1/05		
Direction Photo Taken: Looking toward bluff			
Description: View of hydrophytic vegetation in ditch at base of bluff			

PHOTOGRAPHIC LOG

County, State:
Baldwin County, Alabama

Project:
Spanish Fort Bluff Stabilization

Project No:
PDM-PJ-04-AL-2003-006

Photo No.
9

Date:
1/05

Direction Photo Taken:

n/a

Description:

View of siltation and test pit at base of bluff



PHOTOGRAPHIC LOG

County, State:
Baldwin County, Alabama

Project:
Spanish Fort Bluff Stabilization

Project No:
PDM-PJ-04-AL-2003-006

Photo No.
10

Date:
1/05

Direction Photo Taken:

Northwest

Description:

View from atop bluff showing Earthwork #1 and drainage grate

Note: This photo included only in FEMA's, Applicant's, and SHPO's copies of the EA.



Photo No.
11

Date:
1/05

Direction Photo Taken:

West

Description:

View of Earthwork #2

Note: This photo included only in FEMA's, Applicant's, and SHPO's copies of the EA

