

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

DELTA MENDOTA CANAL AT CHECK 20
WATER QUALITY REPORT

DECEMBER 2008

RUN DATE: January 6, 2009

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN | TDS |
|--------------|------|-----|---------------|-----|
| 1 | 611 | 607 | 609 | 392 |
| 2 | 612 | 610 | 611 | 394 |
| 3 | 613 | 611 | 612 | 394 |
| 4 | 613 | 612 | 613 | 395 |
| 5 | 616 | 613 | 614 | 395 |
| 6 | 623 | 615 | 619 | 399 |
| 7 | 624 | 622 | 623 | 401 |
| 8 | 640 | 623 | 630 | 405 |
| 9 | 635 | 632 | 634 | 408 |
| 10 | 638 | 635 | 636 | 409 |
| 11 | 639 | 636 | 638 | 410 |
| 12 | 641 | 638 | 640 | 412 |
| 13 | 642 | 640 | 641 | 412 |
| 14 | 643 | 641 | 642 | 413 |
| 15 | 643 | 641 | 642 | 413 |
| 16 | 644 | 642 | 643 | 413 |
| 17 | 878 | 643 | 760 | 486 |
| 18 | 876 | 853 | 862 | 549 |
| 19 | 865 | 851 | 860 | 547 |
| 20 | 862 | 842 | 848 | 540 |
| 21 | 881 | 865 | 877 | 558 |
| 22 | 892 | 878 | 886 | 564 |
| 23 | 884 | 873 | 876 | 557 |
| 24 | 905 | 878 | 893 | 568 |
| 25 | 922 | 907 | 917 | 583 |
| 26 | 915 | 893 | 903 | 574 |
| 27 | 909 | 891 | 897 | 570 |
| 28 | 941 | 912 | 927 | 589 |
| 29 | 944 | 939 | 942 | 598 |
| 30 | 951 | 945 | 948 | 602 |
| 31 | 952 | 948 | 950 | 603 |
| TOTAL | | | 23,393 | |

Comments:

0 reading indicates that the station was out of service.