

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
00-001	Sediment traps in Mortadad Canyon	8/16/2001	13	1.3	1.3	0	0	0	0	7	0	22.6
00-004	Container storage, 6th Street Warehouses (inactive)	1/7/1998	1	1.3	1.3	0	0	0	7	0	0	10.6
00-011(a)	Mortar impact area	6/25/1999	1	1.3	1.3	5	1.9	0	0	0	0	10.5
00-011(c)	Mortar impact area	8/13/2001	1	1.3	1.3	5	19	2.2	0	7	0	36.8
00-011(d)	Mortar impact area	8/16/2001	13	1.3	6.5	5	19	22	0	7	0	73.8
00-011(e)	Mortar impact area	6/25/1999	1	1.3	1.3	5	1.9	0	0	0	0	10.5
00-015	Firing range, Rendija Canyon	8/5/1997	13	6.5	13	0	0	0	0	7	0	39.5
00-017	Waste lines	12/7/1998	17	6.5	13	5	19	0	7	0	0	67.5
00-018(a)	Sludge-bed wastewater treatment plant, Pueblo Canyon	5/12/1997	4	1.3	6.5	5	19	0	0	7	0	42.8
00-018(b)	Sludge-bed wastewater treatment plant	4/5/2005	13	1.3	13	0	0	0	7	0	0	34.3
00-019	Wastewater treatment plant, central	5/21/1997	4	1.3	13	5	19	2.2	0	7	0	51.5
00-027	Storage area, DP Road	11/30/2001	1	1.3	1.3	5	1.9	0	7	0	0	17.5
00-030(a)	Septic system, DP Road	8/5/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
00-030(b)	Septic system 6th Street (inactive)	11/30/2001	1	1.3	1.3	5	1.9	0	7	0	0	17.5
00-030(d)	Septic system	4/5/2005	1	1.3	1.3	0	0	0	7	0	0	10.6
00-030(eN)	Septic system	4/5/2005	1	6.5	13	0	0	0	0	0	0	20.5
00-030(eS)	Septic system	4/5/2005	1	1.3	13	5	1.9	2.2	7	0	4	35.4
00-030(f)	Septic system	4/5/2005	1	1.3	1.3	0	0	0	7	0	0	10.6
00-030(g)	Septic system (near old Catholic Church parking lot)	10/16/1998	4	6.5	13	5	9.5	2.2	0	7	0	47.2
00-030(h)	Septic system (near new Catholic Church)	4/5/2005	1	1.3	1.3	0	0	0	7	0	4	14.6
00-030(i)	Septic system	6/25/1999	4	6.5	13	5	19	0	7	0	0	54.5
00-030(j)	Septic system	4/6/2005	1	6.5	13	0	0	0	7	0	4	31.5
00-030(l)	Septic system, 6th Street warehouses (inactive)	11/30/2001	1	1.3	13	0	0	0	0	7	0	22.3
00-030(m)	Septic system, 6th Street warehouses (inactive)	11/30/2001	1	1.3	1.3	5	1.9	0	0	7	0	17.5
00-030(n)	Septic system	8/5/1997	1	6.5	6.5	0	0	0	0	7	0	21
00-030(o)	Septic system	4/6/2005	1	1.3	1.3	0	0	0	7	0	0	10.6
00-030(p)	Septic system	6/25/1999	1	1.3	1.3	0	0	0	0	0	0	3.6
00-033(a)	Former UST, 6th Street Warehouses	12/3/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
00-033(b)	Outlet piping, 6th Street warehouse	11/30/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
00-039	Underground tanks	8/16/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
01-001(a)	Septic Tank 134	8/14/2002	1	6.5	13	0	0	0	7	0	0	27.5
01-001(b)	Septic Tank 135	12/7/1998	4	6.5	13	0	0	0	7	0	0	30.5
01-001(c)	Septic Tank 137	4/1/2000	4	6.5	13	5	19	22	7	0	0	76.5
01-001(d)	Septic Tank 138 (hillside)	8/14/2002	13	6.5	13	0	0	0	7	0	0	39.5
01-001(e)	Septic Tank 139	7/17/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
01-001(f)	Septic Tank 140 (hillside)	6/2/1997	4	13	6.5	5	19	2.2	0	7	0	56.7
01-001(g)	Septic Tank 141	8/20/2001	1	6.5	13	0	0	0	0	0	0	20.5
01-001(o)	Industrial or sanitary wastewater treatment	7/17/2001	1	1.3	6.5	0	0	0	7	0	0	15.8
01-001(s)	Septic system waste line	12/10/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
01-001(t)	Septic system	8/19/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
01-001(u)	Septic system waste line	7/17/2001	1	1.3	6.5	0	0	0	7	0	0	15.8
01-002(b)-00	Outfall TA-01 SWMU to be in TA-45	11/12/1999	17	6.5	13	5	19	0	7	0	4	71.5
01-003(a)	Landfill	9/17/2002	13	1.3	6.5	0	0	0	7	0	0	27.8
01-003(c)	Surface disposal site	12/7/1998	4	6.5	13	0	0	0	7	0	0	30.5
01-003(d)	Surface disposal site	8/12/1997	4	6.5	6.5	5	9.5	11	0	7	0	49.5
01-003(e)	Surface disposal site	8/12/1997	4	13	13	5	19	22	0	7	0	83

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
01-006(a)	Drainlines and outfall	8/14/1997	1	13	6.5	0	0	0	0	0	0	20.5
01-006(b)	Drainlines and outfall	4/1/2000	4	6.5	13	5	19	22	7	0	0	76.5
01-006(c)	Drainlines and outfall	4/1/2000	4	6.5	13	5	19	22	7	0	0	76.5
01-006(d)	Drainlines and outfall	4/1/2000	4	6.5	13	5	19	22	7	0	0	76.5
01-006(e)	Drainlines and outfall	8/14/1997	1	13	6.5	0	0	0	0	0	0	20.5
01-006(g)	Drainlines and outfall	8/14/1997	1	13	6.5	0	0	0	0	0	0	20.5
01-006(h)	Drainlines and outfall	8/14/1997	1	13	6.5	0	0	0	0	0	0	20.5
01-006(n)	Drainlines and outfall	4/1/2000	4	6.5	13	5	19	22	7	0	0	76.5
01-006(o)	Storm drain system	8/14/1997	1	13	6.5	0	0	0	0	0	0	20.5
01-007(a)	Soil contamination area	4/1/2000	1	1.3	1.3	0	0	0	0	0	0	3.6
01-007(b)	Soil contamination area	4/1/2000	1	1.3	1.3	0	0	0	0	0	0	3.6
01-007(c)	Soil contamination area	4/1/2000	1	1.3	1.3	0	0	0	0	0	0	3.6
01-007(d)	Soil contamination area	7/17/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
01-007(e)	Soil contamination area	7/17/2001	1	1.3	6.5	0	0	0	7	0	0	15.8
01-007(j)	Soil contamination area	8/17/2001	1	1.3	6.5	0	0	0	0	0	0	8.8
01-007(k)	Soil contamination area	12/10/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
01-007(l)	Soil contamination area	12/10/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
02-003(a)	Valve house and gaseous effluent line	8/6/1997	13	1.3	1.3	5	19	11	0	7	0	57.6
02-003(b)	Condensate trap	8/6/1997	13	6.5	13	0	0	0	0	7	0	39.5
02-003(c)	Delay system	4/11/2005	13	6.5	6.5	0	0	0	0	7	0	33
02-003(d)	Gaseous effluent line	8/6/1997	13	1.3	6.5	0	0	0	0	7	0	27.8
02-003(e)	Holding tank (near reactor water boiler)	8/6/1997	13	1.3	1.3	5	1.9	11	0	7	0	40.5
02-004(a)	Omega West Reactor facility	4/11/2005	13	6.5	1.3	0	0	0	0	7	0	27.8
02-004(b)	Reactor facility effluent storage tank	4/11/2005	13	6.5	6.5	0	0	0	0	7	0	33
02-004(c)	Reactor facility effluent storage tank	4/24/2001	13	13	6.5	0	0	0	7	0	0	39.5
02-004(d)	Reactor facility effluent storage tank	4/11/2005	13	6.5	6.5	0	0	0	0	7	0	33
02-004(e)	Reactor facility acid pit	4/11/2005	13	6.5	6.5	0	0	0	0	7	0	33
02-004(f)	Reactor facility equipment building	4/11/2005	13	6.5	6.5	0	0	0	0	7	0	33
02-004(g)	Aboveground tank	4/12/2005	13	6.5	1.3	0	0	0	0	7	0	27.8
02-005	Drift loss, cooling tower blowdown	8/6/1997	17	1.3	1.3	0	0	0	0	0	0	19.6
02-006(a)	French drain	9/3/1997	1	13	1.3	0	0	0	0	0	0	15.3
02-006(b)	Acid waste line	10/1/2000	13	6.5	1.3	5	19	0	0	7	0	51.8
02-006(c)	Drainline	8/6/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
02-006(d)	Drainline	8/6/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
02-006(e)	Sump	8/6/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
02-007	Septic system	10/1/2000	13	6.5	1.3	5	19	0	0	0	0	44.8
02-008(a)	Outfall	7/14/2000	17	6.5	1.3	5	19	0	7	0	0	55.8
02-008(c)	Outfall	8/6/1997	13	6.5	1.3	0	0	0	0	0	0	20.8
02-009(a)	Non-intentional release	10/24/2000	13	6.5	6.5	5	19	0	0	7	0	57
02-009(b)	Non-intentional release	10/1/1997	13	6.5	1.3	5	19	0	0	0	0	44.8
02-009(c)	Non-intentional release	10/1/2000	13	13	1.3	5	19	0	0	0	0	51.3
02-009(d)	Non-intentional release	8/6/1997	13	1.3	6.5	0	0	0	0	0	0	20.8
02-009(e)	Non-intentional release [Duplicate of 02-009(c)]	4/11/2005	13	6.5	1.3	0	0	0	0	7	0	27.8
02-010	Former building location	9/3/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
02-011(a)	Storm drain and outfall	9/3/1997	13	6.5	6.5	5	19	0	7	0	0	57
02-011(b)	Former drains and outfalls	9/3/1997	13	1.3	1.3	0	0	0	0	7	0	22.6
02-011(c)	Storm drain	9/3/1997	13	6.5	1.3	0	0	0	0	0	0	20.8
02-011(d)	Former NPDES-permitted outfall	9/3/1997	13	6.5	1.3	0	0	0	0	0	0	20.8

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
02-011(e)	Former NPDES-permitted outfall [duplicate of 02-008(a)]	8/6/1997	17	6.5	1.3	0	0	0	7	0	0	31.8
02-012	Former underground tanks	4/11/2005	13	6.5	1.3	0	0	0	0	7	0	27.8
03-001(k)	Less-than-90-day-storage area	6/11/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
03-002(c)	Storage area	6/26/2001	1	1.3	13	0	0	0	0	0	0	15.3
03-003(a)	Storage area	7/29/1997	1	1.3	1.3	5	9.5	0	7	0	0	25.1
03-003(b)	Storage area	7/24/1997	1	13	1.3	0	0	0	7	0	0	22.3
03-003(c)	Equipment storage area - PCB only site	6/11/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-003(m)	Storage area (capacitor banks) - PCB only site	7/29/1997	1	13	1.3	5	19	0	7	0	0	46.3
03-003(p)	Storage area	8/14/1998	1	6.5	6.5	0	0	0	7	0	0	21
03-004(c)	Storage area	12/16/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
03-004(d)	Storage area	12/16/1998	1	6.5	1.3	0	0	0	7	0	0	15.8
03-007	Firing site	12/3/1998	1	6.5	1.3	0	0	0	0	0	0	8.8
03-009(a)	Surface disposal (soil fill)	6/26/2001	1	1.3	13	5	19	22	0	0	0	61.3
03-009(d)	Surface disposal site	11/19/2002	1	1.3	13	0	0	0	7	0	0	22.3
03-009(i)	Surface disposal site	6/11/2001	1	1.3	6.5	5	1.9	11	0	0	0	26.7
03-009(j)	Surface disposal site	5/15/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-010(a)	Vacuum repair shop (former location)- systematic release site	11/19/2002	1	13	13	0	0	0	7	0	0	34
03-011	Systematic product release	7/29/1997	1	1.3	1.3	5	19	0	7	0	4	38.6
03-012(b)	Operational release and outfall	8/19/1997	17	6.5	6.5	5	19	0	0	7	4	65
03-013(a)	Operational release	8/19/1997	1	6.5	6.5	5	19	0	7	0	0	45
03-013(b)	Operational release	8/19/1997	1	6.5	6.5	5	19	0	7	0	0	45
03-014(a)	Wastewater treatment facility	6/8/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
03-014(b)	Wastewater treatment facility	6/8/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
03-014(b2)	Outfall	8/19/1997	4	1.3	13	5	19	0	0	0	4	46.3
03-014(c)	Wastewater treatment facility	6/8/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-014(c2)	Outfall	8/19/1997	4	13	13	5	19	11	7	0	0	72
03-014(d)	Wastewater treatment facility	6/11/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
03-014(e)	Wastewater treatment facility	6/8/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-014(f)	Wastewater treatment facility	6/8/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
03-014(g)	Wastewater treatment facility	6/8/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-014(h)	Wastewater treatment facility	6/8/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-014(i)	Wastewater treatment facility	6/8/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-014(j)	Wastewater treatment facility	6/8/2001	1	6.5	6.5	0	0	0	7	0	0	21
03-014(k)	Wastewater treatment facility	12/3/1998	1	6.5	1.3	0	0	0	0	0	0	8.8
03-014(l)	Wastewater treatment facility	12/3/1998	1	6.5	1.3	0	0	0	0	0	0	8.8
03-014(m)	Wastewater treatment facility	12/3/1998	1	6.5	1.3	0	0	0	0	0	0	8.8
03-014(n)	Wastewater treatment facility	12/3/1998	1	6.5	1.3	0	0	0	0	0	0	8.8
03-014(o)	Wastewater treatment facility	12/3/1998	4	6.5	1.3	0	0	0	0	0	0	11.8
03-014(p)	Wastewater treatment facility	6/11/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-014(q)	Wastewater treatment facility	6/11/2001	1	6.5	6.5	0	0	0	0	0	0	14
03-014(r)	Wastewater treatment facility	6/26/2001	1	6.5	13	0	0	0	0	0	0	20.5
03-014(s)	Wastewater treatment facility	6/8/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
03-014(t)	Wastewater treatment facility	6/11/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-014(u)	Wastewater treatment facility	6/26/2001	4	13	6.5	0	0	0	7	0	0	30.5
03-015	Outfall	8/19/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
03-021	Surface disposal site	7/29/1997	1	6.5	1.3	5	19	0	7	0	0	39.8
03-022	Sump	8/14/1998	1	6.5	1.3	0	0	0	0	0	0	8.8

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
03-025(b)	Sumps (two, inactive and active)	9/18/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-026(d)	Tank and/or associated equipment	9/11/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-028	Surface impoundment	6/8/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
03-029	Landfill	11/19/2002	1	6.5	1.3	0	0	0	0	0	0	8.8
03-033	Sump	5/15/2001	1	13	13	0	0	0	0	7	0	34
03-034(b)	Tank and/or associated equipment	6/27/2001	4	1.3	13	5	9.5	2.2	0	0	4	39
03-036(a)	Aboveground tanks	6/8/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
03-036(b)	Aboveground tanks	3/28/2005	1	13	1.3	0	0	0	7	0	0	22.3
03-036(c)	Aboveground tanks - duplicate of 03-043(f)	6/8/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
03-036(d)	Aboveground tanks - duplicate of 3-043(g)	6/8/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
03-037	Underground tank	9/11/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-038(a)	Acid tank	12/16/1998	1	6.5	1.3	0	0	0	0	0	0	8.8
03-038(b)	Acid tank	12/16/1998	1	6.5	6.5	5	9.5	0	0	7	0	35.5
03-042	Sump	8/19/1997	1	1.3	1.3	5	19	2.2	0	0	0	29.8
03-043(b)	Aboveground tank	6/18/1999	1	6.5	1.3	0	0	0	0	7	4	19.8
03-043(c)	Tank and/or associated equipment	6/18/1999	1	1.3	1.3	0	0	0	0	0	0	3.6
03-043(d)	Aboveground tank	6/18/1999	1	6.5	1.3	0	0	0	0	7	4	19.8
03-043(h)	Aboveground tank	6/18/1999	1	6.5	1.3	0	0	0	0	7	4	19.8
03-045(a)	Outfall (industrial or sanitary wastewater treatment)	4/29/1999	1	1.3	1.3	0	0	0	0	0	4	7.6
03-045(b)	Industrial or sanitary wastewater treatment	8/19/1997	17	6.5	6.5	5	19	0	0	7	4	65
03-045(c)	Outfall	4/29/1999	1	6.5	13	5	19	2.2	7	0	4	57.7
03-045(e)	Outfall (industrial or sanitary wastewater treatment)	8/19/1997	4	6.5	6.5	0	0	0	0	0	0	17
03-045(f)	Outfall from drain (industrial or sanitary wastewater treatment)	8/19/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
03-045(g)	Storm drain	1/21/1998	13	13	1.3	0	0	0	7	0	0	34.3
03-045(h)	Outfall (industrial or sanitary wastewater treatment)	8/19/1997	1	6.5	1.3	5	9.5	11	0	0	4	38.3
03-046	Above ground wastewater treatment tank	4/27/1999	1	1.3	1.3	0	0	0	0	0	0	3.6
03-047(d)	Storage area	9/2/1997	1	13	1.3	0	0	0	0	0	0	15.3
03-049(a)	Outfall	7/29/1997	1	1.3	6.5	5	19	0	0	0	4	36.8
03-049(b)	Operational release	4/24/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-049(e)	Outfall	8/28/1997	4	1.3	1.3	0	0	0	0	0	4	10.6
03-050(d)	Exhaust emissions, off-gas scrubber of HEPA filter system	6/18/1999	1	1.3	1.3	0	0	0	0	0	0	3.6
03-050(f)	Exhaust emissions, off-gas scrubber of HEPA filter system	6/18/1999	1	1.3	1.3	0	0	0	0	0	0	3.6
03-050(g)	Exhaust emissions, off-gas scrubber of HEPA filter system	6/18/1999	1	1.3	1.3	0	0	0	0	0	0	3.6
03-051(c)	Soil contamination (vacuum pump leaking)	8/14/1998	1	1.3	1.3	5	1.9	2.2	0	0	0	12.7
03-052(a)	Storm drainage	10/22/1997	1	1.3	1.3	5	19	0	7	0	0	34.6
03-052(b)	Storm drainage	7/29/1997	1	6.5	1.3	5	19	0	7	0	0	39.8
03-052(d)	Storm drainage (non-PCB transformers / capacitors)	9/2/1997	1	1.3	1.3	5	19	0	7	0	0	34.6
03-052(e)	Storm drainage	9/2/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
03-052(f)	Storm drainage	8/19/1997	1	6.5	6.5	5	19	0	7	0	0	45
03-054(a)	Outfall	9/9/1997	1	1.3	6.5	0	0	0	0	7	0	15.8
03-054(b)	Outfall	9/2/1997	1	6.5	1.3	5	19	22	7	0	4	65.8

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
03-054(c)	Outfall	9/2/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
03-054(d)	Outfall	9/9/1997	1	1.3	6.5	0	0	0	0	7	0	15.8
03-054(e)	Outfall	7/29/1997	17	13	13	5	19	11	0	7	4	89
03-055(a)	Outfall	9/9/1997	4	13	13	5	19	0	7	0	0	61
03-056(a)	Storage area	6/26/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
03-056(c)	Transformer storage area - PCB only site	9/16/1997	1	6.5	6.5	5	19	0	7	0	0	45
03-056(d)	Drum storage	6/8/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
03-056(h)	Transformer storage area - PCB only site	10/7/1997	1	13	1.3	0	0	0	0	0	0	15.3
03-056(k)	Container storage area	12/16/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
03-056(l)	Drum storage	6/11/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
03-059	Storage area - PCB only site	9/16/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
04-001	Firing site	4/23/2002	1	6.5	13	0	0	0	0	0	0	20.5
04-002	Surface disposal	4/23/2001	1	6.5	13	0	0	0	0	7	0	27.5
04-003(a)	Outfall	8/27/1997	1	13	1.3	5	19	11	7	0	0	57.3
04-003(b)	Outfall	4/23/2002	4	6.5	13	0	0	0	0	0	0	23.5
04-004	Soil contamination beneath buildings	8/27/1997	1	13	1.3	5	19	11	7	0	0	57.3
05-001(a)	Former firing site	4/23/2002	1	6.5	13	0	0	0	0	0	0	20.5
05-001(b)	Former firing site	4/23/2002	1	6.5	13	0	0	0	0	0	0	20.5
05-001(c)	Former firing site	8/27/1997	1	13	6.5	5	19	22	0	7	0	73.5
05-002	Canyonside disposal	8/27/1997	4	6.5	13	0	0	0	0	0	0	23.5
05-003	Former calibration chamber	4/23/2002	1	6.5	1.3	0	0	0	0	0	0	8.8
05-004	Former septic system	4/23/2002	1	6.5	6.5	0	0	0	0	7	0	21
05-005(a)	Former French drain	5/23/2002	4	6.5	13	0	0	0	0	0	0	23.5
05-005(b)	Outfall	4/23/2002	1	6.5	13	0	0	0	0	0	0	20.5
05-006(b)	Soil contamination beneath former buildings	4/23/2002	1	6.5	6.5	0	0	0	0	0	0	14
05-006(c)	Soil contamination beneath former buildings	4/23/2002	1	6.5	13	0	0	0	0	0	0	20.5
05-006(e)	Soil contamination beneath former buildings	5/1/2001	4	6.5	1.3	5	19	2.2	0	7	0	45
05-006(h)	Soil contamination beneath former buildings	4/23/2002	1	6.5	13	0	0	0	0	0	0	20.5
06-001(a)	Septic system	7/31/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
06-001(b)	Septic system	7/31/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
06-002	Septic system (TA-6-41) receives wastewater from PRSs 06-003 and C-06-020.	3/30/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
06-003(a)	Firing site (inactive)	12/11/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
06-003(c)	Firing site used for water recovery shots (inactive)	7/31/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
06-003(d)	Firing site (inactive)	6/20/2001	1	13	6.5	0	0	0	0	0	0	20.5
06-003(e)	Firing site (inactive)	6/20/2001	1	6.5	6.5	0	0	0	0	0	0	14
06-003(f)	Firing site (inactive)	6/20/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
06-003(h)	Firing site (inactive)	9/24/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
06-005	Firing site (pit) (inactive)	6/20/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
06-006	Storage area	6/20/2001	1	1.3	1.3	5	9.5	0	7	0	0	25.1
06-007(a)	Material disposal area (MDA F)	6/20/2001	1	6.5	1.3	0	0	0	0	7	0	15.8
06-007(b)	Landfill	6/20/2001	1	6.5	1.3	0	0	0	0	7	0	15.8
06-007(c)	Landfill	6/20/2001	1	6.5	1.3	0	0	0	0	7	0	15.8
06-007(d)	Landfill	6/20/2001	1	6.5	1.3	0	0	0	0	7	0	15.8
06-007(e)	Landfill	6/20/2001	1	6.5	1.3	0	0	0	0	7	0	15.8
06-007(f)	Surface disposal	9/24/2001	1	1.3	13	0	0	0	0	0	0	15.3
06-007(g)	Building and surface disposal	6/13/2002	1	1.3	6.5	0	0	0	0	7	4	19.8
06-008	Underground tank	6/3/1999	1	6.5	1.3	0	0	0	0	0	0	8.8

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
07-001(a)	Firing site (inactive)	8/13/2001	1	13	13	5	1.9	0	0	0	0	33.9
07-001(b)	Firing site (inactive)	8/13/2001	1	13	6.5	5	19	11	0	0	0	55.5
07-001(c)	Firing site (inactive)	8/13/2001	1	13	6.5	5	19	2.2	0	0	0	46.7
07-001(d)	Firing site (inactive)	8/7/2001	1	6.5	13	5	19	11	0	0	0	55.5
08-002	Firing site	8/14/2001	1	1.3	1.3	5	19	0	0	7	0	34.6
08-003(a)	Septic system	7/24/1997	1	13	1.3	0	0	0	0	7	0	22.3
08-004(a)	Floor drain	7/24/1997	1	13	1.3	0	0	0	0	7	0	22.3
08-004(b)	Drainline	12/15/1997	1	13	1.3	0	0	0	0	7	0	22.3
08-004(c)	Floor drain	12/15/1997	1	13	1.3	0	0	0	0	7	0	22.3
08-004(d)	Drain	12/11/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
08-005	Container storage area	8/14/2001	1	13	13	5	19	0	0	0	0	51
08-006(a)	Material disposal area (MDA Q)	8/14/2001	1	13	6.5	5	19	11	0	0	0	55.5
08-009(a)	Industrial or sanitary wastewater treatment	7/24/1997	1	1.3	1.3	5	1.9	0	0	7	0	17.5
08-009(c)	Storm drain and outfall	7/24/1997	1	6.5	13	0	0	0	7	0	0	27.5
08-009(d)	Industrial or sanitary wastewater treatment	8/14/2001	1	6.5	6.5	5	19	2.2	0	0	0	40.2
08-009(e)	Industrial or sanitary wastewater treatment	8/14/2001	1	1.3	1.3	5	1.9	0	7	0	0	17.5
08-009(f)	Outfall	7/24/1997	1	6.5	1.3	5	19	2.2	7	0	0	42
09-001(a)	Firing sites (inactive)	8/13/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
09-001(b)	Firing sites (inactive)	8/13/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
09-001(c)	Firing site (inactive)	8/13/2001	1	6.5	6.5	0	0	0	0	0	0	14
09-001(d)	Firing sites (inactive)	8/13/2001	1	1.3	6.5	0	0	0	0	0	0	8.8
09-002	Burn pit	3/30/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
09-003(a)	Settling tank	7/31/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
09-003(b)	Settling tank	7/31/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
09-003(d)	Settling tank	8/13/2001	1	1.3	6.5	0	0	0	0	0	0	8.8
09-003(e)	Settling tank	7/31/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
09-003(g)	Potentially contaminated soil	8/13/2001	1	1.3	6.5	0	0	0	0	0	0	8.8
09-003(h)	Potentially contaminated soil	8/13/2001	1	1.3	6.5	0	0	0	0	0	0	8.8
09-003(i)	Potentially contaminated soil	8/13/2001	1	13	1.3	0	0	0	0	7	0	22.3
09-004(a)	Settling tank	7/15/1999	1	1.3	1.3	0	0	0	0	0	0	3.6
09-004(b)	Settling tank	8/8/2001	1	1.3	1.3	0	0	0	7	0	4	14.6
09-004(c)	Settling tank	8/8/2001	1	6.5	13	0	0	0	7	0	0	27.5
09-004(d)	Settling tank	8/8/2001	1	1.3	13	0	0	0	7	0	4	26.3
09-004(e)	Settling tank	8/8/2001	1	6.5	1.3	0	0	0	7	0	0	15.8
09-004(f)	Settling tank	8/8/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
09-004(g)	Settling tank	8/8/2001	1	1.3	6.5	5	19	22	7	0	0	61.8
09-004(h)	Settling tank	8/8/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
09-004(i)	Settling tank	8/8/2001	1	1.3	6.5	0	0	0	7	0	0	15.8
09-004(j)	Settling tank	8/8/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
09-004(k)	Settling tank	8/8/2001	1	1.3	6.5	0	0	0	7	0	0	15.8
09-004(l)	Settling tank	8/8/2001	1	1.3	13	0	0	0	0	0	0	15.3
09-004(m)	Settling tank	8/8/2001	1	1.3	13	0	0	0	7	0	0	22.3
09-004(n)	Settling tank	7/15/1999	1	1.3	1.3	0	0	0	0	0	0	3.6
09-004(o)	Settling tank	6/14/2002	1	6.5	6.5	0	0	0	0	7	0	21
09-005(a)	Septic system	8/8/2001	1	13	13	5	19	0	0	0	0	51
09-005(d)	Septic system	6/3/1999	1	6.5	1.3	0	0	0	0	0	0	8.8
09-005(g)	Septic tank	8/8/2001	1	13	13	5	19	0	0	0	0	51
09-006	Septic tank	7/31/1997	13	1.3	1.3	0	0	0	0	7	0	22.6
09-008(b)	Surface impoundment	6/3/1999	1	6.5	1.3	5	9.5	0	0	7	0	30.3

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
09-009	Surface impoundment	6/14/2002	1	6.5	6.5	0	0	0	0	0	0	14
09-011(b)	Storage area	3/30/1998	1	1.3	1.3	0	0	0	7	0	0	10.6
09-011(c)	Storage area	3/30/1998	1	1.3	1.3	0	0	0	7	0	0	10.6
09-013	Material disposal area (MDA M)	6/14/2002	1	1.3	1.3	0	0	0	0	0	0	3.6
10-001(a)	Firing site (inactive)	7/23/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
10-001(b)	Firing site (inactive)	7/23/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
10-001(c)	Firing site (inactive)	7/23/1997	13	6.5	1.3	0	0	0	0	0	0	20.8
10-001(d)	Firing site (inactive)	7/23/1997	13	6.5	1.3	0	0	0	0	0	0	20.8
10-002(a)	Disposal pit	7/23/1997	13	6.5	6.5	0	0	0	0	0	0	26
10-002(b)	Disposal pit	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(a)	Disposal pit	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(b)	Disposal pit	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(c)	Disposal pit	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(d)	Disposal pit	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(e)	Disposal pit	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(f)	Disposal pit	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(g)	Manholes	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(h)	Manholes	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(i)	Septic tank	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(j)	Tank	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(k)	Tank	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(l)	Tank	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(m)	Waste line	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(n)	Leach field	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-003(o)	Leach field	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-004(a)	Septic tank	7/23/1997	13	6.5	6.5	0	0	0	0	0	0	26
10-004(b)	Septic system	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-005	Surface disposal	7/23/1997	13	1.3	6.5	0	0	0	0	7	0	27.8
10-007	Landfill	1/16/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
10-008	Tree Rimmed Firing Point, Bayo Canyon (inactive)	10/22/1997	17	6.5	1.3	0	0	0	0	7	0	31.8
10-009	Former Bayo Canyon landfill	11/29/1997	1	13	6.5	0	0	0	0	0	0	20.5
11-001(a)	Firing site (inactive)	3/18/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
11-001(b)	Firing site (inactive)	12/1/1998	1	1.3	6.5	5	1.9	0	7	0	0	22.7
11-001(c)	Firing site (inactive)	10/10/1997	4	13	13	5	19	2.2	0	0	0	56.2
11-002	Burn site	8/15/1997	1	13	1.3	0	0	0	0	0	0	15.3
11-003(b)	Air gun	8/15/1997	1	13	6.5	5	19	11	0	0	0	55.5
11-004(a)	Drop tower - firing site (active)	8/15/1997	1	6.5	6.5	5	19	11	0	7	0	56
11-004(b)	Drop tower - firing site (active)	8/15/1997	1	6.5	6.5	5	19	11	0	7	0	56
11-004(c)	Drop tower - firing site (active)	8/15/1997	1	6.5	6.5	5	19	11	0	7	0	56
11-004(d)	Drop tower - firing site (active)	8/15/1997	1	6.5	6.5	5	19	11	0	7	0	56
11-004(e)	Drop tower - firing site (active)	8/15/1997	1	6.5	6.5	5	19	11	0	7	0	56
11-004(f)	Drop tower - firing site (active)	8/15/1997	1	6.5	6.5	5	19	11	0	7	0	56
11-005(a)	Septic system	4/6/2001	4	6.5	13	0	0	0	0	0	0	23.5
11-005(b)	Septic system	8/15/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
11-005(c)	Outfall (inactive)	4/6/2001	4	6.5	6.5	5	19	11	7	0	0	59
11-006(a)	Sump	3/18/1998	1	1.3	1.3	0	0	0	7	0	0	10.6
11-006(b)	Tank and/or associated equipment	3/18/1998	4	6.5	6.5	5	19	0	7	0	4	52
11-006(c)	Tank and/or associated equipment	3/18/1998	4	1.3	6.5	5	19	22	7	0	4	68.8

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
11-006(d)	Tank and/or associated equipment	3/18/1998	4	6.5	6.5	5	19	22	7	0	4	74
11-009	Material disposal area (MDA S)	4/6/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
11-011(a)	Industrial or sanitary wastewater treatment	8/15/1997	1	1.3	13	0	0	0	0	0	4	19.3
11-011(b)	Industrial or sanitary wastewater treatment	8/15/1997	1	1.3	13	0	0	0	0	0	4	19.3
11-011(d)	Industrial or sanitary wastewater treatment	8/15/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
11-012(a)	Building	7/25/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
11-012(b)	Building	7/25/1997	1	13	1.3	0	0	0	0	0	0	15.3
11-012(c)	Building	10/10/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
11-012(d)	Building	8/15/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
12-001(a)	Firing site steel-lined chamber (inactive)	10/14/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
12-001(b)	Former firing site (inactive)	10/14/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
12-002	Open burning ground	8/21/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
12-004(a)	Radiation test facility	10/14/1997	1	6.5	1.3	5	19	2.2	0	0	0	35
12-004(b)	Pipe	10/14/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
13-001	Firing site at P-Site (inactive)	8/29/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
13-002	Landfill at P-Site	8/29/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
13-003(a)	Septic tank same as 16-005(i)	8/29/1997	1	1.3	6.5	0	0	0	0	0	0	8.8
13-003(b)	Septic system	8/29/1997	1	1.3	6.5	0	0	0	0	0	0	8.8
13-004	Disposal pit - existence not determined	8/21/2001	1	1.3	1.3	0	0	0	0	7	0	10.6
14-001(a)	Firing site (active)	10/6/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
14-001(b)	Firing site (active)	10/6/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
14-001(c)	Firing site (active)	10/6/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
14-001(d)	Firing site (active)	10/6/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
14-001(e)	Firing site (active)	10/6/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
14-001(f)	Firing site - bullet test facility (active)	10/6/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
14-001(g)	Firing site - Open Burn/Open Detonation (active)	2/7/1997	4	13	1.3	5	19	11	0	0	0	53.3
14-002(a)	Firing site (inactive)	10/1/2000	1	13	1.3	5	19	0	7	0	0	46.3
14-002(c)	Building	10/6/1997	1	13	1.3	5	9.5	0	0	7	0	36.8
14-002(d)	Firing site (inactive)	11/6/1997	1	13	1.3	5	9.5	11	0	0	0	40.8
14-002(e)	Firing site (inactive)	10/6/1997	1	13	1.3	5	9.5	11	0	7	0	47.8
14-003	Open burning ground	6/1/1998	1	6.5	1.3	0	0	0	0	0	0	8.8
14-004(a)	Storage area (active)	10/6/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
14-005	Incinerator (active)	10/6/1997	1	13	1.3	5	19	11	0	7	0	57.3
14-006	Tank and/or associated equipment	10/6/1997	1	1.3	1.3	5	9.5	22	7	0	0	47.1
14-007	Septic system	10/6/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
14-009	Surface disposal site	10/6/1997	1	13	6.5	5	19	2.2	0	7	0	53.7
14-010	Sump	10/6/1997	1	13	6.5	5	19	0	7	0	0	51.5
15-001	Surface disposal	8/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-002	Disposal pit and burn site	8/25/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-003	Firing site PHERMEX (active)	10/14/1997	1	13	1.3	0	0	0	0	0	0	15.3
15-004(a)	Firing Site C (inactive)	8/25/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
15-004(b)	Firing Site A (inactive)	8/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-004(c)	Firing Site B (inactive)	8/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-004(d)	Firing Site C (inactive)	8/25/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
15-004(f)	Machine firing site E-F non-RCRA (inactive) hazard but VCA uranium	8/25/1997	1	13	1.3	5	1.9	11	0	0	0	33.2
15-004(g)	Machine firing site (inactive)	1/28/1997	1	1.3	1.3	5	1.9	0	0	7	0	17.5
15-004(h)	Firing site H (inactive)	8/28/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
15-005(b)	Container storage area	8/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
15-005(c)	Container storage area (R-41)	11/4/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-006(a)	Firing site PHERMEX (active)	10/14/1997	1	13	1.3	0	0	0	0	0	0	15.3
15-006(b)	Firing Site Ector (active)	8/25/1997	1	13	1.3	0	0	0	0	0	0	15.3
15-006(c)	Firing site R-44 (inactive)	9/1/2000	17	13	1.3	5	19	2.2	0	7	0	64.5
15-006(d)	Firing site R-45 (inactive)	8/25/1997	1	6.5	1.3	5	9.5	0	0	0	0	23.3
15-007(a)	Material disposal area (MDA N) landfill	10/2/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-007(b)	Material disposal area (MDA Z) landfill	8/28/1997	4	13	6.5	5	9.5	2.2	0	0	0	40.2
15-007(c)	Shaft	8/25/1997	1	13	1.3	0	0	0	0	0	0	15.3
15-007(d)	Shaft	8/25/1997	1	13	1.3	0	0	0	0	0	0	15.3
15-008(a)	Surface disposal E/F Site	8/25/1997	17	6.5	6.5	5	19	11	0	7	0	72
15-008(b)	Surface disposal	8/25/1997	17	13	1.3	5	1.9	22	0	7	0	67.2
15-008(c)	Surface disposal	8/28/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
15-008(d)	Surface disposal	10/2/1997	1	13	13	5	19	11	0	7	0	69
15-008(f)	I-J Firing Site mounds at TA-36 (active)	11/4/1997	1	13	1.3	5	19	11	7	0	0	57.3
15-008(g)	Surface disposal	8/25/1997	1	6.5	1.3	5	9.5	0	0	0	0	23.3
15-009(a)	Septic system	10/2/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-009(b)	Septic system	8/26/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
15-009(c)	Septic tank	8/25/1997	17	6.5	13	5	19	0	0	7	4	71.5
15-009(e)	Septic system, E/F Site	8/25/1997	4	6.5	6.5	5	9.5	2.2	0	7	4	44.7
15-009(f)	Septic tank	10/2/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-009(g)	Septic tank (active)	10/14/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-009(h)	Septic tank	8/25/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
15-009(i)	Septic tank	8/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-009(k)	Septic tank	5/17/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
15-010(a)	Septic system	10/2/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
15-010(b)	Septic system	10/2/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-010(c)	Drainline	10/14/1997	1	6.5	13	5	19	0	7	0	0	51.5
15-011(a)	Sump	10/2/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-011(b)	Dry well	10/2/1997	4	13	13	5	19	22	7	0	4	87
15-011(c)	Sump	10/2/1997	4	13	13	5	19	22	7	0	4	87
15-014(a)	Industrial or sanitary wastewater treatment	10/2/1997	1	6.5	1.3	5	1.9	11	7	0	0	33.7
15-014(b)	Industrial or sanitary wastewater treatment	10/2/1997	1	6.5	1.3	5	1.9	11	7	0	0	33.7
15-014(d)	Industrial or sanitary wastewater treatment	10/14/1997	1	6.5	1.3	5	19	0	7	0	0	39.8
15-014(g)	Industrial or sanitary wastewater treatment	10/2/1997	4	13	1.3	5	19	2.2	7	0	4	55.5
15-014(h)	Outfall	10/2/1997	1	1.3	6.5	0	0	0	0	0	0	8.8
15-014(i)	Outfall	10/2/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-014(j)	Outfall	10/2/1997	1	13	1.3	5	19	11	7	0	4	61.3
15-014(k)	Outfall	10/2/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
15-014(l)	NPDES-permitted outfall (active)	10/14/1997	1	6.5	1.3	5	19	0	7	0	0	39.8
16-001(a)	Tank	3/23/2001	1	6.5	6.5	5	19	22	7	0	0	67
16-001(b)	Dry wells	3/23/2001	1	6.5	6.5	5	19	0	7	0	0	45
16-001(c)	Tank	3/23/2001	1	6.5	6.5	5	19	0	7	0	0	45
16-001(d)	Dry well	5/9/2001	1	1.3	1.3	5	19	11	7	0	0	45.6
16-001(e)	Dry well	4/6/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
16-003(a)	Sump	8/22/1997	1	6.5	13	5	19	0	7	0	4	55.5
16-003(b)	Sump	12/5/1997	1	6.5	1.3	5	1.9	11	7	0	0	33.7
16-003(c)	Sump 16-460	3/29/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
16-003(d)	Sump	4/6/2001	1	13	1.3	0	0	0	0	0	0	15.3
16-003(e)	Sump	4/6/2001	1	13	1.3	0	0	0	0	0	0	15.3

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
16-003(f)	Sump	9/14/2000	1	6.5	6.5	5	19	11	7	0	0	56
16-003(g)	Sump	2/24/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
16-003(h)	Sump 16-280	8/22/1997	1	1.3	1.3	5	9.5	0	7	0	4	29.1
16-003(i)	Sump 16-265	9/5/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-003(j)	Sump 16-267	9/5/1997	1	1.3	1.3	5	1.9	0	7	0	0	17.5
16-003(k)	Sumps / drainlines with 16-260	11/9/1998	1	1.3	1.3	5	19	0	7	0	4	38.6
16-003(l)	Sump 16-430	8/22/1997	1	1.3	1.3	5	9.5	0	7	0	4	29.1
16-003(m)	Sump	8/22/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-003(n)	Sump	8/29/1997	1	6.5	6.5	0	0	0	7	0	4	25
16-003(o)	Sump- fish ladder	8/29/1997	13	13	1.3	0	0	0	0	0	0	27.3
16-003(p)	Sump at P-Site	11/24/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-004(a)	Wastewater treatment facility	8/29/1997	1	13	13	0	0	0	0	0	4	31
16-004(b)	Wastewater treatment facility	8/29/1997	1	13	13	0	0	0	0	0	4	31
16-004(c)	Wastewater treatment facility	8/29/1997	1	13	13	0	0	0	0	0	4	31
16-004(d)	Wastewater treatment facility	8/29/1997	1	13	13	0	0	0	0	0	4	31
16-004(e)	Wastewater treatment facility	8/29/1997	1	13	13	0	0	0	0	0	4	31
16-004(f)	Wastewater treatment facility	8/29/1997	1	13	13	0	0	0	0	0	4	31
16-005(a)	Septic tank	3/29/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
16-005(c)	Septic tank	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-005(d)	Septic tank	8/8/1997	1	1.3	1.3	5	1.9	0	0	0	0	10.5
16-005(e)	Septic tank	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-005(g)	Burn site	4/26/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
16-005(h)	Septic tank	4/6/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
16-005(j)	Septic tank T-Site	4/26/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
16-005(k)	Septic tank	3/29/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
16-005(l)	Grease trap	3/29/2001	1	1.3	1.3	0	0	0	0	7	0	10.6
16-005(m)	Soil contamination area associated with former chemical pit T-Site	5/9/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
16-005(n)	Septic system	5/9/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
16-006(a)	Septic system	5/9/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
16-006(c)	Septic system	2/4/1998	4	6.5	6.5	5	9.5	11	7	0	0	49.5
16-006(d)	Septic system	8/22/1997	4	1.3	6.5	5	9.5	0	0	7	4	37.3
16-006(e)	Septic system 16-385	4/26/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
16-006(g)	Septic tank	8/21/2001	1	6.5	1.3	5	19	2.2	7	0	4	46
16-006(h)	Pump pit	3/23/2001	1	6.5	1.3	0	0	0	7	0	0	15.8
16-007(a)	Surface impoundment	10/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-008(a)	Surface impoundment (90s-Line pond)	4/26/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
16-009(a)	Burn site	10/20/1997	1	1.3	1.3	5	1.9	2.2	0	0	0	12.7
16-010(a)	Burn site	7/25/1997	1	13	6.5	5	1.9	11	0	0	0	38.4
16-010(b)	Flash pad; RCRA unit (undergoing closure)	9/15/1997	1	13	6.5	5	19	11	0	0	0	55.5
16-010(c)	Burn site 16-388 - RCRA Unit (active)	10/17/1997	1	6.5	6.5	5	19	2.2	0	7	0	47.2
16-010(d)	Burn site 16-399 - RCRA unit (active)	12/5/1997	1	13	1.3	5	19	11	0	0	0	50.3
16-010(e)	HE filter vessel; RCRA unit (active)	10/28/1997	1	6.5	6.5	0	0	0	0	0	0	14
16-010(f)	HE filter vessel; RCRA unit (active)	10/28/1997	1	6.5	6.5	0	0	0	0	0	0	14
16-010(h)	Burn site	9/15/1997	1	1.3	6.5	0	0	0	0	0	0	8.8
16-010(i)	Burn site	9/15/1997	1	6.5	6.5	0	0	0	0	0	0	14
16-010(j)	Burn site - RCRA Unit	9/15/1997	1	6.5	6.5	0	0	0	0	0	0	14
16-010(k)	Trough	9/15/1997	1	6.5	6.5	0	0	0	0	0	0	14
16-010(l)	Trough	9/15/1997	1	6.5	6.5	0	0	0	0	0	0	14

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
16-010(m)	Trough	9/15/1997	1	6.5	6.5	0	0	0	0	0	0	14
16-010(n)	Trough	9/15/1997	1	6.5	6.5	0	0	0	0	0	0	14
16-011	Incinerator	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-013	Container storage, V-Site	8/8/1997	1	1.3	6.5	5	1.9	0	7	0	0	22.7
16-015(a)	Men's locker room and laundry facility	10/10/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-015(b)	Steam-washing facility	10/10/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-015(c)	Operational facility	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-015(d)	Operational facility 16-51	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-016(a)	Landfill - buried metal site	6/9/1998	1	1.3	1.3	5	1.9	0	0	7	0	17.5
16-016(b)	Landfill	7/12/1999	1	1.3	1.3	0	0	0	0	7	0	10.6
16-016(c)	Landfill	1/12/1998	4	13	13	5	19	11	0	7	0	72
16-016(d)	Surface disposal site	8/21/2001	1	6.5	13	5	19	0	0	0	0	44.5
16-016(e)	Surface disposal site	4/6/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
16-016(f)	Landfill	7/17/1998	1	13	1.3	5	9.5	0	0	0	0	29.8
16-016(g)	Surface disposal site	4/6/2001	4	13	13	5	1.9	2.2	7	0	0	46.1
16-017	Former HE machining building, 16-92	2/24/1998	1	1.3	1.3	0	0	0	0	7	0	10.6
16-018	Material disposal area (MDA P); RCRA unit (currently undergoing RCRA closure)	10/17/1997	13	1.3	13	5	19	11	0	7	0	69.3
16-019	Material disposal area (MDA R)	4/1/1999	17	13	6.5	5	19	11	7	0	4	82.5
16-020	Silver recovery unit	9/5/1997	1	13	1.3	5	19	11	7	0	4	61.3
16-021(a)	Systematic release site	7/25/1997	1	13	6.5	0	0	0	0	7	0	27.5
16-021(b)	Systematic leak	7/17/1998	1	1.3	1.3	5	1.9	0	0	7	0	17.5
16-021(c)	Industrial or sanitary wastewater treatment at 16-260	9/5/1997	17	13	1.3	5	19	11	7	0	0	73.3
16-022(a)	Underground tank	7/17/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
16-022(b)	Underground tank	7/17/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
16-023(b)	Incinerator	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-024(a)	Magazine	8/29/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-024(b)	Magazine	9/22/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-024(c)	Magazine	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-024(d)	Magazine	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-024(e)	Operational facility 16-33	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-024(f)	Magazine	8/8/1997	1	1.3	1.3	5	1.9	2.2	0	7	0	19.7
16-024(g)	Magazine	8/8/1997	1	1.3	1.3	5	1.9	2.2	0	7	0	19.7
16-024(h)	Magazine	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-024(i)	Magazine	10/17/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-024(j)	Magazine	10/17/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
16-024(k)	Magazine	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-024(l)	Magazine	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-024(m)	Magazine	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-024(n)	Magazine	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-024(o)	Magazine	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-024(p)	Magazine	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-024(q)	Magazine	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-024(r)	Magazine	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-024(s)	Magazine	8/8/1997	1	13	1.3	0	0	0	0	0	0	15.3
16-024(t)	HE magazine	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-024(u)	Magazine	10/17/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-024(v)	Magazine	10/20/1997	1	1.3	1.3	0	0	0	0	0	0	3.6

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
16-025(a)	Abandoned radiography building, 16-39	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-025(a2)	Abandoned building and appurtenances, 16-50	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-025(b)	Abandoned radiography building, 16-40	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-025(b2)	Abandoned building and appurtenances	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-025(c2)	Abandoned building, 16-56	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-025(d)	Abandoned building and appurtenances	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-025(d2)	Abandoned building, 16-480	8/29/1997	1	1.3	1.3	5	1.9	0	7	0	0	17.5
16-025(e)	Abandoned building and appurtenances	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-025(e2)	Abandoned building, 16-106	7/17/1998	1	1.3	1.3	5	19	0	0	7	0	34.6
16-025(f)	Abandoned building and appurtenances, 16-32	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-025(f2)	Abandoned building, 16-107	7/17/1998	1	1.3	1.3	5	19	0	0	7	0	34.6
16-025(g)	Abandoned building and appurtenances	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-025(h)	Abandoned building and appurtenances	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-025(h2)	Abandoned building, 16-109	7/17/1998	1	1.3	1.3	5	19	0	0	7	0	34.6
16-025(i)	Abandoned building and appurtenances, 16-97	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-025(j)	Abandoned building and appurtenances	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-025(k)	Abandoned building and appurtenances	8/8/1997	1	1.3	1.3	5	1.9	0	0	0	0	10.5
16-025(l)	Abandoned building and appurtenances, 16-26	8/8/1997	1	1.3	1.3	5	1.9	0	0	0	0	10.5
16-025(m)	Abandoned building and appurtenances	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-025(n)	Abandoned building and appurtenances	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-025(o)	Abandoned building and appurtenances	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-025(p)	Abandoned building and appurtenances, 16-44	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-025(q)	Abandoned building and appurtenances, 16-45	10/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-025(r)	Abandoned building and appurtenances, 16-46	10/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-025(s)	Abandoned building and appurtenances, 16-48	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-025(t)	Abandoned building and appurtenances, 16-38	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-025(u)	Abandoned building and appurtenances, 16-42	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-025(v)	Abandoned building and appurtenances, 16-81	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-025(w)	Abandoned building, 16-81	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-025(x)	Abandoned building and appurtenances	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-025(y)	Abandoned building and appurtenances	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-025(z)	Abandoned building and appurtenances	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-026(a)	Outfall	6/9/1998	1	13	6.5	5	19	22	7	0	0	73.5
16-026(a2)	Outfall from 16-200	10/17/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
16-026(b)	Outfall from building 16-307 - PCB only site	7/25/1997	1	6.5	1.3	0	0	0	0	7	0	15.8
16-026(c)	Outfall from building, 16-305	7/25/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
16-026(c2)	Outfall, 16-462	7/25/1997	1	6.5	1.3	5	19	21	7	0	0	61.8
16-026(d)	Outfall from building 16-303	7/25/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
16-026(d2)	Outfall from 16-435	9/15/1997	1	6.5	1.3	0	0	0	0	7	0	15.8
16-026(e)	Outfall from building 16-301	7/25/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
16-026(e2)	Outfall from 16-415	9/15/1997	1	6.5	1.3	0	0	0	0	7	0	15.8
16-026(f)	Outfall	9/22/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-026(f2)	Outfall and associated drainline	9/15/1997	1	6.5	1.3	0	0	0	0	7	0	15.8
16-026(g)	Outfall	9/15/1997	1	6.5	1.3	0	0	0	0	7	0	15.8
16-026(g2)	Outfall from 16-285	9/15/1997	1	6.5	1.3	0	0	0	0	7	0	15.8
16-026(h)	Outfall from 16-281	8/22/1997	1	1.3	1.3	5	9.5	0	7	0	4	29.1
16-026(h2)	Outfall, 16-360	7/25/1997	4	13	13	5	19	0	7	0	0	61
16-026(i)	Outfall	2/24/1998	1	6.5	1.3	0	0	0	7	0	0	15.8
16-026(j)	Outfall, 16-226	9/5/1997	1	13	1.3	5	1.9	11	7	0	0	40.2

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
16-026(j2)	Outfall	10/28/1997	1	6.5	1.3	0	0	0	7	0	0	15.8
16-026(k)	Outfall and associated drainline	9/15/1997	1	6.5	1.3	0	0	0	0	7	0	15.8
16-026(k2)	Outfall, 16-260	9/5/1997	1	13	1.3	0	0	0	0	0	0	15.3
16-026(l)	Drainlines and outfall	9/5/1997	1	6.5	1.3	0	0	0	7	0	4	19.8
16-026(m)	Outfall	10/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-026(n)	Outfall	10/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-026(o)	Outfall	10/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-026(p)	Outfall	10/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-026(q)	Outfall, 16-27	8/8/1997	1	1.3	1.3	5	1.9	0	0	0	0	10.5
16-026(r)	Outfall, 16-180	10/20/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-026(s)	Outfall, 16-5	9/22/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-026(u)	Outfall, 16-195	10/17/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-026(v)	Outfall	7/25/1997	1	6.5	1.3	5	19	22	7	0	4	65.8
16-026(w)	Outfall, 16-45	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-026(x)	Outfall and associated drainline	9/15/1997	1	6.5	1.3	0	0	0	0	7	0	15.8
16-026(y)	Outfall	9/15/1997	1	6.5	1.3	0	0	0	0	7	0	15.8
16-026(z)	Outfall	9/22/1997	1	1.3	1.3	5	19	11	7	0	4	49.6
16-027(a)	Transformer - PCB only site	12/19/1997	1	13	1.3	0	0	0	0	0	0	15.3
16-027(c)	Transformer - PCB only site	7/17/1998	1	6.5	1.3	5	1.9	0	0	7	0	22.7
16-027(d)	Transformer - PCB only site	10/10/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-028(a)	South drainage channel	7/25/1997	1	13	6.5	5	19	0	7	0	0	51.5
16-028(b)	Industrial or sanitary wastewater treatment, 16-370	2/4/1998	17	6.5	6.5	5	19	22	7	0	0	83
16-028(d)	Industrial or sanitary wastewater treatment, 16-202	10/17/1997	1	1.3	1.3	5	1.9	0	7	0	4	21.5
16-028(e)	Industrial or sanitary wastewater treatment	4/6/2001	1	6.5	6.5	5	19	2.2	7	0	0	47.2
16-029(a)	Sump from 300s-Line	7/25/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
16-029(a2)	Sump, 16-55	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-029(b)	Sump from 300s-Line	7/25/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
16-029(b2)	Sump, 16-53	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-029(c)	Sump from 300s-Line	7/25/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
16-029(c2)	Sump	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-029(d)	Sump from 300s-Line	7/25/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
16-029(d2)	Sump, 16-50	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-029(e)	Sump, 16-360	7/25/1997	1	13	1.3	0	0	0	0	0	0	15.3
16-029(e2)	Sump, 16-52	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-029(f)	Sump from building 16-345	8/29/1997	1	6.5	1.3	0	0	0	7	0	0	15.8
16-029(f2)	Outfall, 16-24	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-029(g)	Sump, 16-450	5/15/1997	1	1.3	1.3	5	1.9	0	0	7	4	21.5
16-029(g2)	Pump pit	4/26/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
16-029(h)	Sump at P-Site	8/29/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-029(h2)	Drainline and outfall	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-029(i)	Outfall	9/22/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-029(j)	Outfall, 16-260	9/5/1997	1	13	1.3	0	0	0	0	0	0	15.3
16-029(k)	Sump	10/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-029(l)	Sump	10/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-029(m)	Sump, 16-95	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-029(n)	Sump, 16-96	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-029(o)	Sump, 16-97	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
16-029(p)	Sump, 16-98	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-029(q)	16-99 and associated structures	10/28/1997	1	1.3	1.3	5	1.9	0	0	0	0	10.5
16-029(r)	Outfall, 16-25	9/22/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-029(s)	Sump	3/23/2001	1	13	1.3	5	19	2.2	0	0	4	45.5
16-029(t)	Sump	3/23/2001	1	13	1.3	5	19	2.2	0	0	0	41.5
16-029(u)	Sump	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
16-029(v)	Sump, 16-49	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-029(w)	Sump	3/23/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
16-029(x)	Sump	2/24/1998	1	1.3	1.3	0	0	0	0	7	0	10.6
16-029(y)	Sump, 16-38	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-029(z)	Sump, 16-42	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-030(a)	Outfall from 16-344, chemical storage building	8/29/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-030(b)	Outfall and associated drainline	10/10/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-030(d)	Outfall, 16-280	10/10/1997	1	6.5	1.3	5	19	0	0	0	0	32.8
16-030(f)	Outfall and associated drainline	9/15/1997	1	6.5	1.3	0	0	0	0	7	0	15.8
16-030(g)	Outfall	7/25/1997	1	6.5	6.5	5	19	22	7	0	4	71
16-030(h)	Outfall, 16-430	10/28/1997	1	1.3	1.3	5	9.5	0	7	0	4	29.1
16-031(a)	Industrial or sanitary wastewater treatment, 16-372	2/4/1998	1	6.5	6.5	5	1.9	0	0	7	0	27.9
16-031(b)	Industrial or sanitary wastewater treatment, 16-262	11/24/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-031(c)	Industrial or sanitary wastewater treatment, 16-515	3/23/2001	1	6.5	1.3	0	0	0	7	0	0	15.8
16-031(d)	Cooling tower, 16-28	8/8/1997	1	1.3	1.3	5	1.9	0	0	0	0	10.5
16-031(e)	Outfall, industrial or sanitary wastewater treatment	5/9/2001	1	1.3	6.5	0	0	0	0	0	0	8.8
16-031(f)	Outfall, industrial or sanitary wastewater treatment	5/9/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
16-031(h)	Industrial or sanitary wastewater treatment at P-Site	5/9/2001	1	6.5	13	0	0	0	0	0	0	20.5
16-032(a)	Sump, 16-45	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-032(c)	Sump, 16-26	8/8/1997	1	1.3	1.3	5	1.9	0	0	0	0	10.5
16-033(a)	Underground tank	8/14/1998	1	6.5	1.3	5	1.9	2.2	0	0	0	17.9
16-033(b)	Underground tank	7/17/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
16-033(f)	Underground tank	7/17/1998	1	1.3	1.3	5	1.9	0	0	7	0	17.5
16-033(g)	Underground tank	10/10/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-033(h)	Underground tank	10/10/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-033(i)	Underground tank	7/17/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
16-033(j)	Underground tank	7/17/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
16-034(a)	Soil contamination area, 16-24	8/8/1997	1	1.3	1.3	5	1.9	0	0	0	0	10.5
16-034(b)	Soil contamination area, 16-490	8/8/1997	1	1.3	1.3	5	1.9	2.2	0	7	0	19.7
16-034(c)	Soil contamination area	8/8/1997	1	1.3	1.3	5	1.9	2.2	0	7	0	19.7
16-034(d)	Soil contamination area	8/8/1997	1	1.3	1.3	5	1.9	2.2	0	7	0	19.7
16-034(e)	Soil contamination area	8/8/1997	1	1.3	1.3	5	1.9	2.2	0	7	0	19.7
16-034(f)	Soil contamination area	8/8/1997	1	1.3	1.3	5	1.9	2.2	0	7	0	19.7
16-034(h)	Soil contamination area, 16-137	10/20/1997	1	1.3	1.3	5	1.9	2.2	0	0	0	12.7
16-034(i)	Soil contamination area	2/24/1998	1	1.3	1.3	0	0	0	0	7	0	10.6
16-034(j)	Soil contamination area	10/20/1997	1	1.3	1.3	5	1.9	2.2	0	0	0	12.7
16-034(k)	Soil contamination area	2/24/1998	1	1.3	1.3	0	0	0	0	7	0	10.6

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
16-034(l)	Soil contamination area	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-034(m)	Soil contamination area	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-034(n)	Soil contamination area	8/8/1997	1	13	1.3	0	0	0	7	0	0	22.3
16-034(o)	Soil contamination area, 16-49	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-034(p)	Soil contamination area	8/8/1997	1	13	1.3	0	0	0	0	0	0	15.3
16-035	Soil contamination area at P-Site	10/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
16-036	Soil contamination area at P-Site	8/29/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
18-001(a)	Lagoon	8/14/2001	13	1.3	1.3	0	0	0	0	0	0	15.6
18-001(b)	Sewer lines	8/14/2001	13	1.3	1.3	0	0	0	0	0	0	15.6
18-001(c)	Sump	8/13/2001	13	1.3	1.3	0	0	0	7	0	0	22.6
18-002(a)	Firing site (inactive)	8/13/2001	13	1.3	1.3	0	0	0	0	0	0	15.6
18-002(b)	Firing site (inactive)	8/13/2001	13	1.3	1.3	0	0	0	7	0	0	22.6
18-003(a)	Settling pit	8/5/1997	13	13	1.3	0	0	0	0	0	0	27.3
18-003(b)	Septic system	8/5/1997	13	13	1.3	0	0	0	0	0	0	27.3
18-003(c)	Septic system	4/3/1998	17	13	1.3	5	19	0	7	0	0	62.3
18-003(d)	Septic system	8/4/1997	13	6.5	1.3	0	0	0	0	0	0	20.8
18-003(e)	Septic system	8/4/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
18-003(f)	Septic system	8/13/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
18-003(g)	Septic system	8/13/2001	13	1.3	6.5	0	0	0	7	0	0	27.8
18-003(h)	Septic system	8/13/2001	13	1.3	6.5	5	1.9	0	7	0	0	34.7
18-004(a)	Waste lines containment	8/13/2001	13	1.3	1.3	0	0	0	7	0	4	26.6
18-004(b)	Pit	8/13/2001	13	1.3	1.3	0	0	0	7	0	4	26.6
18-005(a)	Storage area	8/13/2001	13	1.3	1.3	0	0	0	0	7	0	22.6
18-006	Storage pipe	6/18/1998	13	13	1.3	0	0	0	0	0	0	27.3
18-010(b)	Outfall	8/4/1997	13	1.3	1.3	0	0	0	7	0	0	22.6
18-010(c)	Outfall	8/4/1997	13	1.3	1.3	0	0	0	7	0	0	22.6
18-010(d)	Outfall	8/4/1997	13	1.3	6.5	5	1.9	10.5	7	0	0	46.2
18-010(e)	Outfall	8/4/1997	13	1.3	1.3	5	1.9	0	7	0	0	29.5
18-010(f)	Outfall	4/3/1998	17	13	1.3	5	19	0	7	0	0	62.3
18-012(a)	Outfall	8/4/1997	13	6.5	6.5	5	19	2.2	7	0	0	59.2
18-012(b)	Outfall	8/5/1997	13	1.3	1.3	5	19	0	7	0	0	46.6
18-012(c)	Sump and drainlines	8/5/1997	13	13	1.3	0	0	0	0	0	0	27.3
19-001	Septic system	9/16/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
19-002	Surface disposal site	9/12/2001	1	6.5	13	5	1.9	2.2	0	7	0	36.6
19-003	Septic tank	9/16/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
20-001(a)	Landfill	8/8/2001	13	13	6.5	0	0	0	0	0	0	32.5
20-001(b)	Landfill	8/8/2001	13	13	6.5	0	0	0	0	7	0	39.5
20-001(c)	Landfill	8/8/2001	13	6.5	6.5	0	0	0	0	0	0	26
20-002(a)	Firing site	8/8/2001	13	6.5	13	5	1.9	2.2	0	7	0	48.6
20-002(b)	Firing site	8/8/2001	13	1.3	6.5	0	0	0	0	0	0	20.8
20-002(c)	Firing site	8/8/2001	13	6.5	1.3	5	19	22	7	0	0	73.8
20-002(d)	Firing site	7/29/1998	13	6.5	1.3	0	0	0	0	0	0	20.8
20-003(a)	Control building at a firing site	8/8/2001	13	1.3	6.5	0	0	0	0	0	0	20.8
20-003(b)	Firing site	7/29/1998	13	6.5	1.3	0	0	0	0	7	0	27.8
20-003(c)	Firing site	7/31/1998	13	6.5	13	5	1.9	11	0	7	0	57.4
20-004	Septic system	7/29/1998	13	1.3	6.5	0	0	0	0	0	0	20.8
20-005	Septic tank	7/29/1998	13	6.5	1.3	0	0	0	0	7	0	27.8
21-002(a)	Container storage areas located throughout TA-21	7/25/2001	0	0	0	0	0	0	0	0	0	0

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
21-002(b)	Container storage	12/18/2003	1	6.5	6.5	0	0	0	7	0	0	21
21-003	Container storage - RCRA Unit	2/10/1998	4	1.3	6.5	5	9.5	0	7	0	0	33.3
21-004(b)	Tank and/or associated equipment	7/16/2001	1	1.3	6.5	0	0	0	0	0	0	8.8
21-004(c)	Tank and/or associated equipment	7/16/2001	1	1.3	6.5	0	0	0	0	0	0	8.8
21-006(a)	Disposal pit, building 21-2	7/16/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
21-006(b)	Disposal pit	9/23/1997	4	13	6.5	0	0	0	0	7	0	30.5
21-006(c)	Disposal pit, building 21-3	7/16/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
21-006(d)	Disposal pit, building 21-3	7/16/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
21-006(e)	Surface disposal site, building 21-4	7/16/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
21-006(f)	Disposal pit, building 21-4	4/11/2005	1	13	6.5	0	0	0	7	0	4	31.5
21-007	Incinerators	7/17/2001	1	1.3	6.5	5	9.5	0	7	0	0	30.3
21-009	Waste treatment laboratory	7/12/2004	1	6.5	1.3	0	0	0	0	0	0	8.8
21-010(a)	Waste treatment facility	7/17/2001	1	1.3	6.5	5	9.5	0	7	0	0	30.3
21-010(b)	Waste treatment facility	7/17/2001	1	1.3	6.5	5	9.5	0	7	0	0	30.3
21-010(c)	Waste treatment facility	7/17/2001	1	1.3	6.5	5	9.5	0	7	0	0	30.3
21-010(d)	Waste treatment facility	7/17/2001	1	1.3	6.5	5	9.5	0	7	0	0	30.3
21-010(e)	Waste treatment facility	7/17/2001	1	1.3	6.5	5	9.5	0	7	0	0	30.3
21-010(f)	Waste treatment facility	7/17/2001	1	1.3	6.5	5	9.5	0	7	0	0	30.3
21-010(g)	Waste treatment facility	7/17/2001	1	1.3	6.5	5	9.5	0	7	0	0	30.3
21-010(h)	Waste treatment facility	7/17/2001	1	1.3	6.5	5	9.5	0	7	0	0	30.3
21-011(a)	Waste treatment facility	7/17/2001	1	1.3	6.5	5	9.5	0	7	0	0	30.3
21-011(b)	Sump	7/16/2001	1	6.5	6.5	0	0	0	7	0	0	21
21-011(c)	Tank and sump	5/22/1997	13	1.3	6.5	5	19	2.2	7	0	0	54
21-011(d)	Aboveground tank	6/28/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
21-011(e)	Aboveground tank	6/28/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
21-011(f)	Aboveground tank	6/28/2001	1	1.3	13	0	0	0	0	0	0	15.3
21-011(g)	Aboveground tank	6/28/2001	1	1.3	13	0	0	0	0	0	0	15.3
21-011(i)	Aboveground tank	6/28/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
21-011(j)	Aboveground tank	6/28/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
21-011(k)	Outfall	5/22/1997	13	6.5	6.5	5	19	2.2	0	0	0	72
21-012(b)	Dry well	7/26/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
21-013(a)	Surface disposal site	7/16/2001	1	6.5	13	0	0	0	0	0	0	20.5
21-013(b)	Surface disposal site	2/10/1998	4	6.5	13	5	9.5	22	0	7	0	67
21-013(c)	Surface disposal site	6/25/1999	1	6.5	1.3	5	1.9	0	0	0	0	15.7
21-013(d)	Surface disposal site (cold dump)	6/25/1999	1	6.5	1.3	5	1.9	2.2	0	7	0	24.9
21-013(e)	Surface disposal site	6/25/1999	1	6.5	1.3	5	1.9	2.2	0	7	0	24.9
21-013(f)	Surface disposal site	2/10/1998	1	1.3	6.5	0	0	0	7	0	0	15.8
21-013(g)	Surface disposal site	2/10/1998	4	6.5	13	5	9.5	22	0	7	0	67
21-014	Material disposal area (MDA A)	7/17/2001	1	1.3	6.5	0	0	0	7	0	0	15.8
21-015	Material disposal area (MDA B)	9/23/1997	1	6.5	1.3	5	1.9	2.2	0	0	0	17.9
21-016(a)	Material disposal area (MDA T)	5/22/1997	13	1.3	6.5	5	19	2.2	7	0	0	54
21-016(b)	Material disposal area (MDA T)	5/22/1997	13	1.3	6.5	5	19	2.2	7	0	0	54
21-016(c)	Material disposal area (MDA T)	5/22/1997	13	1.3	6.5	5	19	2.2	7	0	0	54
21-017(a)	Material disposal area (MDA U)	6/18/1998	1	1.3	6.5	0	0	0	0	0	0	8.8
21-017(b)	Material disposal area (MDA U)	6/18/1998	1	1.3	6.5	0	0	0	0	0	0	8.8
21-017(c)	Material disposal area (MDA U)	6/18/1998	1	1.3	6.5	0	0	0	0	0	0	8.8
21-018(a)	Material disposal area (MDA V)	5/18/1999	1	1.3	1.3	5	9.5	0	0	0	0	18.1
21-018(b)	Material disposal area (MDA V) laundry facility	9/30/1997	1	6.5	1.3	0	0	0	0	7	0	15.8
21-021	Systematic release (site -wide)	7/25/2001	1	1.3	1.3	0	0	0	0	0	0	3.6

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
21-022(a)	Waste lines	7/19/2001	1	6.5	1.3	0	0	0	7	0	0	15.8
21-022(b)	Waste lines, building 21-2	6/28/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
21-022(c)	Waste lines, building 21-3	6/28/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
21-022(d)	Waste lines, building 21-4	6/28/2001	1	6.5	6.5	0	0	0	7	0	0	21
21-022(e)	Waste lines, building 21-5	6/28/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
21-022(f)	Sump and drainlines	7/24/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
21-022(g)	Waste lines, building 21-150	7/17/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
21-022(h)	Waste lines	9/23/1997	4	6.5	13	0	0	0	0	0	4	27.5
21-022(i)	Tank and/or associated equipment	7/19/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
21-022(j)	Tank and/or associated equipment	6/25/1999	1	1.3	1.3	0	0	0	0	0	0	3.6
21-023(a)	Septic system, building 21-3	6/28/2001	1	6.5	1.3	0	0	0	7	0	0	15.8
21-023(b)	Septic system, building 21-3	6/28/2001	1	6.5	1.3	0	0	0	7	0	0	15.8
21-023(c)	Septic system	4/12/1999	1	6.5	6.5	5	9.5	0	0	7	0	35.5
21-023(d)	Septic system, building 21-3	6/28/2001	1	6.5	13	0	0	0	7	0	0	27.5
21-024(a)	Septic system	9/20/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
21-024(b)	Septic system	11/25/1997	1	1.3	6.5	0	0	0	0	7	0	15.8
21-024(c)	Septic system	9/30/1997	1	6.5	6.5	0	0	0	0	0	0	14
21-024(d)	Septic system	5/22/1997	4	6.5	6.5	0	0	0	7	0	0	24
21-024(e)	Septic system	2/10/1998	4	6.5	13	5	9.5	11	7	0	0	56
21-024(f)	Septic system	5/18/1999	4	6.5	6.5	5	1.9	0	0	7	0	30.9
21-024(g)	Septic system	9/30/1997	4	6.5	6.5	0	0	0	0	0	0	17
21-024(h)	Septic system	5/22/1997	17	6.5	6.5	5	19	0	0	0	0	54
21-024(i)	Septic system	2/23/2003	4	6.5	13	0	0	0	0	7	4	34.5
21-024(j)	Septic system	9/30/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
21-024(k)	Septic system	9/30/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
21-024(l)	Industrial or sanitary wastewater treatment	9/30/1997	1	1.3	6.5	0	0	0	0	0	0	8.8
21-024(n)	Drainline	9/30/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
21-024(o)	Drainline	11/25/1997	1	1.3	1.3	0	0	0	0	7	0	10.6
21-026(a)	Industrial or sanitary wastewater treatment	7/16/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
21-026(b)	Surface disposal site (sand filter / sludge drying beds)	7/16/2001	1	6.5	1.3	0	0	0	7	0	0	15.8
21-026(d)	Outfall	9/23/1997	13	6.5	13	0	0	0	0	7	0	39.5
21-027(a)	Industrial or sanitary wastewater treatment	5/22/1997	4	6.5	6.5	5	19	0	7	0	4	52
21-027(c)	Industrial or sanitary wastewater treatment	11/25/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
21-027(d)	Drainline	4/12/1999	4	6.5	13	5	9.5	0	0	7	0	45
21-028(c)	Container storage building 21-3	4/11/2005	1	13	1.3	0	0	0	7	0	0	22.3
21-029	Soil contamination area	8/24/2001	1	1.3	1.3	5	19	22	7	0	0	56.6
22-010(a)	Septic system	7/31/1997	4	1.3	6.5	0	0	0	0	0	0	11.8
22-010(b)	Septic system	7/31/1997	1	1.3	1.3	5	19	0	0	0	0	27.6
22-011	Disposal pit	8/21/2001	1	13	1.3	0	0	0	0	0	0	15.3
22-012	Decontamination facility	2/1/1999	1	1.3	1.3	5	1.9	0	7	0	0	17.5
22-014(a)	Industrial or sanitary wastewater treatment	7/31/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
22-014(b)	Sump	7/31/1997	4	6.5	6.5	5	19	11	0	0	4	56
22-015(a)	Drainlines and dry wells	7/31/1997	1	1.3	1.3	5	19	0	0	7	0	34.6
22-015(b)	Sump and outfall	7/31/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
22-015(c)	Outfall	10/10/1999	4	6.5	13	5	19	0	0	0	4	51.5
22-015(d)	Drainline and outfall	7/31/1997	1	1.3	6.5	5	19	0	0	7	0	39.8
22-015(e)	Industrial or sanitary wastewater treatment	7/31/1997	1	1.3	1.3	5	1.9	0	7	0	0	17.5
22-016	Septic system	7/31/1997	1	1.3	1.3	5	19	0	0	0	0	27.6

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
26-001	Surface disposal site	8/14/2001	4	13	13	5	19	11	0	0	0	65
26-002(a)	Former acid sump system	8/14/2001	1	13	13	0	0	0	0	0	0	27
26-002(b)	Former drainage system	8/14/2001	1	13	13	0	0	0	0	0	0	27
26-003	Septic tank	8/14/2001	1	6.5	13	0	0	0	0	0	0	20.5
27-002	Firing sites (inactive)	8/14/2001	13	1.3	1.3	0	0	0	0	0	0	15.6
27-003	Bazooka impact area	8/14/2001	13	1.3	13	0	0	0	0	7	0	34.3
31-001	Septic system	9/16/1997	4	1.3	6.5	0	0	0	0	7	0	18.8
32-001	Incinerator (former location)	11/25/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
32-002(a)	Septic tank (former location); drainlines	10/7/1997	1	6.5	1.3	0	0	0	7	0	0	15.8
32-002(b)	Septic system	10/7/1997	1	6.5	1.3	0	0	0	7	0	0	15.8
32-003	Transformer site (former location)	10/7/1997	1	6.5	1.3	5	1.9	11	7	0	0	33.7
32-004	Drainline and outfall	7/24/1999	1	6.5	13	5	9.5	0	7	0	0	42
33-001(a)	Material disposal area (MDA E)	1/10/2000	1	6.5	1.3	5	19	2.2	0	0	0	35
33-001(b)	Material disposal area (MDA E)	1/10/2000	1	6.5	1.3	5	19	2.2	0	0	0	35
33-001(c)	Material disposal area (MDA E)	1/10/2000	1	6.5	1.3	5	19	2.2	0	0	0	35
33-001(d)	Material disposal area (MDA E)	1/10/2000	1	6.5	1.3	5	19	2.2	0	0	0	35
33-001(e)	Material disposal area (MDA E)	1/10/2000	1	6.5	1.3	5	19	2.2	0	0	0	35
33-002(a)	Material disposal area (MDA K) - septic tank	2/2/1999	1	6.5	1.3	5	1.9	0	0	0	0	15.7
33-002(b)	Material disposal area (MDA K) - sump	2/2/1999	1	1.3	1.3	0	0	0	0	0	0	3.6
33-002(c)	Material disposal area (MDA K) - sump	2/2/1999	1	13	1.3	0	0	0	0	0	0	15.3
33-002(d)	Material disposal area (MDA K) - drainline and outfall	2/2/1997	1	13	1.3	5	1.9	0	0	0	4	26.2
33-002(e)	Material disposal area (MDA K) - drainline and outfall	2/2/1999	1	6.5	1.3	5	1.9	0	7	0	0	22.7
33-003(a)	Material disposal area (MDA D)	9/24/2001	1	6.5	13	0	0	0	0	0	0	20.5
33-003(b)	Material disposal area (MDA D)	9/24/2001	1	6.5	1.3	0	0	0	0	0	0	8.8
33-004(a)	Septic system	5/14/2001	1	6.5	6.5	0	0	0	0	7	0	21
33-004(b)	Septic system	8/15/2001	1	1.3	13	0	0	0	0	0	0	15.3
33-004(c)	Septic system	5/24/1999	1	6.5	1.3	0	0	0	0	0	0	8.8
33-004(d)	Septic system	8/13/2001	1	6.5	6.5	5	19	11	7	0	0	56
33-004(g)	Outfall	8/1/1997	1	6.5	6.5	0	0	0	0	0	0	14
33-004(h)	Outfall	11/24/1997	1	1.3	1.3	5	19	22	7	0	0	56.6
33-004(i)	Outfall	8/1/1997	1	1.3	6.5	5	19	0	0	7	0	39.8
33-004(j)	Outfall	8/1/1997	17	13	13	5	19	11	0	7	0	85
33-004(k)	Outfall	8/1/1997	1	6.5	6.5	0	0	0	0	0	0	14
33-004(m)	Septic system	5/24/1999	1	6.5	1.3	0	0	0	0	0	0	8.8
33-005(a)	Septic system	8/15/2001	1	6.5	6.5	5	19	11	0	0	0	49
33-005(b)	Septic system	8/15/2001	1	6.5	6.5	5	19	11	0	0	0	49
33-005(c)	Septic system	8/15/2001	1	6.5	6.5	5	19	11	0	0	0	49
33-006(a)	Firing site (inactive)	8/1/1997	1	6.5	6.5	5	19	11	7	0	0	56
33-006(b)	Firing range (inactive)	9/24/2001	1	6.5	6.5	0	0	0	0	0	0	14
33-007(a)	Firing range (inactive)	8/1/1997	1	6.5	1.3	0	0	0	7	0	0	15.8
33-007(b)	Firing range (inactive)	8/1/1997	17	13	1.3	5	19	0	0	0	4	59.3
33-007(c)	Firing range (inactive)	8/1/1997	17	1.3	6.5	0	0	0	0	0	0	24.8
33-008(a)	Landfill	8/15/2001	1	6.5	6.5	5	1.9	0	0	0	0	20.9
33-008(b)	Landfill	9/24/2001	1	6.5	1.3	0	0	0	7	0	0	15.8
33-008(c)	Landfill	8/1/1997	1	6.5	6.5	5	19	11	7	0	0	56
33-009	Surface disposal - PCB only site	8/1/1997	1	13	13	0	0	0	0	0	0	27
33-010(a)	Surface disposal	8/1/1997	1	13	13	5	19	2.2	0	0	0	53.2

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
33-010(b)	Surface disposal	11/5/1998	4	6.5	13	5	9.5	0	0	7	0	45
33-010(c)	Surface disposal	8/1/1997	17	6.5	13	5	19	0	0	0	0	60.5
33-010(d)	Surface disposal	5/24/1999	4	6.5	13	5	9.5	0	7	0	0	45
33-010(f)	Surface disposal	8/15/2001	1	6.5	6.5	5	19	2.2	0	7	0	47.2
33-010(g)	Surface disposal	8/13/2001	1	1.3	13	5	9.5	11	7	0	0	47.8
33-010(h)	Surface disposal	5/24/1999	1	6.5	1.3	5	19	0	0	0	0	32.8
33-011(a)	Storage area	8/1/1997	1	13	1.3	5	1.9	11	0	0	0	33.2
33-011(b)	Storage area	8/1/1997	1	6.5	6.5	5	19	0	0	0	0	49
33-011(c)	Storage area	5/24/1999	1	6.5	1.3	0	0	0	0	0	0	8.8
33-011(d)	Storage area	10/8/1998	1	1.3	1.3	5	19	0	7	0	0	34.6
33-011(e)	Drum storage	8/15/2001	1	6.5	1.3	5	9.5	2.2	0	7	0	32.5
33-012(a)	Drum storage - PCB only site	5/14/2001	1	6.5	6.5	0	0	0	7	0	0	21
33-013	Storage area	8/1/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
33-014	Burn site	8/1/1997	1	13	1.3	0	0	0	0	0	0	15.3
33-015	Incinerator	5/24/1999	1	6.5	1.3	5	19	11	0	7	0	50.8
33-016	Sump	5/24/1999	4	13	6.5	5	19	0	0	7	0	54.5
33-017	Operational release	8/1/1997	1	1.3	13	0	0	0	7	0	0	22.3
35-002	Material disposal area (MDA X)	7/30/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
35-003(a)	Wastewater treatment facility	5/20/1998	1	1.3	1.3	5	19	0	0	0	0	27.6
35-003(b)	Wastewater treatment facility	5/20/1998	1	1.3	1.3	5	19	0	0	0	0	27.6
35-003(c)	Wastewater treatment facility	5/20/1998	1	1.3	1.3	5	19	0	0	0	0	27.6
35-003(d)	Wastewater treatment facility	8/6/1997	4	1.3	13	0	0	0	0	0	0	18.3
35-003(e)	Wastewater treatment facility	8/6/1997	1	6.5	1.3	5	9.5	2.2	7	0	0	32.5
35-003(f)	Wastewater treatment facility	8/6/1997	1	6.5	1.3	5	9.5	2.2	7	0	0	32.5
35-003(g)	Wastewater treatment facility	8/6/1997	1	6.5	1.3	5	9.5	2.2	7	0	0	32.5
35-003(h)	Wastewater treatment facility	7/31/2001	1	1.3	13	5	1.9	11	7	0	4	44.2
35-003(j)	Wastewater treatment facility	8/20/1997	1	1.3	1.3	5	19	0	7	0	0	34.6
35-003(k)	Wastewater treatment facility	8/20/1997	1	1.3	1.3	5	19	0	7	0	0	34.6
35-003(l)	Wastewater treatment facility	8/6/1997	4	6.5	6.5	5	19	11	7	0	0	59
35-003(m)	Wastewater treatment facility	8/6/1997	1	6.5	1.3	5	9.5	2.2	7	0	0	32.5
35-003(misc)	Industrial waste lines	4/24/2001	1	6.5	13	0	0	0	7	0	0	27.5
35-003(n)	Wastewater treatment facility	5/20/1998	1	1.3	1.3	5	19	0	0	0	0	27.6
35-003(o)	Wastewater treatment facility	8/6/1997	1	6.5	1.3	5	9.5	2.2	7	0	0	32.5
35-003(p)	Wastewater treatment facility	9/24/1997	1	6.5	1.3	5	19	11	7	0	0	50.8
35-003(q)	Wastewater treatment facility	8/6/1997	4	6.5	6.5	5	19	11	7	0	0	59
35-003(r)	Outfall	8/20/1997	17	6.5	6.5	5	19	22	7	0	4	87
35-004(a)	Storage areas	7/30/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
35-004(b)	Storage areas	7/30/1997	1	13	1.3	0	0	0	7	0	0	22.3
35-004(g)	Container storage area	7/30/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
35-004(h)	Container storage area	8/24/1997	1	6.5	1.3	5	19	11	7	0	0	50.8
35-004(m)	Container storage area	8/20/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
35-008	Surface disposal and landfil	6/4/1997	4	13	13	5	19	0	7	0	0	61
35-009(a)	Septic system	7/30/1997	1	13	1.3	0	0	0	7	0	0	22.3
35-009(b)	Septic system	7/30/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
35-009(c)	Septic system	8/21/1997	4	13	1.3	0	0	0	0	0	0	18.3
35-009(d)	Septic system	8/6/1997	1	6.5	1.3	5	19	0	0	0	0	32.8
35-009(e)	Septic system	7/30/1997	4	1.3	13	0	0	0	0	0	0	18.3
35-010(a)	Sanitary lagoon	8/6/1997	13	6.5	1.3	0	0	0	0	0	0	20.8
35-010(b)	Sanitary lagoon	8/6/1997	13	6.5	1.3	0	0	0	0	0	0	20.8

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
35-010(c)	Sanitary lagoon	8/6/1997	13	6.5	1.3	0	0	0	0	0	0	20.8
35-010(d)	Sand filters	8/6/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
35-010(e)	Discharge headwall from sand filter	8/6/1997	17	6.5	1.3	0	0	0	0	0	0	24.8
35-013(a)	Sump	9/13/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
35-013(b)	Sump	8/1/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
35-013(c)	Sump	8/7/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
35-014(a)	Operational release	8/20/1997	1	1.3	1.3	0	0	0	0	7	0	10.6
35-014(b)	Leaking drum	4/24/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
35-014(d)	Operational release	8/20/1997	1	6.5	1.3	0	0	0	7	0	0	15.8
35-014(e)	Oil Spill	6/4/1997	4	13	13	5	19	0	7	0	0	61
35-014(e2)	Oil Spill	9/24/1997	1	1.3	1.3	5	19	11	0	7	0	45.6
35-014(f)	Soil contamination	8/21/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
35-014(g)	Soil contamination	8/20/1997	1	1.3	6.5	5	19	0	7	0	0	39.8
35-014(g2)	Soil contamination	8/20/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
35-014(g3)	Soil contamination	8/20/1997	1	1.3	6.5	5	19	0	7	0	0	39.8
35-015(a)	Soil contamination	8/20/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
35-015(b)	Waste oil treatment	8/20/1997	1	1.3	1.3	5	19	0	7	0	0	34.6
35-016(a)	Drains and outfalls	8/20/1997	13	13	13	5	19	22	0	7	0	92
35-016(b)	Outfall	8/20/1997	13	13	13	5	19	22	7	0	4	96
35-016(c)	Outfall	7/30/1997	4	6.5	13	5	9.5	2.2	7	0	0	47.2
35-016(d)	Outfall	8/20/1997	4	6.5	13	5	19	22	7	0	0	76.5
35-016(e)	Outfall	7/30/1997	4	13	13	5	19	11	7	0	0	72
35-016(f)	Storm drain	7/30/1997	4	6.5	13	5	19	22	7	0	0	76.5
35-016(g)	Outfall	8/21/1997	4	1.3	13	5	19	22	0	0	4	68.3
35-016(h)	Storm drain	8/21/1997	4	6.5	13	5	19	22	7	0	0	76.5
35-016(i)	Drains and outfalls	7/30/1997	4	13	13	5	19	0	7	0	0	61
35-016(j)	Storm drain	8/21/1997	4	6.5	6.5	0	0	0	7	0	0	24
35-016(k)	Drains and outfalls	8/6/1997	1	6.5	6.5	5	19	11	0	0	4	53
35-016(l)	Storm drain	8/6/1997	1	6.5	6.5	5	19	22	0	0	4	64
35-016(m)	Drains and outfalls	8/20/1997	4	13	13	5	19	11	7	0	0	72
35-016(n)	Storm drain	8/20/1997	4	1.3	6.5	5	19	0	7	0	0	42.8
35-016(o)	Drains and outfalls	8/20/1997	4	1.3	13	5	19	11	7	0	0	60.3
35-016(p)	Outfall	8/20/1997	4	1.3	13	5	19	11	7	0	0	60.3
35-016(q)	Drains and outfalls	8/20/1997	13	13	13	5	19	22	0	7	0	92
35-018(a)	Transformer	8/20/1997	1	6.5	1.3	0	0	0	7	0	0	15.8
36-001	Material disposal area (MDA AA)	12/9/1998	13	6.5	1.3	5	1.9	11	0	7	0	45.7
36-002	Sump	5/15/2001	1	6.5	1.3	0	0	0	0	7	0	15.8
36-003(a)	Septic system	5/15/2001	1	1.3	13	0	0	0	0	0	0	15.3
36-003(b)	Septic system, I-J Site	7/19/1999	4	6.5	6.5	5	19	2.2	0	7	0	50.2
36-004(a)	Firing site (active)	12/9/1997	1	13	1.3	5	19	2.2	0	7	0	48.5
36-004(b)	Firing site (active)	12/9/1997	1	13	1.3	5	19	11	0	7	0	57.3
36-004(c)	Firing site - open detonation (active)	12/9/1997	1	13	1.3	5	19	22	7	0	0	68.3
36-004(d)	Firing site (Lower Slobbovia, skunk works, burn pit) (active)	8/25/1997	13	6.5	6.5	0	0	0	0	7	0	33
36-004(e)	I-J Firing Site (active)	11/4/1997	1	13	1.3	5	19	11	7	0	0	57.3
36-005	Surface disposal site	8/25/1997	1	13	6.5	5	1.9	11	0	7	0	45.4
36-006	Surface disposal site	8/25/1997	17	13	13	5	19	11	0	0	0	78
36-008	Surface disposal area located near TA-36-1	12/9/1997	4	6.5	6.5	5	19	0	7	0	4	52
39-001(a)	Landfill	8/4/1997	13	6.5	1.3	0	0	0	0	0	0	20.8

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
39-001(b)	Material disposal area (MDA Y)	8/4/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
39-002(a)	Storage area	12/9/1997	13	6.5	1.3	0	0	0	0	0	0	20.8
39-002(b)	Storage area	8/4/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
39-002(c)	Storage area	8/4/1997	13	1.3	1.3	5	1.9	0	0	7	0	29.5
39-002(d)	Storage area	8/4/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
39-002(f)	Storage area	8/4/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
39-004(a)	Firing site	12/16/1997	13	13	13	5	19	0	0	7	4	74
39-004(b)	Firing site	8/4/1997	13	13	6.5	5	19	11	7	0	0	74.5
39-004(c)	Firing site 39-6 (open detonation) - RCRA Unit (active)	8/1/1998	13	13	6.5	5	19	11	7	0	0	74.5
39-004(d)	Firing site 39-57 (open detonation) - RCRA Unit (active)	8/4/1997	13	13	13	5	19	0	0	7	4	74
39-004(e)	Firing site (active)	8/4/1997	13	13	6.5	5	19	11	0	7	4	78.5
39-005	Seepage pit	5/24/1999	1	6.5	1.3	0	0	0	0	7	0	15.8
39-006(a)	Septic system	8/4/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
39-007(a)	Storage area	8/23/2001	13	1.3	1.3	0	0	0	0	0	0	15.6
39-007(d)	Storage area	5/24/1999	1	1.3	1.3	0	0	0	7	0	0	10.6
39-008	Firing range (inactive)	8/4/1997	13	1.3	1.3	5	1.9	0	0	7	0	29.5
39-010	Excavated soil dump	10/15/2001	13	1.3	1.3	5	1.9	0	0	0	0	22.5
40-001(b)	Septic system	7/31/1997	1	6.5	6.5	0	0	0	0	0	0	14
40-001(c)	Septic system	8/7/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
40-003(a)	Scrap burn site - completed RCRA closure	12/18/2000	1	13	1.3	5	19	0	0	7	0	46.3
40-003(b)	Burning area/open detonation (closure)	12/18/2000	1	13	1.3	5	19	0	0	7	0	46.3
40-004	Operational release	8/2/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
40-005	Sump	8/7/1997	1	6.5	1.3	5	19	0	7	0	0	39.8
40-006(a)	Firing site (active)	6/22/2000	4	13	13	5	19	2.2	0	0	0	56.2
40-006(b)	Firing site (active)	6/22/2000	1	13	13	5	19	0	7	0	4	62
40-006(c)	Firing site (active)	6/13/2002	4	1.3	13	0	0	0	7	0	0	25.3
40-007(a)	Storage area	8/3/2001	1	6.5	13	5	1.9	2.2	0	0	0	29.6
40-009	Landfill	6/13/2002	4	6.5	13	0	0	0	7	0	0	30.5
40-010	Surface disposal site	6/22/2000	4	13	6.5	5	9.5	2.2	0	0	0	40.2
41-001	Septic system	8/15/2001	13	1.3	13	0	0	0	0	0	0	27.3
41-002(a)	Wastewater treatment facility	8/15/2001	13	13	1.3	0	0	0	0	0	0	27.3
41-002(b)	Wastewater treatment facility	8/6/1997	13	6.5	6.5	0	0	0	0	7	0	33
41-002(c)	Wastewater treatment facility	8/6/1997	13	6.5	6.5	0	0	0	0	7	0	33
41-003	Sump	9/24/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
42-001(a)	Incinerator (former location)	3/3/1998	1	6.5	1.3	5	19	22	7	0	4	65.8
42-001(b)	Ash storage tank (former location)	4/24/2002	1	1.3	13	0	0	0	7	0	0	22.3
42-001(c)	Ash storage tank (former location)	3/3/1998	1	6.5	1.3	5	19	22	7	0	4	65.8
42-002(a)	Decontamination facility (former location)	3/3/1998	1	6.5	1.3	5	19	22	7	0	4	65.8
42-002(b)	Decontamination facility driveway (former location)	3/3/1998	1	6.5	1.3	5	19	22	7	0	4	65.8
42-003	Septic system (former location)	1/13/2000	4	6.5	1.3	5	19	0	0	0	0	35.8
43-001(a1)	Waste lines (pre-1981)	8/24/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
43-001(b2)	Outfall	10/7/1997	1	6.5	1.3	5	1.9	0	7	0	4	26.7
43-002	Incinerator	8/24/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
45-001	Wastewater treatment facility	8/14/2001	1	1.3	13	5	19	0	7	0	4	50.3
45-002	Vehicle decontamination facility	11/12/1999	1	1.3	1.3	5	19	0	0	0	0	27.6
45-003	Waste lines	11/12/1999	1	1.3	1.3	5	19	0	0	0	0	27.6

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
45-004	Sanitary sewer outfall	11/12/1999	4	6.5	6.5	5	19	2.2	0	7	0	50.2
46-002	Surface impoundment	8/8/2002	17	6.5	1.3	0	0	0	0	7	0	31.8
46-003(a)	Septic system	7/26/2001	1	1.3	6.5	5	1.9	22	7	0	0	44.7
46-003(b)	Septic system	7/26/2001	1	6.5	13	5	19	11	0	0	0	55.5
46-003(c)	Septic system	7/26/2001	1	1.3	13	0	0	0	7	0	0	22.3
46-003(d)	Septic system	7/26/2001	1	1.3	13	5	1.9	2.2	7	0	0	31.4
46-003(e)	Septic system	7/26/2001	1	6.5	1.3	5	19	11	7	0	0	50.8
46-003(f)	Septic system	7/26/2001	1	1.3	13	5	1.9	0	7	0	0	29.2
46-003(g)	Septic system	7/26/2001	1	6.5	13	5	1.9	2.2	7	0	0	36.6
46-003(h)	Operational release	7/12/1999	1	6.5	1.3	0	0	0	0	0	0	8.8
46-004(a)	Waste line	10/1/2000	4	6.5	13	5	9.5	0	7	0	4	49
46-004(a2)	Outfall	4/25/2002	1	1.3	13	0	0	0	7	0	0	22.3
46-004(b2)	Operational release	4/25/2002	1	13	6.5	0	0	0	7	0	0	27.5
46-004(c)	Sump	10/1/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
46-004(c2)	Outfall	4/24/2002	1	6.5	13	0	0	0	7	0	0	27.5
46-004(d)	Sump	10/1/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
46-004(d2)	Stack emissions	6/4/2002	4	6.5	13	0	0	0	7	0	0	30.5
46-004(e)	Sump	10/1/2000	1	1.3	1.3	0	0	0	7	0	0	10.6
46-004(f)	Outfall	10/8/1997	4	1.3	1.3	5	19	0	7	0	0	37.6
46-004(g)	Outfall / stack emissions	10/1/1997	4	6.5	13	5	9.5	11	7	0	0	56
46-004(h)	Outfall / stack emissions	6/3/2002	4	13	13	0	0	0	7	0	0	37
46-004(m)	Outfall	10/1/2000	4	6.5	13	5	9.5	0	7	0	4	49
46-004(p)	Sump	10/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
46-004(q)	Outfall	10/1/2000	4	6.5	13	5	9.5	0	7	0	0	45
46-004(r)	Outfall	10/8/1997	4	1.3	1.3	5	19	0	7	0	0	37.6
46-004(s)	Outfall	10/1/2000	4	6.5	13	5	9.5	0	7	0	4	49
46-004(t)	Outfall	8/8/2002	1	1.3	13	5	19	0	7	0	0	46.3
46-004(u)	Outfall	10/1/2000	4	6.5	13	5	9.5	0	7	0	0	45
46-004(v)	Outfall	4/25/2002	4	13	13	0	0	0	0	0	0	30
46-004(w)	Outfall	10/8/1997	4	1.3	1.3	5	19	0	7	0	0	37.6
46-004(x)	Outfall	4/25/2002	4	6.5	13	0	0	0	7	0	0	30.5
46-004(y)	Outfall	10/1/2000	4	6.5	13	5	9.5	0	7	0	4	49
46-004(z)	Outfall	4/24/2002	4	6.5	13	0	0	0	7	0	0	30.5
46-005	Surface impoundment	9/30/2000	17	6.5	1.3	5	19	0	0	0	4	52.8
46-006(a)	Operational release	10/1/1997	4	6.5	13	0	0	0	7	0	0	30.5
46-006(b)	Operational release	10/8/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
46-006(c)	Operational release	10/8/1997	1	1.3	6.5	5	9.5	0	7	0	0	30.3
46-006(d)	Operational release	10/1/2000	4	6.5	13	5	9.5	0	7	0	4	49
46-006(f)	Storage area	10/8/1997	1	1.3	1.3	5	19	0	7	0	0	34.6
46-006(g)	Operational release	7/26/2001	1	1.3	13	5	1.9	0	7	0	0	29.2
46-007	Operational release	10/1/1997	4	6.5	1.3	0	0	0	7	0	4	22.8
46-008(a)	Storage area	10/8/1997	1	1.3	1.3	5	1.9	0	7	0	0	17.5
46-008(b)	Storage area	10/1/1997	4	6.5	1.3	0	0	0	7	0	4	22.8
46-008(d)	Storage area	10/8/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
46-008(e)	Storage area	10/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
46-008(f)	Storage area	10/8/1997	1	1.3	1.3	5	1.9	0	7	0	0	17.5
46-008(g)	Storage area	11/19/2002	1	1.3	13	0	0	0	7	0	0	22.3
46-009(a)	Surface disposal	1/13/2000	13	6.5	6.5	5	19	0	7	0	0	57
46-009(b)	Surface disposal	8/8/2002	4	6.5	13	0	0	0	0	7	0	30.5

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
46-010(d)	Operational release SAA	7/26/2001	1	6.5	6.5	5	1.9	2.2	7	0	0	30.1
48-001	Air exhaust system	9/24/1997	1	13	13	0	0	0	7	0	0	34
48-002(a)	Container storage area	7/30/1997	1	13	1.3	0	0	0	0	0	0	15.3
48-002(b)	Container storage area	7/30/1997	1	13	1.3	0	0	0	0	0	0	15.3
48-002(e)	Container storage	5/8/2003	1	1.3	1.3	0	0	0	7	0	0	10.6
48-003	Septic system	9/2/1999	4	6.5	6.5	5	9.5	2.2	0	7	0	40.7
48-004(a)	Sumps and tanks	7/27/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
48-004(b)	Sumps and tanks	7/27/2001	1	13	6.5	0	0	0	7	0	0	27.5
48-004(c)	Sumps and tanks	7/27/2001	1	1.3	13	5	1.9	0	7	0	0	29.2
48-005	Waste lines	7/27/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
48-007(a)	Drains and outfalls	4/22/2002	1	6.5	6.5	0	0	0	7	0	0	21
48-007(b)	Drains and outfalls	7/30/1997	4	1.3	13	5	19	0	7	0	0	49.3
48-007(c)	Drains and outfalls	4/22/2002	1	6.5	13	0	0	0	0	7	0	27.5
48-007(d)	Drains and outfalls	7/30/1997	13	1.3	6.5	5	19	0	7	0	4	55.8
48-007(f)	Drains and outfalls	7/30/1997	4	6.5	13	5	19	22	7	0	0	76.5
48-010	Surface impoundment	7/30/1997	13	1.3	13	5	19	22	0	7	0	80.3
49-001(a)	Material disposal area (MDA AB) (experimental shafts)	8/15/2001	1	1.3	6.5	5	19	22	0	0	0	54.8
49-001(b)	Material disposal area (MDA AB) (experimental shafts)	2/26/1998	1	1.3	1.3	5	19	0	0	7	0	34.6
49-001(c)	Material disposal area (MDA AB) (experimental shafts)	2/26/1998	1	1.3	1.3	5	1.9	0	0	7	0	17.5
49-001(d)	Material disposal area (MDA AB) (experimental shafts)	9/4/2002	1	1.3	1.3	0	0	0	0	0	0	3.6
49-001(e)	Material disposal area (MDA AB) (experimental shafts)	8/23/2001	1	6.5	1.3	5	1.9	11	0	0	0	26.7
49-001(f)	Material disposal area (MDA AB) (experimental shafts)	8/15/2001	1	6.5	6.5	0	0	0	0	0	0	14
49-001(g)	Material disposal area (MDA AB) (miscellaneous)	8/20/2002	13	1.3	6.5	0	0	0	0	7	0	27.8
49-002	Operational facility (Area 10 underground chamber)	8/24/2001	1	6.5	13	0	0	0	0	0	0	20.5
49-003	Leach field (Area 11 rad/chem and small shot area)	8/3/1998	1	1.3	1.3	5	19	2.2	0	7	0	36.8
49-004	Burn site and landfill (Area 6)	8/15/2001	1	1.3	6.5	5	19	2.2	0	0	0	35
49-005(a)	Landfill (east of Area 10)	8/15/2001	1	13	6.5	5	19	22	7	0	0	73.5
49-005(b)	Landfill (Area 5)	7/2/1999	1	1.3	1.3	0	0	0	0	0	0	3.6
49-006	Sump (Area 5)	7/2/1999	1	1.3	1.3	0	0	0	0	0	0	3.6
49-008(a)	Soil contamination (Area 5)	8/24/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
49-008(b)	Soil contamination (Area 6)	8/24/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
49-008(c)	Soil contamination (Area 11)	8/24/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
49-008(d)	Firing sites (Bottle House area) soil contamination and underground chamber (inactive)	9/24/1998	1	6.5	1.3	0	0	0	0	0	0	8.8
50-001(a)	Waste treatment facility TA-50-1 - RCRA Unit (active)	7/30/2001	1	1.3	6.5	0	0	0	0	0	0	8.8
50-002(a)	Underground tanks	7/30/2001	1	1.3	6.5	0	0	0	7	0	0	15.8
50-002(b)	Underground tank	7/30/2001	1	1.3	6.5	0	0	0	0	0	0	8.8
50-002(c)	Underground tank	7/30/2001	1	1.3	6.5	0	0	0	0	0	0	8.8

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
50-004(a)	Waste lines	7/6/1999	1	1.3	1.3	5	19	0	7	0	4	38.6
50-004(b)	Underground tanks	7/6/1999	1	1.3	1.3	5	19	0	7	0	4	38.6
50-004(c)	Waste lines	7/30/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
50-006(a)	Operational release	9/4/1997	17	6.5	1.3	5	19	22	7	0	0	77.8
50-006(c)	Operational release	7/6/1999	1	1.3	1.3	5	19	0	7	0	4	38.6
50-006(d)	Effluent discharge	7/31/1998	17	13	13	5	19	11	0	7	4	89
50-007	Incinerator	7/6/1999	1	1.3	1.3	5	19	0	7	0	4	38.6
50-008	Reduction site	7/6/1999	1	1.3	1.3	5	19	0	7	0	4	38.6
50-009	Material disposal area (MDA C)	4/18/2001	1	6.5	1.3	5	19	22	0	0	0	54.8
50-011(a)	Septic system	7/6/1999	1	1.3	1.3	5	19	0	7	0	4	38.6
51-001	Septic system	5/5/2000	1	6.5	1.3	0	0	0	0	0	0	8.8
52-001(d)	UHTREX equipment	8/24/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
52-002(a)	Septic system	8/27/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
52-003(a)	Waste treatment facility	3/10/2005	1	13	6.5	0	0	0	0	7	0	27.5
53-001(a)	Storage area - PCB only site	6/18/1999	1	1.3	1.3	0	0	0	7	0	0	10.6
53-001(b)	Storage area	8/22/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
53-002(a)	Disposal lagoon (NE, NW impoundments) (inactive)	10/29/1997	1	6.5	1.3	5	19	11	0	0	4	47.8
53-002(b)	Disposal lagoon RCRA corrective action (active)	10/29/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
53-005	Disposal pit	8/22/2001	1	6.5	6.5	0	0	0	0	0	4	18
53-006(b)	Underground tank	7/31/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
53-006(c)	Underground tank	7/31/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
53-006(d)	Underground tank	7/31/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
53-006(e)	Underground tank	7/31/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
53-006(f)	Underground tank	7/31/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
53-007(a)	Aboveground neutralizer tank	8/22/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
53-008	Storage area, Boneyard	10/29/1997	1	6.5	1.3	5	19	22	7	0	0	61.8
53-012(e)	Outfall	10/29/1997	1	6.5	1.3	0	0	0	0	7	0	15.8
53-014	Soil Contamination, lead storage site II	6/18/1999	4	6.5	13	5	19	22	7	0	4	80.5
54-001(a)	Storage area	7/25/2001	1	1.3	13	0	0	0	7	0	0	22.3
54-001(d)	Storage area	8/14/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
54-004	Material disposal area (MDA H)	12/20/2000	1	1.3	1.3	5	19	11	0	7	0	45.6
54-005	Material disposal area (MDA J) (Pits 1-5, Shafts 1-4)	7/25/2001	1	6.5	6.5	5	1.9	0	0	0	0	20.9
54-006	Material disposal area (MDA L) (all subsurface units such as Pit A, SI B,C,D, Shafts 1-28, 29-34)	7/25/2001	1	1.3	1.3	0	0	0	7	0	0	10.6
54-007(a)	Septic system	7/25/2001	1	6.5	13	0	0	0	0	0	0	20.5
54-007(d)	Septic system	5/5/2000	1	6.5	1.3	5	9.5	0	0	0	0	23.3
54-012(b)	Reduction site	7/25/2001	1	1.3	13	0	0	0	7	0	0	22.3
54-013(b)	Material disposal area (MDA G) disposal pit (truck washing pit converted to Pit 19)	9/21/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
54-014(b)	Material disposal area (MDA G) storage pit (Pit 9, TRU waste)	7/30/2001	1	6.5	6.5	0	0	0	0	0	0	14
54-014(c)	Material disposal area (MDA G) storage shafts (shafts 200-233)	8/2/2001	1	6.5	1.3	5	19	0	7	0	0	39.8
54-014(d)	Material disposal area (MDA G) storage trenches A, B, C, D	7/30/2001	1	6.5	13	5	19	11	7	0	4	66.5

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
54-015(a)	Storage area (surface corrosive inhibitor)	8/14/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
54-015(b)	Pit 39- LLW disposal area (former TRU surface storage)	8/14/1997	1	13	13	0	0	0	0	0	0	27
54-015(c)	Storage area, TRU Pad 1	8/14/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
54-015(d)	Storage area, TRU Pad 2	8/14/1997	1	13	13	0	0	0	0	0	0	27
54-015(e)	Storage area, TRU Pad 3	8/14/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
54-015(f)	Storage area, TRU Pad 4	8/14/1997	1	13	13	0	0	0	0	0	0	27
54-015(k)	Storage area (TRU waste mound)	7/30/2001	1	6.5	6.5	0	0	0	0	0	4	18
54-017	Material disposal area (MDA G) disposal pits 16, 22 (active before 11/19/80)	7/30/2001	1	13	13	5	19	0	7	0	4	62
54-018	Material disposal area (MDA G) disposal pits 27-33,35-37 (active after 11/19/80)	8/2/2001	13	6.5	13	5	1.9	2.2	7	0	4	52.6
54-019	Material disposal area (MDA G) disposal shafts (active before 11/19/80)	8/2/2001	1	6.5	13	0	0	0	7	0	0	27.5
54-020	Material disposal area (MDA G) disposal shafts (active after 11/19/80)	8/2/2001	1	6.5	13	5	19	2.2	7	0	0	53.7
55-008	Sumps and tanks	9/13/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
55-009	Concrete enclosure	3/3/1998	1	1.3	1.3	0	0	0	7	0	0	10.6
57-001(b)	Settling ponds	9/4/1997	1	13	1.3	0	0	0	7	0	0	22.3
57-002	Sludge pit	9/4/1997	1	13	1.3	0	0	0	0	0	0	15.3
57-004(a)	Settling ponds	9/4/1997	1	13	1.3	0	0	0	0	0	0	15.3
57-006	Drum and contents, Fenton Hill (removed)	9/4/1997	1	1.3	6.5	0	0	0	7	0	0	15.8
57-007	Leach field	9/4/1997	1	1.3	6.5	0	0	0	7	0	0	15.8
59-004	Outfall	10/15/1997	4	6.5	6.5	0	0	0	0	7	0	24
60-002	Storage area	7/31/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
60-004(b)	Storage area	12/9/1999	1	6.5	1.3	0	0	0	0	0	0	8.8
60-004(c)	Storage area	3/10/2005	1	13	1.3	5	1.9	2.2	0	0	0	24.4
60-004(d)	Storage area	12/9/1999	1	6.5	1.3	0	0	0	0	0	0	8.8
60-004(e)	Storage area	12/9/1999	1	6.5	1.3	5	9.5	2.2	0	7	0	32.5
60-005(a)	Surface impoundment -formerly SWMU 03-029(a)	7/31/2001	1	1.3	13	0	0	0	0	0	0	15.3
60-006(a)	Septic system	8/16/2001	1	1.3	13	0	0	0	0	7	0	22.3
60-007(a)	Systematic or intent. prod. release	12/9/1999	1	13	1.3	0	0	0	0	0	0	15.3
60-007(b)	Systematic or intent. prod. release	7/31/2001	1	1.3	6.5	5	19	0	7	0	4	43.8
61-002	Transformer storage area - PCB only site	10/15/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
61-005	Landfill (Los Alamos municipal)	7/31/2001	1	13	13	0	0	0	0	0	0	27
61-006	Waste oil tank	7/31/2001	1	13	1.3	0	0	0	7	0	0	22.3
61-007	Transformer site - systematic leak - PCB only site	7/23/2001	1	6.5	1.3	5	19	0	7	0	4	43.8
63-001(a)	Septic system	8/27/1997	4	6.5	6.5	0	0	0	7	0	0	24
63-001(b)	Septic system	8/27/1997	4	6.5	6.5	0	0	0	7	0	0	24
69-001	Incinerator and associated equipment	8/16/2001	1	6.5	13	0	0	0	7	0	0	27.5
72-001	Firing range	7/29/1998	17	13	1.3	5	19	22	0	7	0	84.3
73-001(a)	Landfill	3/13/1998	13	6.5	13	5	19	22	7	0	0	85.5
73-001(b)	Surface disposal site (waste oil pit)	7/24/2001	1	1.3	13	0	0	0	7	0	0	22.3
73-001(c)	Landfill	7/24/2001	1	1.3	1.3	0	0	0	0	0	0	3.6
73-001(d)	Landfill	7/24/2001	1	1.3	13	0	0	0	7	0	0	22.3
73-002	Incinerator surface disposal	10/15/1997	4	6.5	13	5	9.5	11	7	0	0	56

SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
73-003	Steam cleaning plant	10/15/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
73-004(a)	Septic tank	10/15/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
73-004(b)	Septic tank	10/15/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
73-004(c)	Septic system	10/15/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
73-004(d)	Septic tank (landfill)	10/15/1997	1	6.5	13	5	19	2.2	0	0	0	46.7
73-006	Airport building outfalls	10/15/1997	4	6.5	13	5	9.5	11	7	0	0	56
C-00-020	Mortar impact area	4/5/2005	4	13	6.5	5	1.9	11	0	7	0	48.4
C-00-041	Asphalt and tar remnant site	5/14/1997	4	1.3	6.5	5	19	0	0	7	0	42.8
C-00-043	Manhole (removed)	4/6/2005	1	1.3	6.5	0	0	0	0	0	0	8.8
C-03-014	Storage area	7/29/1997	1	13	1.3	0	0	0	7	0	0	22.3
C-03-016	Oil metal bin	9/16/1997	1	13	1.3	0	0	0	0	0	0	15.3
C-06-001	Building	3/30/1998	1	6.5	1.3	0	0	0	0	0	0	8.8
C-06-005	Building TA-6-13 chemistry laboratory, assembly, and storage	3/30/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
C-06-006	Building TA-6-14 used for explosives pressing and storage	3/30/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
C-06-016	Building TA-6-28, magazine used for explosives storage	3/30/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
C-08-010	Building	6/3/1999	1	1.3	1.3	5	1.9	0	7	0	0	17.5
C-09-001	Soil contamination	6/3/1999	1	6.5	1.3	5	1.9	11	0	7	0	33.7
C-10-001	Surface soil, Bayo Canyon	10/22/1997	13	1.3	1.3	0	0	0	0	0	0	15.6
C-11-001	Laboratory	3/18/1998	1	1.3	1.3	0	0	0	0	0	0	3.6
C-11-002	Laboratory	11/9/1998	1	13	6.5	5	9.5	0	0	0	0	35
C-14-001	Building	10/6/1997	1	13	1.3	0	0	0	0	0	0	15.3
C-14-002	Building	10/6/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
C-14-003	Building	10/6/1997	1	6.5	6.5	0	0	0	0	0	0	14
C-14-004	Building	10/6/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
C-14-005	Building	10/6/1997	1	6.5	6.5	0	0	0	0	0	0	14
C-14-006	Building	10/6/1997	1	1.3	1.3	5	1.9	2.2	7	0	0	19.7
C-14-007	Building	10/6/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-14-008	Building	10/6/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
C-14-009	Building	10/6/1997	1	13	6.5	5	1.9	2.2	0	0	0	29.6
C-15-001	Surface disposal	8/28/1997	1	6.5	1.3	5	1.9	0	0	0	0	15.7
C-15-004	Transformers - PCB only site	8/25/1997	17	6.5	6.5	5	1.9	0	0	7	0	43.9
C-15-005	Former laboratory and building	10/2/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-15-006	Building	10/2/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-15-007	Non-intentional release	10/2/1997	4	13	1.3	5	19	2.2	7	0	0	51.5
C-15-010	Former underground tank	10/2/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
C-15-011	Former underground tank	10/14/1997	1	1.3	1.3	0	0	0	7	0	0	10.6
C-16-002	Building 16-262	11/24/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-16-005	Building	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-16-006	Building TA-16-148	8/8/1997	1	1.3	1.3	5	1.9	0	0	0	0	10.5
C-16-011	Building TA-16-132	10/20/1997	1	1.3	1.3	5	1.9	2.2	0	0	0	12.7
C-16-017	Building	8/8/1997	1	1.3	1.3	5	1.9	2.2	0	7	0	19.7
C-16-025	Building	9/22/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-16-026	Building	9/22/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-16-028	Former structure	9/22/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-16-030	Former structure	9/22/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-16-031	Building	9/22/1997	1	1.3	1.3	0	0	0	0	0	0	3.6

**SOP 2.01 SURFACE WATER SITE ASSESSMENTS
SUMMARY OF EROSION MATRIX SCORES**

LA-UR-05-4616

Site ID	Site Name	DATE ASSESSED	TOPO SCORE	% GROUND COVER SCORE	% SLOPE SCORE	RUNOFF EVIDENCE SCORE	TERMINUS SCORE	EROSION TYPE SCORE	STRUCTURE RUN-ON SCORE	NATURAL RUN-ON SCORE	OPERATIONS RUN-ON SCORE	TOTAL EROSION SCORE
C-16-051	Transport area	11/24/1997	1	1.3	1.3	5	1.9	2.2	0	7	0	19.7
C-16-060	Soil contamination area	8/29/1997	1	1.3	6.5	0	0	0	0	0	0	8.8
C-16-063	Generation area	9/5/1997	1	1.3	1.3	5	1.9	0	0	7	0	17.5
C-16-064	Drum storage area (HE scrap pick-up)	10/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-16-065	Drum storage area TA-16-185	8/8/1997	1	1.3	1.3	5	1.9	0	0	0	0	10.5
C-16-067	Storage area	10/28/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-16-068	Building 16-522	8/8/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
C-16-069	Media contamination area	8/8/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-16-073	Underground tank	10/17/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-16-074	Storage	10/10/1997	1	1.3	1.3	0	0	0	0	0	0	3.6
C-33-001	Transformer	8/1/1997	1	6.5	6.5	5	19	11	7	0	0	56
C-33-002	Transformer	8/1/1997	1	6.5	1.3	0	0	0	0	0	0	8.8
C-33-003	Soil contamination area	2/2/1999	4	6.5	6.5	5	19	11	7	0	0	59
C-35-007	Soil contamination	9/24/1997	13	13	6.5	0	0	0	0	7	0	39.5
C-36-001	Containment vessel	7/22/1999	1	13	1.3	5	19	11	7	0	0	57.3
C-36-003	Storm drainages	8/1/2000	4	6.5	6.5	5	19	0	7	0	4	52
C-36-006(e)	I-J Firing Site, projectile test area [duplicate of SWMU 15-006(e)] (active)	12/9/1997	1	13	1.3	0	0	0	0	0	0	15.3
C-41-004	Storm drains	8/6/1997	17	1.3	1.3	5	19	2.2	0	7	0	52.8
C-43-001	Outfall	10/7/1997	1	6.5	13	5	1.9	11	7	0	0	45.4
C-45-001	Parking lot of former treatment plant (inactive)	4/6/2005	17	6.5	13	5	19	22	7	0	4	93.5
C-46-001	One-time spill	10/8/1997	1	1.3	13	5	19	22	7	0	0	68.3