

EXPLANATION

✱	Reference Flag	M	Surface Metal	AT	Acetylene Tank
	Crest of Slope	SD	Surface Debris	PLS	Purple Loose Strife
	Toe of Slope	CD	Construction Debris	Frg	Fragmities
	Gully	h	Hummucky Ground	T●	Large Tree

SOUTH ROAD, TREE NURSERY AREA

SITE SKETCH MAP

Poplar Point Site, Washington, D.C.
Job #565-02 November 2002

Figure 5a