

FINAL DRAFT

Simulations Conducted in House in Bethel, Vermont




Figure 33: Wet Simulation in Attic of Vermont House - Versar Employee Spraying Water on Attic Insulation During Simulation.

Notes: Portion of stationary ambient air monitoring pump is visible in foreground. Personal air monitoring cassettes can be seen on Versar employee, oriented toward the breathing zone.



Figure 34: Dry Simulation in Attic of Vermont House - Versar employee manipulating attic insulation during simulation.

Notes: Portion of stationary ambient air monitoring pump is visible in foreground. SKC low volume air pump visible on belt of Versar employee.



Figure 35: Hole Being Cut in Ceiling of Vermont House - View from living space, hole being cutting from attic side.




Figure 36: Equipment for Blower Door Test Installed in Door of Vermont House.