



To enable safe asbestos removal, (sometimes broken) window glass was removed and the building was sealed.



Cedar Street view of main entrance.



Side view of overgrown Southern Medical Center property.



U.S. EPA's cleanup included excavation and proper disposal of underground storage tanks.



Crumbling asbestos-containing insulation on pipes.



Debris containing haz mat, medicines and old paperwork.



September 5, 2007: U.S. EPA on-scene coordinator Kevin Turner updates state and local officials, and community leaders, on the completed cleanup.