

**GULF COAST VACUUM SERVICES SUPERFUND SITE**  
Vermilion Parish, Louisiana



*BEFORE*

Organic-contaminated sludge in West Pit prior to treatment, after cover removal (right side of picture shows cover used to keep contaminated rainwater from accumulating and overflowing into nearby pasture)

*AFTER*

One of the on-site landfarms where the sludge is taken for biological treatment (note color change from above by end of treatment)



On-site pit where biological treatment residuals and stabilized metal-contaminated material are placed (pit will be capped at end of project)

