

**APPENDIX A**  
**Shumaker Photographs**



Photograph No. 1  
Date: 01/07/2008

Direction: West  
Time: 0725

Description: View of deep groundwater monitoring well DW3L. Well appeared in good condition.



Photograph No. 2  
Date: 01/07/2008

Direction: West  
Time: 0744

Description: View of TechLaw team member decontaminating water level meter.



Photograph No. 3  
Date: 01/07/2008

Direction: West  
Time: 0818

Description: View of TechLaw team member decontaminating bladder pump.



Photograph No. 4  
Date: 01/07/2008

Direction: West  
Time: 1517

Description: View of deep groundwater monitoring well DW-03. Well appeared in good condition.



Photograph No. 5  
Date: 01/09/2008

Direction: Southeast  
Time: 1142

Description: View of TechLaw team member decontaminating equipment at deep groundwater monitoring well DW-02L.



Photograph No. 1  
Date: 02/11/2008

Direction: Not Available  
Time: 1530

Description: View of EPA representative and TechLaw team member collecting sample blank.



Photograph No. 2  
Date: 02/11/2008

Direction: Not Available  
Time: 1532

Description: View of EPA representatives containerizing surface water sample SW-09.





Photograph No. 3  
Date: 02/11/2008

Direction: South  
Time: 1540

Description: View of surface water sample location SW-09.



Photograph No. 4  
Date: 02/11/2008

Direction: Not Available  
Time: 1541

Description: View of EPA representative collecting surface water sample SW-09.



Photograph No. 5  
Date: 02/11/2008

Direction: Not Available  
Time: 1630

Description: View of EPA representative collecting surface water sample SW-08 from middle of creek, approximately 30 ft west of bridge.



Photograph No. 6  
Date: 02/11/2008

Direction: Not Available  
Time: 1653

Description: View of EPA representative collecting surface water sample SW-08 from middle of creek, approximately 30 ft west of bridge.



Photograph No. 7  
Date: 02/11/2008

Direction: Not Available  
Time: 1654

Description: View of EPA representative collecting surface water sample SW-08 from middle of creek, approximately 30 ft west of bridge.



Photograph No. 8  
Date: 02/11/2008

Direction: Not Available  
Time: 1654

Description: View of EPA representatives containerizing surface water sample SW-08.



Photograph No. 9  
Date: 02/11/2008

Direction: Not Available  
Time: 1721

Description: View of EPA representative collecting surface water sample SW-06.



Photograph No. 10  
Date: 02/11/2008

Direction: Not Available  
Time: 1721

Description: View of EPA representatives containerizing surface water sample SW-06.





Photograph No. 11  
Date: 02/11/2008

Direction: Not Available  
Time: 1721

Description: View of EPA representative collecting surface water sample SW-06.



Photograph No. 12  
Date: 02/12/2008

Direction: Southeast  
Time: 0820

Description: View of EPA representative collecting surface water sample SW-06.



Photograph No. 13  
Date: 02/12/2008

Direction: Northwest  
Time: 0821

Description: View of EPA representatives containerizing surface water sample SW-33.



Photograph No. 14  
Date: 02/12/2008

Direction: Southeast  
Time: 0916

Description: View of EPA representative collecting surface water sample SW-34.



Photograph No. 15  
Date: 02/12/2008

Direction: Not Available  
Time: 0917

Description: View of EPA representative containerizing surface water sample SW-34.



Photograph No. 16  
Date: 02/12/2008

Direction: Not Available  
Time: 0918

Description: View of surface water sample location SW-34 and nearby power line tower.



Photograph No. 17  
Date: 02/12/2008

Direction: Not Available  
Time: 0944

Description: View of EPA representative collecting surface water sample SW-30.



Photograph No. 18  
Date: 02/12/2008

Direction: South  
Time: 1011

Description: View of EPA representative collecting surface water sample SW-32.





Photograph No. 19  
Date: 02/12/2008

Direction: Not Available  
Time: 1036

Description: View of EPA representative collecting surface water sample SW-31.



Photograph No. 20  
Date: 02/12/2008

Direction: Northwest  
Time: 1059

Description: View of surface water sample location SW-29 and sign adjacent to the road.



Photograph No. 21  
Date: 02/12/2008

Direction: Northeast  
Time: 1101

Description: View of EPA representative collecting surface water sample SW-29.



Photograph No. 22  
Date: 02/12/2008

Direction: Northeast  
Time: 1127

Description: View of EPA representative collecting surface water sample SW-28.



Photograph No. 23  
Date: 02/12/2008

Direction: Not Available  
Time: 1218

Description: View of EPA representative collecting surface water sample SW-27.



Photograph No. 24  
Date: 02/12/2008

Direction: Northwest  
Time: 1316

Description: View of EPA representative collecting surface water sample SW-26.



Photograph No. 25  
Date: 02/12/2008

Direction: Northwest  
Time: 1406

Description: View of EPA representative collecting surface water sample SW-25.



Photograph No. 26  
Date: 02/12/2008

Direction: Northeast  
Time: 1428

Description: View of bridge that crosses over the stream where surface water sample SW-20 will be collected.





Photograph No. 27  
Date: 02/12/2008

Direction: East  
Time: 1431

Description: View of EPA representative collecting surface water sample SW-20.



Photograph No. 28  
Date: 02/13/2008

Direction: Northwest  
Time: 0820

Description: View of EPA representative collecting surface water sample SW-23.



Photograph No. 29  
Date: 02/13/2008

Direction: Northeast  
Time: 0825

Description: View of EPA representative collecting surface water sample SW-24.



Photograph No. 30  
Date: 02/13/2008

Direction: East  
Time: 0855

Description: View of EPA representative collecting surface water sample SW-22.



Photograph No. 31  
Date: 02/13/2008

Direction: Southwest  
Time: 0911

Description: View of EPA representative collecting surface water sample SW-21.



Photograph No. 32  
Date: 02/13/2008

Direction: East  
Time: 0931

Description: View of EPA representative collecting surface water sample SW-18.



Photograph No. 33  
Date: 02/13/2008

Direction: West  
Time: 0956

Description: View of EPA representative collecting surface water sample SW-19.



Photograph No. 34  
Date: 02/13/2008

Direction: Northwest  
Time: 1112

Description: View of EPA representative collecting surface water sample SW-17.





Photograph No. 35  
Date: 02/13/2008

Direction: West  
Time: 1151

Description: View of EPA representative collecting surface water sample SW-14.



Photograph No. 36  
Date: 02/13/2008

Direction: Northeast  
Time: 1229

Description: View of EPA representative collecting surface water sample SW-13.



Photograph No. 37  
Date: 02/13/2008

Direction: Not Available  
Time: 1256

Description: View of EPA representative collecting surface water sample SW-10.



Photograph No. 38  
Date: 02/13/2008

Direction: Southeast  
Time: 1402

Description: View of EPA representative collecting surface water sample SW-12.



Photograph No. 39  
Date: 02/13/2008

Direction: Southeast  
Time: 1427

Description: View of EPA representative collecting surface water sample SW-11.



Photograph No. 40  
Date: 02/14/2008

Direction: Northwest  
Time: 0837

Description: View of EPA representative collecting surface water sample SW-04.



Photograph No. 41  
Date: 02/14/2008

Direction: Southeast  
Time: 0852

Description: View of EPA representative collecting surface water sample SW-05.



Photograph No. 42  
Date: 02/14/2008

Direction: Not Available  
Time: 0917

Description: View of EPA representative collecting surface water sample SW-16.





Photograph No. 43  
Date: 02/14/2008

Direction: Southwest  
Time: 0937

Description: View of EPA representative collecting surface water sample SW-03.



Photograph No. 44  
Date: 02/14/2008

Direction: East  
Time: 0957

Description: View of EPA representative collecting surface water sample SW-01.



Photograph No. 45  
Date: 02/14/2008

Direction: Not Available  
Time: 1016

Description: View of EPA representative collecting surface water sample SW-02.



Photograph No. 1  
Date: 05/21/2008

Direction: Not Available  
Time: Not Available

Description: View of isotope columns and well pump at SW-7.



Photograph No. 2  
Date: 05/21/08

Direction: Not Available  
Time: Not Available

Description: View of cones set up at site SW-7 due to nearness to roadside.



Photograph No. 3  
Date: 05/21/08

Direction: Not available  
Time: Not Available

Description: View of isotopes column setup for SW-7.



Photograph No. 4  
Date: 05/21/2008

Direction: Not Available  
Time: Not Available

Description: View of generator and filter at SW-7.



Photograph No. 5  
Date: 05/21/2008

Direction: Not Available  
Time: Not Available

Description: View of well pump and filter at SW-7.





Photograph No. 6  
Date: 05/20/07

Direction: Not Available  
Time: 1013

Description: View of well pump, filter unit, and generator at SW-5.



Photograph No. 7  
Date: 5/20/07

Direction: Not Available  
Time: 1012

Description: View of isotope columns at site SW-5.