

efficient NNS bridges in Indiana, 3 could not geolocate begolocate because of haveficient data. Sinculturally deficient bridges are not recessarily unaske; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient tat the time the maps were developed

Bridge Label	Structure ID	Bridge Description	Location Description	
1	40900 I-69 SBL		0.55 S SR 127	
2	40890 I-69 NBL		0.55 S SR 127	
3	40950 I-69 SBL		0.14 S SR 120	
4	40940 I-6	9 NBL	0.14 S SR 120	