



## Structurally Deficient Bridges on the National Highway System Massachusetts - Congressional District 04



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 187 structurally deficient NHS bridges in Massachusetts, 11 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	N120654QLMTANBI	I 90 RAMPS A & B	AT INT 14 L50
2	N120674QNMATANBI	I 90	.1 MI E.CHARLES RV S11
3	S090093PTMHDNBI	US 1 NB/GL EDWRDS	NEAR STADIUM EXIT
4	S090103PRMHDNBI	US 1 NB/GL EDWRDS	US 1 AT I 95NB
5	N120174R5MTANBI	HWY CHURCH ST	.3 MI S. CHARLES RV S26
6	N120714RBMATANBI	I 90	.1 MI S. CHARLES RV S40
7	F020593TAMHDNBI	HWY RAMP A	AT E END OF BRAGA BR
8	F020583TKMHDNBI	I 195	FALL RIVER/SOMERSET LINE
9	T010283N8MHDNBI	US 44 WINTHROP ST	.1 MI NE OF NO WALKER ST
10	F090113MTMHDNBI	ST 24	ST 24 AT ST 79 (ASSONET)
11	R020133PAMHDNBI	US 44 CAPE HWY	US 44 AT ST 24
12	M1804147CMHDNBI	I 495 NB	AT MIDDLEBORO RAYNHAM TL
13	B2300346DMHDNBI	ST 18 BEDFORD ST	0.5 M N OF PLYMOUTH ST
14	N060143U2MHDNBI	I 195 EB	I 195 AT ST 140
15	N060143U3MHDNBI	I 195 WB	I 195 AT ST 140
16	N060203TVMHDNBI	I 195 EB RAMP F	I 195 AT ST 18
17	N060203TUMHDNBI	I 195 WB RAMP C	I 195 AT ST 18
18	F010023PJMHDNBI	US 6 (WEST BRG)	.7 MI W OF NBED C.L.
19	F010023PGMHDNBI	US 6 (EAST BRG)	AT NEW BEDFORD CITY LINE