



Structurally Deficient Bridges on the National Highway System Massachusetts - Congressional District 06



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 187 structurally deficient NHS bridges in Massachusetts, 11 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	S0500339KMHDNBI	ST107 SALEM TNPK	4.0 KM N OF JET SR 60
2	L1801639JMHDNBI	ST107 WESTERN AVE	200 FT N OF BALLARD ST
3	D030182U0MHDNBI	ST128	.4 MI N ST114
4	D030202U2MHDNBI	ST128	2 KM N ST114
5	A070262WJMHDNBI	I 495 NB	.1 MI N EXIT 55
6	A070162V1MHDNBI	I 95	AT MERRIMAC RIVER
7	S010012UNMHDNBI	ST114 NORTH ST	.1 MI N ST107
8	G050172U8MHDNBI	ST128	AT ANNISQUAM RIVER