



Structurally Deficient Bridges on the National Highway System Massachusetts - Congressional District 09



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 187 structurally deficient NHS bridges in Massachusetts, 11 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	D0503034EMHDNBI	HWY PROVIDNCE HWY	.08 KM. NO. OF ST135
2	D0503334FMHDNBI	HWY PROVIDNCE HWY	.32 KM. N OF ST 1A
3	D0504835QMHDNBI	I 95 SB/ST128 SB	1.6 KM.SE OF US 1
4	D0504735NMHDNBI	I 95 SB/ST128 SB	.51 KM. SE OF US 1
5	D0504735MMHDNBI	I 95 NB/ST128 NB	.51 KM. SE OF US 1
6	C0204035KMHDNBI	I 95 RAMP T	I 95 AT ST 128
7	C0202735GMHDNBI	I 95 SB/US1/ST128	I 95 AT DEDHAM T.L.
8	C0202635FMHDNBI	I 95 NB/US1/ST128	I 95 AT DEDHAM T.L.
9	B160094F0MDCNBI	ST 3 CAMBRIDGE ST	.2 MI S OF BLOSSOM ST
10	B162584FNMDCNBI	HWY EMBKT WB ON	CHARLES CIRCLE STORROW D
11	B160134EMMDCNBI	ST 28 CHAS R DM RD	.1 MI NW OF NASHUA ST
12	B250483V4MHDNBI	ST123 BELMONT ST	.1 MI W OF VA HOSPITAL
13	W180123W2MHDNBI	ST106 W CENTER ST	.5 MI E OF ST 138
14	B161964F5MDCNBI	HWY MORRSSEY BLV	.1 MI W OF I 93
15	B163904F7MDCNBI	ST 3 A/MORRSY BLV	.2 MI E OF I 93
16	W180163MWMHDNBI	ST 24	.1 MI N OF BRIDGEWATER TL