




Structurally Deficient Bridges on the National Highway System Texas - Congressional District 30



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 184 structurally deficient NHS bridges in Texas, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	180570058102015	LOOP 12 SB	0.6 MI SE OF SH 303
2	180570044202011	IH 35E NB	0.9 MI S OF IH 30
3	180570M00903001	REINDEER ROAD	0.7 MI E OF HOUSTON SH RD
4	180570009214198	IH 45 NB	IH 45 & IH 30 INTERCHANGE
5	180570009214197	IH 45 SB	IH 45 & IH 30 INTERCHANGE