




Structurally Deficient Bridges on the National Highway System Illinois - Congressional District 18



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 297 structurally deficient NHS bridges in Illinois, 7 could not be geocoded because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	5000101220	US 24	E RIPLEY-SCHUYLER CL
2	69200115773	US 67 & ILL 100	1 MI NO JCT104
3	72013624952	US 24 & ILL 9	1 MI W OF MAPLETON
4	72001016398	US 24 & ILL9	WHEELER RD & US 24
5	72013428519	US 24	.5 MI E OF MCKINLEY
6	72001216400	WB US 24	W CL OF PEORIA
7	72201213525	ILL 6	0.5 MI W OF ILL 40
8	54002312706	US 136	.2M E 1ST-SAN JOSE
9	54002412707	US 136	1.6M E 1ST-SAN JOSE
10	72001716405	ILL 29	.1 MI S MOSSVILLE RD
11	54002512708	US 136	1.9M W I-55
12	90001219667	WB I-74	I-155 INTERCHANGE
13	90001319668	EB I-74	I-155 INTERCHANGE
14	90001419669	WB I-74	.15 MI E OF ILL 155
15	90001519670	EB I-74	.15 MI E OF ILL 121
16	90001619671	I-74	TWIN TUBES W OF MORT
17	90001719672	WB I-74	.5 MI W MORTON INTER
18	90001819673	EB I-74	.5 MI W MORTON INTER
19	58007923635	FAP 322(US 51)	S EDGE FORSYTH