




Structurally Deficient Bridges on the National Highway System Maine - Congressional District 02



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 28 structurally deficient NHS bridges in Maine, 1 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	2948	ROUTE 2	.1 MI W 113
2	2261	302	4 MI E 5
3	3791	ROUTES 2-5-26	US 2 OVER CNRR & RTE 26
4	1498	MTPK (SB)	81.41 MILE POINT
5	100	MTPK(NB)	81.4 MILE POINT
6	3842	US #2	1.5 MI E OF JCT RTE 27
7	2133	US 201	8.2 MI N OF BINGHAM T.L.
8	2504	ROUTE US 201	0.1 MI N JCT RTE 201A & 8
9	2767	US 2	CANAAN PITTSFLD TL
10	1438	I-95 SB	INTERCHANGE 167 (42)
11	5962	I-95 NB	INTERCHANGE 167 (42)
12	3008	US 1 & 3	COUNTY LINE&TL
13	5796	I-395	0.3 MI E OF I-95
14	6091	95 S.B.	SMYRNA / LUDLOW T.L.