




## Structurally Deficient Bridges on the National Highway System Connecticut - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 66 structurally deficient NHS bridges in Connecticut, 2 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	914	US ROUTE 202	1.5 MILE NO. OF ROUTE 219
2	1236	INTERSTATE-84 WB	NEAR EX 30
3	1235	INTERSTATE-84 EB	NEAR EX 30
4	518	ROUTE 10	ROUTE 10 OVER ROUTE 322
5	1247	INTERSTATE-84 WB	.2 MI W EXIT 32, ROUTE 10
6	649	INTERSTATE-84 WB	AT EXIT 32 INTERSTATE 84
7	03401B	SR 503 EASTBOUND	.26 MILES S OF JCT I-84WB
8	03399C	I-84 TR 824	.10 M SO OF JCT US6&US202
9	03400C	I-84 TR 823	RAMP I-84EB TO SISSON AVE
10	03160B	INTERSTATE-84 WB	.82 MI N OF JCT SR 504 SB
11	03160A	INTERSTATE-84 EB	EASTBOUND
12	03160D	I-84 RAMP 115	.33 MI N OF JCT SR 503 WB
13	01686B	I-84 TR 825	RAMP TO I91SB FROM I84 EB
14	5868	W-N TURNING RDWY	FLY-OVER
15	814	ROUTE 15 RAMP 161	15 SB RAMP TO BRAINARD RD
16	2376	I-84 TR 831	RTE 2/84 EB EXIT 70 GOV
17	981	US ROUTE 44	.7 MI EAST OF HARTFORD TL
18	417	ROUTE 3	.22MI N OF ACCESS TO I-91
19	386	ROUTE 2 & RT 17 SB	ROUTE 2 AT EXIT NO 7
20	5845	CD WB ROADWAY	1.2 MI E OF 84-384 SPLIT
21	1702	ROUTE 2 WESTBOUND	.5 MILE WEST UP ROUTE 83