




Structurally Deficient Bridges on the National Highway System Texas - Congressional District 12



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 154 structurally deficient NHS bridges in Texas, 15 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	21840031401082	I 20 (EBL)	1.65 MI W OF FM 113
2	22490013411076	US 380	2.9 MILES EAST OF FM 1156
3	22490001306023	US 81 - 287 NBL	1.7MI.N.OF US-81 BI C
4	21840000803038	N SIDE PULL OFF	1.2 MI E OF FM-5
5	22490001308073	US 81/287 SB	1.77 MI N OF FM-2264
6	022200ZS4528002	SILVER CREEK RD	1.53 MI S FM 1886 W LK WO
7	22200000815302	IH820 SB FRTG ROAD	0.943MI SO OF US80
8	22200000815301	IH820 NB FRTG ROAD	0.943MI SO OF US80
9	22490013408039	US 380	8.1 MI E OF BUS 81
10	022200ZH8500005	S HULEN ST	1.2 MI S OF IH 30
11	022200ZU4000005	S UNIVERSITY DR NB	0.7 MI S OF IH 30
12	022200ZZ7600001	W 7TH STREET	W 7TH OVER FOREST PRK BLV
13	22200009401024	SH 183	0.2 MI E OF LP496
14	22200008101065	SP 347 EB WEATHFRD	0.2 MI W OF IH 35W
15	22200001416187	IH 35W SB	0.25 MI S OF NORTHSIDE DR
16	22200001416188	IH 35W NB	0.25 MI S OF NORTHSIDE DR
17	22200001416190	I 35W SB	0.1 MI N OF 287/377 INTER
18	22200001416189	I 35W NB	0.1 MI N OF 287/377 INTER
19	22200001416191	IH 35W NB	0.3 MI N OF E 4TH STREET
20	22200008112309	US 81/287 WB	3.1 MI S GOLDEN TRIANGLE
21	22200001416260	IH 35W SB	1.1 MI N OF SH 183