




Structurally Deficient Bridges on the National Highway System Ohio - Congressional District 16



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 178 structurally deficient NHS bridges in Ohio, 7 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	5202795	IR 71	5.41 MILES NORTH OF SR 83
2	5202825	IR 71	5.41 MILES NORTH OF SR 83
3	5202914	IR 71	6.06 MILES NORTH OF SR 83
4	5202949	IR 71	6.06 MILES NORTH OF SR 83
5	5204259	IR 76	OVER US 224
6	5203007	IR 71	.16 MILES NORTH OF IR 76
7	5200725	SR 18	1.46 MI W OF IR 71
8	7600518	SR 21	4.10 MI N OF SR 30
9	7600488	SR 21	4.10 MI N OF SR 30
10	7600186	SR 241	JCT OF SR 21 AND SR 241
11	7603002	IR-77 NB	6.10 MI S OF SR 627
12	7603576	IR 77	0.72 MI N OF SR 800