APPENDIX A PHOTO LOG OF SITE AND SAMPLING ACTIVITIES

APPENDIX A: PHOTO LOG OF SITE AND SAMPLING ACTIVITIES



Photograph A-1. The pole barn area. September 23, 2003.



Photograph A-2. Sampling activities at the pole barn area. September 23, 2003.



Photograph A-3. Sampling activities at the pole barn area. September 23, 2003.



Photograph A-4. The canal near the farmyard area. September 23, 2003.



Photograph A-5. The farmyard area. September 23, 2003.



Photograph A-6. Sample ID in the farmyard area. September 23, 2003.



Photograph A-7. The east pond area. September 23, 2003.



Photograph A-8. Sampling activities at the east pond area. September 23, 2003



Photograph A-9. Sampling activities at the east pond area. September 23, 2003.



Photograph A-10. The west pond area. September 24, 2003.



Photograph A-11. Sample ID in the west pond area. September 24, 2003.



Photograph A-12. The west pond area. September 24, 2003.



Photograph A-13. The west pond area looking at the salt crystal formations. September 24, 2003



Photograph A-14. The west pond area. September 24, 2003.



Photograph A-15. The west pond area. Salt crystal formations surrounding soil indention. September 24, 2003.



Photograph A-16. Vegetation found in the west pond area. September 24, 2003.