

Figure 4 Building 203 (Heating Plant)  
Suspected Asbestos (April 4, 2002)

Peeling  
Lead Paint  
↓




Figure 5 Building 203 (Heating Plant)  
Boiler Room Suspected Asbestos Containing Material  
(June 5, 2003)







Figure 6  
Building 203 (Heat Plant)  
Suspected Asbestos From Boiler  
(9/4/03)

Figure 7 Finland Radar Base Before It Was Decommissioned



**An aerial view of the radar station in February 1958 shows its utilitarian buildings, including two of the four radar towers (the big white domes).**