

Appendix A. Photos and Maps

Figure 1: Location of Former WRG/Zonolite Plant Dearborn





Figure 1. Location of former WRG Dearborn plant at 14300 Henn Street, Dearborn, Michigan.



Figure 2. Aerial photo of site (shaded blue). Visible are the soccer field immediately south of property and the school bus garage to the east. Approximate scale: 1" = 0.10 miles.



Figure 3. View of site, facing northeast. The railroad line is visible in the background. When the plant was active, this railroad line would transport vermiculite from Libby, Montana, into the facility for processing.



Figure 4. Looking down toward floor with slat wall in background. Libby asbestos-contaminated material (grayish substance) is visible at the bottom of the wall. Material escapes from the wall cavity through a gap between the lowest slat and the concrete floor.