


Sago Mine



2 Left Working Section

1 Left Working Section

Recently Sealed Area

Older Sealed Areas

Travel Route Into Mine

Mine Entrance

2 Miles

Prior to Accident on 1/2/06

- 3-6 a.m. - Section preshift exams conducted.
- 6:00 a.m. - 1 Left & 2 Left crews enter mine.
- 6:30 a.m. - Explosion occurs as 1 Left crew reaches section entrance.