




Structurally Deficient Bridges on the National Highway System New York - Congressional District 23



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 227 structurally deficient NHS bridges in New York, 5 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	1031872	RTE I81	EXIT 35 OF I81
2	1094681	RTE I81	7.3 MI N JCT I-81 + 411
3	1009630	RTE 12	0.2 MI SE JCT 12 + 194
4	5512859	RTE I90	4 MI W EXIT 33 OF I90
5	5523230	OGD-PRES INTER BR	1.8 MI.NE OF OGDENSBURG
6	1032800	RTE 812	IN VILLAGE OF HEUVELTON
7	1009540	RTE 12	02MI N JCT RTS 12D+12
8	1033822	RTE I87	1.5 MI N EXIT 32 OF I87
9	1033821	RTE I87	1.5 MI N EXIT 32 OF I87
10	1033771	RTE I87	RT I87 2.8 MI N EXIT 31
11	1033772	RTE I87	RT I87 2.8 MI N EXIT 31
12	1005911	RTE I87	2.3 MI S JCT RTS I87 & 22
13	1005912	RTE I87	2.3 MI S JCT RTS I87 & 22
14	1033851	RTE I87	1.6 MI N JCT RTS I87 & 22
15	1033941	RTE I87	.5 MI S OF SO.PLATTSBURGH
16	1009070	RTE 11	JCT RTS 11 +I-87