



Structurally Deficient Bridges on the National Highway System Maine - Congressional District 01



Consult your state DOT for the most up-to-date status of bridges.

Area of Detail



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 28 structurally deficient NHS bridges in Maine, 1 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	2047 #11-302		.3 MI W 35
2	290	GRAY INTERCHANGE	63.1 MILE POINT
3	348	RIVERSIDE/LARRABEE	48.5 MILE POINT
4	284	MTPK	55.5 MILE POINT
5	279	MTPK	56.70 MILE MARKER
6	363	MTPKSPUR	FS0.30
7	1467	MTPR SP (WB)	FS0.41 MILE POINT
8	364	MTPKSP EB	FS0.40 MILE POINT
9	549	GARDINER/LITCHFIEL	102.0 MILE POINT
10	3838	US RTE # 1	0.1 MI E OF JCT RTE 209
11	5793	I-95 NORTHBOUND	MILE 105.8 ON I-95 N B
12	5695	US #1	2 MI E 127
13	2577	ROUTE US 1	ON TOWNLINE