


Structurally Deficient Bridges on the National Highway System North Dakota



Consult your state DOT for the most up-to-date status of bridges.



Note: The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's National Bridge Inventory (NBI). With the exception of Kentucky and Pennsylvania, whose most current data is 2006, all data is from the 2007 NBI. Of the 9 structurally deficient NHS bridges in North Dakota, 0 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive regular safety inspections. The bridges listed were categorized as structurally deficient at the time the maps were developed.

Bridge Label	Structure ID	Bridge Description	Location Description
1	0094073264	L INTERSTATE 94	12 WEST OF ND 8
2	0002144205	L U.S. HWY 2	2 WEST OF HWY 83
3	281174610	US HIGHWAY 281	1 NORTH US 2
4	281127480	US HIGHWAY 281	NEW ROCKFORD SOUTH
5	29203413	US #81 & ND #5	JCT US 81 AND ND 5
6	13363552	ND HIGHWAY 13	2 WEST OF ND HIGHWAY 18
7	10934484	US HIGHWAY 10	IN WEST FARGO
8	0029053832	R INTERSTATE 29	6 NORTH OF ND 46
9	0029053832	L INTERSTATE 29	6 NORTH OF ND 46