

RTK GPS Log

Project Name: IPET TASK GROUP 6-LIDAR CHECKS
Project No: GROUND TRUTH PATCH AREA-PATCH 5
Project Location: LAKE PONT.-NEW ORLEANS

Date	Site	Ref. Station	Ant. Hgt	Ant. Type	Start Point	End Point	Ant. Hgt	Ant. Type
01/10/06	PATCH 5	PAT5	2.063M	TRIMBLE COMP. L1/L2 W/GRD.PLANE	AG06		2.063M	TRIMBLE MICRO-CENTERED L1/L2
01/10/06	PATCH 5	PAT5	2.063M	TRIMBLE COMP. L1/L2 W/GRD.PLANE	PA5A1	PA5A15	2.063M	TRIMBLE MICRO-CENTERED L1/L2
01/10/06	PATCH 5	PAT5	2.063M	TRIMBLE COMP. L1/L2 W/GRD.PLANE	PA5A16	PA5A18	0.20FT.	TRIMBLE MICRO-CENTERED L1/L2
01/10/06	PATCH 5	PAT5	2.063M	TRIMBLE COMP. L1/L2 W/GRD.PLANE	PA5A19	PA5A28	2.063M	TRIMBLE MICRO-CENTERED L1/L2
01/10/06	PATCH 5	PAT5	2.063M	TRIMBLE COMP. L1/L2 W/GRD.PLANE	PA5A29	PA5A49	2.063M	TRIMBLE MICRO-CENTERED L1/L2
01/10/06	PATCH 5	PAT5	2.063M	TRIMBLE COMP. L1/L2 W/GRD.PLANE	PA5A50	PA5A59	2.063M	TRIMBLE MICRO-CENTERED L1/L2
01/10/06	PATCH 5	PAT5	2.063M	TRIMBLE COMP. L1/L2 W/GRD.PLANE	PA5A60	PA5A72	2.063M	TRIMBLE MICRO-CENTERED L1/L2
01/10/06	PATCH 5	PAT5	2.063M	TRIMBLE COMP. L1/L2 W/GRD.PLANE	AG06		2.063M	TRIMBLE MICRO-CENTERED L1/L2

Ground Check-Point Descriptive Codes

Surface Type	Sky Visibility	Surface Slope	Confidence
--------------	----------------	---------------	------------

1	Dirt	1	Open	1	Flat	1	Good
2	Sand	2	Part open	2	Slight Slo	2	Fair
3	Asphalt	3	Covered	3	Slope	3	Bad
4	Concrete						
5	Tall Grass						
6	Mowed Grass						
7	Trees and Brush						
8	Weeds and short grass						
9	Thick brush						
A	Thick cut grass						
B	Cultivated field - unplowed						
C	Limestone						
D	Trees and grass						
E	Gravel						
F	Brush and grass						

Point Code

CHK

3111

BLDG ROOF CORNERS-HORZ

5111

4111-CONC-BRIDGE

6131-SLOPE

4111-CONC-FLOODWALL-HORZ

CHK

