


Condition of the 100m Buffer Around Perennial Freshwater Rivers and Streams in the Parker River Watershed (1999)





Legend

- Wetlands
- Open Water
- Uplands

Buffer Status

- Agriculture
- Developed Land
- Natural Vegetation
- Water



Scale 1:60,000



U.S. Fish and Wildlife Service
National Wetlands Inventory
Northeast Region
300 Westgate Center Drive
Hadley, MA 01035-9589

