

Levee and Floodwall Observation Sheet

Report location of Incident (GPS location preferred, levee station is a second choice)

Limit a single observation record to conditions that are uniform along the levee or floodwall.

Location (parish, area) in which incident is occurring: Orleans Parish, East Bank Lakefront, Map ID L50

A. Type of Structure: Levee X, Levee with I-Wall (capped) ____, Levee with T-Wall ____,
Levee with Sheetpile (uncapped) ____, Other: __

B. GPS Coordinates

Location of observation using GPS unit:

Start of problem: N 90° 05' 10.4" W 030° 01' 36.1"

End of problem:

Length of damage: 10'

C. Photo Numbers: PHOTO ATTACHED

D. Report Category of Severity of Scour Damage

Select one

-
-
-

Class	Descriptor	Description of Scour
I	Light	Scour from crown 2 feet down slope
II	Heavy	Scour from crown to ground surface
III	Breach	Scour below ground surface

Comments: Scour – width: 20 ft and depth: 1 ft.

E. Condition of Floodwall: I-Wall ____ T-Wall ____ Sheetpile Wall (uncapped) ____

Other: __ - (select most appropriate category)

Select one

-
-
-
-

Description
Rotated I-wall
Scour adjacent to wall
Breached wall
Other: _____

Comments: _

F. Date and Time of Observation Date: __ Time: _____

G. Name of person making observation:

H. Sketches/Diagrams

