

Old Inger Oil Refinery
Ascension Parish, Louisiana
March 2002
(after completion of Bioremediation)



Photographs of the former Land Treatment Unit (LTU) after the cap and vegetative cover were installed at the end of the “Bioremediation Process” as part of the Remedial Action (RA) Phases IV-B and IV-C. (Looking north, photo take from levee that separates the Mississippi River from the Old Inger site)



Current condition of the area of the former lagoon and tanks. Lagoons removed (1990 - 1992), tanks removed (removed 1999) soils excavated, treated in the LTU, backfilled and the levee). area graded, capped and vegetated (2000-2001). (Onsite photo, view towards the north).



Current conditions of the area where abandoned tanks and structure of the former refinery were located. (View west, towards the Mississippi River).



Detail of grass cover (onsite picture, looking east). As part of the remedial action, contaminated soils were removed from the lagoon and waste disposal areas. Soils were treated in the LTU. After treatment soils were backfilled into the former excavation areas. The site was graded to provide adequate drainage, capped with a clay cap, top soil was placed over the cap and the entire site was vegetated with grass.