



chipped flange

lower portion of U-joint
connecting steering shaft to
miter box

Miter Box
(after removed from vehicle)

Photo #7

Veh. Photo #07 U-joint from input shaft removed and photographed (Note: Chipped steel on the inside edge of the toothed flange)