



Photo #8

Veh. Photo #08 - Photo with miter box on the left with intermediate shaft attached. The spare tire truss, upon which the miter box is mounted is bowed up, as evidenced by the crease in the truss that can be seen at the very right edge of the photo,