



**ZF, Type 8098
Steering Gearbox**

**Spare Tire
truss**

Bend in truss

**Pitman
Arm**

Photo #9

Veh. Photo #09 - Crease in spare tire truss near the firewall