
Stability of Li-rich layered cathodes, Li_{1.2}Mn_{0.525} Ni_{0.175}Co_{0.1}O₂

Investigate the cause of poor cycle life. Discover paths for improvement.



MnLi O

1 nm

10 Managed by UT-Battelle for the Department of Energy