

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Machinery		3. Date/Time of Accident 09/26/2012 08:40 AM		4. Date/Time of Death 09/26/2012 08:40 AM		5. Fatal Case No 14		
6. Mine Information :										
a) Mining Company Name Eagle Peak Rock and Paving			b) Mine Name North Pit			c) Parent of Mining Company Tony Cruse				
7. Mine Location : a) City ALTURAS			b) County Modoc		c) State CA		8. Mine ID Number: 04-03367		9. Union: NO	
10. Primary Mineral Mined: CONSTRUCTION SAND & GRAVEL M		11. Number of Mine Employees: a) Total 8		b) Underground 3		c) Open Pit/Quarry 5		d) Mill/Prep Plant 5		e) Other
12. Contractor Name:						13. Union		14. Contractor ID Number:		
15. Contractor Address: a) City			b) County			c) State		d) Zip Code		
16. Number of Contractor Employees:										
a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other		
17. Number of Persons in Mine at Time of Accident:					18. Number of Persons Unaccounted For:					
a) Mine Employees: 3		b) Contractor Employees:			a) Mine Employees: 0		b) Contractor Employees:			
19) Location of Accident								20. Mining Height:		
<input type="checkbox"/> 01-Underground		<input checked="" type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		
<input type="checkbox"/> 02-Surface at Underground		<input type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility		Feet Inches		
21. Nonfatal Injuries:		22. Fatal Injuries: 1								
23. Victim Information :										
a) Name Loren A. Bucher				b) Age 79						
c) Regular Job Title: Foreman/Equipment Operator				d) Activity at Time of Accident: Operating D-8K Dozer				<input checked="" type="checkbox"/> Mine Employee		
24. Experience :										
Years		Weeks		Days		Years		Weeks		Days
a) Total: 56		b) at the mine: 17 38 4		c) at activity (23d): 17 38 4		d) with Contractor				
25. Autopsy Performed: NO						26. Mine Telephone No.: (530) 233-4568				

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The victim had been operating a dozer and experienced trouble with the engine throttle. He exited the cab and was standing on the left track when the dozer moved forward and ran over him.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer: Caterpillar			29. Model: D-8K		
30. District: M7000 Western		32. Field Office: Albany OR			33. Event Number: 1156739
34. Accident Investigator: Rickie D. Dance			35. MSHA Person Notified: Roderic B. Breland		Date 09/26/2012
					Time 09:22 A
36. Type of Report: Initial		37. Name of Preparer and Date Prepared: Mike Hancher <i>MH</i>			Date 09/27/2012
38. Reason For Amendment:					